

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE	INSURANCE (SIN	IGAPORE) PTE LTD	Ref : CC3/QBE20001679/Eea3q2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date: 05-05-2020 Code: QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKN 1290T	Veh. Inspected	SHB 223T
	Policy No.	8-V0010557-MVA-R004	Coverage (\$)	0.00
	Claim No.	VC013411	Excess (\$)	0.00
	Assign From		Assign Date	29/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	JTDKN36U405692448	Colour	MAROON
	Odometer	603485	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R15	FIRENZA	5 mm
	L/H Front Tyre	195/50 R15	FIRENZA	5 mm
	R/H Rear Tyre	195/50 R15	FIRENZA	5 mm
	L/H Rear Tyre	195/50 R15	FIRENZA	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	26/01/2020	Inspection Date	29/01/2020
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD		
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			