FAX: 65073849

# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883 TEL. 67476106 (6 lines) FAX. 67442368 Email: service@smemotor.com.sg GST:201119451E RCB NO:201119451E

M/S: MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

65073848 TEL:

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

20/FC/TP-028(01)

Accident Date:

Third Party 20/01/2020

TP Veh Reg No: SHD8588C **Estimate No:** 

EST0005302

Date:

23 Jan 2020

Policy No:

P10253261R00

Veh Reg No:

SJD9785U

Make/Model:

HONDA STREAM

Chasis No: Engine No:

RN61054753

R18A1761195

Reg. Date:

11/04/2008

Estimate Repair Cost to Vehicle No :SJD9785U

	Description	Quantity	List Price	Amoun
	List Price		SS	<u>S</u> :
,	FRT LH SHOCK ABSORBER			2
2	FRT LH LOWER ARM	1 PC	329.00	
3	FRT LH KNUCKLE ARM	1 PC	302.00	
		IPC S	289.00	
4	FRT LH KNUCKLE BEARING	1 PC	129.00	
5	STEERING RACK ASSY		W1.651.00 -	
6	FRT LH DRIVE SHAFT	IPC Tun	966.00	
7	FRT BUMPER	1 PC	1 677.000	<b>(</b> .
8	FRT BUMPER CLIPS	10 PC 1	1 55.00 L	X
			4,398.00	
		Less 20%	879.60	3,518.40
	Labour			
9	WIRE CHECKING	1 UNIT	30.00	20
10	REMOVE & REFIX FRT UNDERCARRIAGE (WITH STEERING RACK)	1 UNIT	350.00 3	
11	WHEEL ALIGNMENT	LUNIT	65.00	
12	LABOUR CHARGE	LUNIT	200.00	
13	SPRAY PAINTING	1 UNIT	350.00 3	
			995.00	995.00
			Total	S\$ 4,513.40
		Add GST	7%	315.94
		Total Amount Pa	yable	S\$ 4,829.34

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED TWENTY NINE AND CENTS THIRTY FOUR ONLY

30/120 | 15 # 2950 | The pho Ather M

For SME Motor Pte Ltd

sultants hence notify

the following: prelatter spray painting

AUTHORISED SIGNATURE

- ey is on a "Without Prejudice" basis
  - cation(s) is allowed
- dementary item(s) must be reserve

SHD8588C

# MOTOR PTE LTD

Your Insured Veh No.

MS FIRST Capital Insurance Limited Your Ref 36 Robinson Road #16-01 SJD9785U Our Ref CITY HOUSE Singapore 068877 02/04/2020 Date WITHOUT PREJUDICE Dear Sir/Madam and SJD9785U Accident involving SHD8588C on 20/01/2020 at JALAN PARI BURONG. Please refer only to the boxes marked (x). We refer to The above accident our/your letter dated We have been authorised by the owner of vehicle number which was damaged by your SJD9785U insured's motor vehicle number SHD8588C in the aforesaid accident. X We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows: Cost of Repair / Insurance Excess Survey report fees 240.00 Loss of Use(3 days @ \$80.00 per day) Car Rental Fees 7.45 GIA/LTA search fees Total S\$ 3,403.95 We forward herewith the following relevant supporting documents:-Survey Reports & photographs (To be returned within 7 days on demand) X Copy of NRIC/Driving licence Final repair bill(Tax Invoice) X Copy of LTA/GIA vehicle search X Bill/Receipt for the excess X Non-injury motor report form Rental Agreement X Letter of Authority X Copy of the Insurance Certificate X Cheque to be make payable to Messrs SME MOTOR PTE LTD. Any request for a re-survey of our client's vehicle must be arrange within the 14 days upon receipt of this letter. The re-survey must be conducted at our premises, in the presence of our client. X | Please note that you should send to us an acknowledgment of receipt of this letter within 07 days of your receipt of this letter. WE HEREBY ACKNOWLEDGE RECEIPT Yours faithfully. Date: PLEASE CHOP AND SIGN SME MOTOR PTE LTD

encl:

### **SME Motor Pte Ltd**

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg GST:201119451E RCB NO:201119451E

M/S: MS FIRST CAPITAL INSURANCE LIMITED

EST0005302

36 ROBINSON ROAD #16-01

Final No:

Claim No:

INV0004621

**CITY HOUSE** 

Date:

01 Apr 2020

Singapore 068877

Policy No:

P10253261R00

TEL:

65073848

FAX: 65073849

Veh Reg No:

SJD9785U

ATTN: Motor Claim Department

Make/Model:

**HONDA STREAM** 

Your Ref No:

20/FC/TP-028(01)

Chasis No: Engine No: RN61054753 R18A1761195

Claim Type: Accident Date:

Third Party 20/01/2020

Reg. Date:

11/04/2008

#### Tax Invoice to Vehicle No :SJD9785U

PAGE:1

Description

Quantity |

**List Price** S\$

Amount S\$

As agreed to proceed repair at Lump Sum Repair Less Excess

S\$ 2,950.00

Amount Before GST

S\$ 0.00

Add GST @ 7%

S\$ 2,950.00 206.50

Total Amount payable

S\$ 3,156.50

TOTAL: SINGAPORE DOLLAR THREE THOUSAND ONE HUNDRED FIFTY SIX AND CENTS FIFTY ONLY

For SME Motor Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE

## > Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

23 Jan 2020 / 09:26:26

Receipt Date/Time: 23 Jan 2020 / 09:26:26

# Tax Invoice/Receipt

Receipt No.: ITNET-00000-200123-000505

Previous Receipt No. :

S/N Item Description/ Business Transaction Reference No.  Result of Insurance Enquiry - SHD8588C As at 20 Jan 2020/20:00:00 Insurance Co: MS FIRST CAPITAL INSUR	ANCE LIMITED	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
1 Insurance Enquiry - SHD8588C Enquiry Fee 20200123092533967499		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxx2266	Credit Card: Visa/MasterCard		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.