

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SJU 4706 S**
 Make Toyota
 Model Wish
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bonnet	1	\$ 1,120.00	\$ 1,120.00
2	Front grille	1	\$ 362.00	\$ ✓ 362.00
3	Headlamp Lh	1	\$ 1,206.90	\$ 918.97 1,206.90
4	Headlamp bracket Lh	1	\$ 154.00	\$ 85.00 154.00
5	Front bumper	1	\$ 1,096.00	\$ 545.10 1,096.00
6	Front bumper side retainer	2	\$ 61.90 134.00	\$ 123.80 268.00
7	Front bumper grille	1	\$ 113.00	\$ 113.00
8	Front bumper reinforcement	1	\$ 287.00	\$ 287.00
9	Front bumper inner sponge	1	\$ 182.00	\$ 108.50 182.00
10	Front support panel	1	\$ 699.40	\$ ✓ 699.40
11	Front support panel top garnish	1	\$ 327.50	\$ 182.00 327.50
12	Air duct	1	\$ 326.00	\$ 130.00 326.00
13	Front fog lamp cover	1	\$ 127.50	\$ 127.50
14	Front fender Lh	1	\$ 978.00	\$ 645.10 978.00
15	Front fender lamp	1	\$ 89.00	\$ 69.70 89.00
16	Front fender inner shield	1	\$ 216.00	\$ 155.20 216.00
17	Front shock absorber LH	1	\$ 319.60	\$ 319.60
18	Front lower arm LH	1	\$ 394.50	\$ ✓ 394.50
19	Front knuckle arm LH	1	\$ 365.80	\$ 365.80
20	Front knuckle arm bearing LH	1	\$ 135.00	\$ 135.00
21	Front wheel hub with bearing LH	1	\$ 251.00	\$ 251.00
22	Side mirror	1	\$ 356.00	\$ 356.00
23	Side skirt	1	\$ 423.00	\$ ✓ 423.00
24	Front door LH	1	\$ 1,292.30	\$ ✓ 1,292.30
25	Front door black tape LH	1	\$ 92.60	\$ 45.64 92.60

Parts Sub Total : \$ ~~6179.81~~ 11,182.10
 Discount : \$ ~~1544.95~~ 2,795.53
PARTS TOTAL : \$ ~~4634.86~~ 8,386.58

25%

BRX
 BR ✓
 MIS ✓
 BR ✓
 BR ✓
 NEC ✓
 ASSP X
 ND X
 BR ✓
 BT ✓
 BR ✓
 DIS ✓
 ND X
 DD ✓
 SC ✓
 TN ✓
 ND X
 DD ✓
 } ND X
 RX
 DL ✓
 DD ✓
 NEC ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$		
1	Number plate with garnish	1	\$ 80.00	\$ 50.00	80.00	NEC
2	Front grille clips	1	\$ 50.00	\$ 30.00	50.00	NEC ✓
3	Front bumper clips	1	\$ 50.00	\$ 30.00	50.00	NEC ✓
4	Front support panel top garnish clips	1	\$ 50.00	\$ 30.00	50.00	NEC ✓
5	Sideskirt clips	1	\$ 50.00	\$ 30.00	50.00	NEC ✓
6	Headlamp clips	1	\$ 60.00	\$ 30.00	60.00	NEC ✓
7	Front alloy rim LH <i>local repair</i>	1	\$ 650.00	\$ 300.00	650.00	R
8	Front tyre LH	1	\$ 350.00		350.00	NDX
9	Front fender inner shield clips	1	\$ 60.00	\$ 20.00	60.00	NEC
SPECIAL NETT TOTAL :				\$ 530.00	1,400.00	

Nos.	LABOUR	S\$		
1	To Panel Beat & Realign Front Accident Damage Portion	\$ 1,000.00	1,400.00	✓
2	To Spray Front Accident Damage Portion	\$ 1,000.00	1,400.00	✓
3	R&R front under carriage	\$ 120.00	350.00	✓
4	R&R wiper garnish		120.00	NDX
5	Wheel alignment	\$ 60.00	180.00	✓
6	Tyre rotation and balancing		180.00	NDX
7	R&R wire harness and check function	\$ 50.00	150.00	✓
8	Rust proofing	\$ 60.00	150.00	✓
LABOUR TOTAL :		\$ 2,290.00	3,930.00	

Survey 30/1/2020
TGLim Lin
1500 hrs

Resurvey 31/1/2020
TGLim Lin
1600 hrs

Lump sum repair
Repair days 8 @20%

PARTS TOTAL : \$ 4634.86 8,386.58
SPECIAL NETT TOTAL : \$ 530.00 1,400.00
LABOUR TOTAL : \$ 2290.00 3,930.00
GRAND TOTAL : ~~\$ 7454.86~~ 13,716.58
1490.97
5963.89

45 5950/2

TGLim Lin
12/2/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: