

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SJU 4706 S**
 Make Toyota
 Model Wish
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bonnet	1	\$ 1,120.00	\$ 1,120.00
2	Front grille	1	\$ 362.00	\$ ✓ 362.00
3	Headlamp Lh	1	\$ 1,206.90	\$ 918.97 1,206.90
4	Headlamp bracket Lh	1	\$ 154.00	\$ 85.00 154.00
5	Front bumper	1	\$ 1,096.00	\$ 545.10 1,096.00
6	Front bumper side retainer	2	\$ 61.90 134.00	\$ 123.80 268.00
7	Front bumper grille	1	\$ 113.00	\$ 113.00
8	Front bumper reinforcement	1	\$ 287.00	\$ 287.00
9	Front bumper inner sponge	1	\$ 182.00	\$ 108.50 182.00
10	Front support panel	1	\$ 699.40	\$ ✓ 699.40
11	Front support panel top garnish	1	\$ 327.50	\$ 182.00 327.50
12	Air duct	1	\$ 326.00	\$ 130.00 326.00
13	Front fog lamp cover	1	\$ 127.50	\$ 127.50
14	Front fender Lh	1	\$ 978.00	\$ 645.10 978.00
15	Front fender lamp	1	\$ 89.00	\$ 69.70 89.00
16	Front fender inner shield	1	\$ 216.00	\$ 155.20 216.00
17	Front shock absorber LH	1	\$ 319.60	\$ 319.60
18	Front lower arm LH	1	\$ 394.50	\$ ✓ 394.50
19	Front knuckle arm LH	1	\$ 365.80	\$ 365.80
20	Front knuckle arm bearing LH	1	\$ 135.00	\$ 135.00
21	Front wheel hub with bearing LH	1	\$ 251.00	\$ 251.00
22	Side mirror	1	\$ 356.00	\$ 356.00
23	Side skirt	1	\$ 423.00	\$ ✓ 423.00
24	Front door LH	1	\$ 1,292.30	\$ ✓ 1,292.30
25	Front door black tape LH	1	\$ 92.60	\$ 45.64 92.60

Parts Sub Total : \$ ~~6179.81~~ 11,182.10
 Discount \$ ~~1544.95~~ 2,795.53
PARTS TOTAL : \$ ~~4634.86~~ 8,386.58

25%

BRX
 BR ✓
 MIS ✓
 BR ✓
 BR ✓
 NEC ✓
 KSPX
 ND ✓
 BR ✓
 BT ✓
 BR ✓
 DIS ✓
 ND ✓
 DD ✓
 SC ✓
 TN ✓
 ND ✓
 DD ✓
 ND ✓
 RX
 DL ✓
 DD ✓
 NEC ✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Number plate with garnish	1	\$ 80.00	\$ 50.00 80.00
2	Front grille clips	1	\$ 50.00	\$ 30.00 50.00
3	Front bumper clips	1	\$ 50.00	\$ 30.00 50.00
4	Front support panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00
5	Sideskirt clips	1	\$ 50.00	\$ 30.00 50.00
6	Headlamp clips	1	\$ 60.00	\$ 30.00 60.00
7	Front alloy rim LH <i>local repair</i>	1	\$ 650.00	\$ 300.00 650.00
8	Front tyre LH	1	\$ 350.00	\$ 350.00
9	Front fender inner shield clips	1	\$ 60.00	\$ 20.00 60.00
SPECIAL NETT TOTAL :				\$ 530.00 1,400.00

NEC ✓
NEC ✓
NEC ✓
NEC ✓
NEC ✓
R
NDX
NEC

Nos.	LABOUR	S\$
1	To Panel Beat & Realign Front Accident Damage Portion	\$ 1,000.00 1,400.00
2	To Spray Front Accident Damage Portion	\$ 1,000.00 1,400.00
3	R&R front under carriage	\$ 120.00 350.00
4	R&R wiper garnish	\$ 120.00
5	Wheel alignment	\$ 60.00 180.00
6	Tyre rotation and balancing	\$ 180.00
7	R&R wire harness and check function	\$ 50.00 150.00
8	Rust proofing	\$ 60.00 150.00
LABOUR TOTAL :		\$ 2,290.00 3,930.00

NDX
NDX
✓

Survey 30/1/2020
TGLim W
1500 hrs

Resurvey 31/1/2020
TGLim W
1600 hrs

PARTS TOTAL : \$ 4634.86 8,386.58
SPECIAL NETT TOTAL : \$ 530.00 1,400.00
LABOUR TOTAL : \$ 2290.00 3,930.00
GRAND TOTAL : \$ 7454.86 13,716.58

Lump sum repair
Repair days 8 @ 20%

1490.97
5963.89

45 5950/2

TGLim W
12/2/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: