

India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
Singapore 409711

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475 Fax : 6844 2474
E-mail : claims@teamworkgarage.com
ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number : SKF5824U
Make / Model : HONDA/CIVIC TYPE R
Chassis number : FD21401080
Accident date : 24 January 2020
Reference : 2001-43

Qty Particulars

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT EMBLEM	97.74
2	FRONT BUMPER RETAINER	150.20
1	FRONT BUMPER REINFORCEMENT	400.20
1	FRONT SUPPORT PANEL	626.75
1	FRONT SUPPORT PANEL TOP GARNISH	110.40
1	FRONT HEADLAMP LH	1030.35
1	FRONT HEADLAMP RH ✓	1030.35
2	FRONT HEADLAMP BRACKET RH	80.50
1	FRONT RH FENDER INNER SHIELD	132.25
1	FRONT BONNET LOCK	119.20
1	AIRCON CONDENSER	876.30
1	RADIATOR	1481.20
1	RADIATOR COWLING	120.75
1	RADIATOR FAN MOTOR ASSY	369.15
1	RADIATOR EXPANSION TANK	63.25
1	WIPER WASHER TANK	86.25
		6774.84
Less 20%		1354.96
Subtotal		5419.88
Balance C/F		5419.88
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	FRONT BUMPER (AFTER MARKET) ✓	1600.00
1	FRONT BUMPER LOWER MESH (AFTER MARKET)	250.00
1	FRONT BUMPER LOWER GARNISH (AFTER MARKET)	800.00
1	FRONT BUMPER SIDE GARNISH LH (AFTER MARKET)	180.00
1	FRONT BUMPER SIDE GARNISH RH (AFTER MARKET)	180.00
1	FRONT GRILLE (AFTER MARKET)	410.00
1	FRONT FENDER RH (AFTER MARKET) ✓	1500.00
1	FRONT BONNET (AFTER MARKET)	1850.00
1	OIL COOLER	1530.00
1	OIL COOLER PIPE	250.00
1	FRONT NUMBER PLATE	70.00
1 SET	FRONT BUMPER CLIP	30.00
1 SET	FRONT GRILLE CLIP	20.00
1 SET	FRONT FENDER INNER TRIM CLIP	20.00
1 BOT	COOLANT	60.00
Subtotal		8750.00
Balance C/F		14169.88

X
nn

914.80

40.25

X
nn

955.05

20% - 764.04

1200

X
nn

1100

X
nn

nn

nn

nn

2330

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

14169.88

1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00	30
2	REMOVE, RENEW AIRCON CONDENSER AND TOP UP GAS	150.00	X
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	150.00	X
4	REMOVE AND RENEW OIL COOLER	120.00	X
5	PANEL BEATING ON AFFECTED AREAS	1200.00	400
6	SPRAY PAINTING ON AFFECTED AREAS	1400.00	300
7	APPLY ANTI RUST ON AFFECTED AREAS	120.00	X

Subtotal

3200.00

Grand total

17369.88

Tauplin 97495744
up

31/1/20

Lumpsum

Resurvey after repair

03 days

tauplin@lklauto.com

03 days #

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: