

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
YIK
JINXIONG (YI JINXIONG)
BLK 287 BUKIT BATOK EAST AVE 3
#20-405
SINGAPORE 650287

Document no.
Document date 30-01-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2020000303/ 1
Job order date 29-01-2020
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SML9181J	5E36UDR1	25-04-2019	TMBBU7NE4K0114466	Octavia RS 2.0 TSI 180kW DSG	80

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00 ✓	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00 ✓	#1	280.00	299.60
	WHEEL ALIGNMENT	1	pcs.	360.00 ✓	#1	360.00	385.20
	R&R RIM & BALANCE	1	pcs.	50.00 ✓	#1	50.00	53.50
5E5807421B	Cover For (REAR BUMPER COVER)	1	pcs.	1,375.00 <i>de</i> ✓	#1	1,375.00	1,471.25
5E0807837B 9B9	Connecting BUMPER UPPER SIDE TRIM LH	1	pcs.	28.20 <i>new</i> ✓	#1	28.20	30.17
5E5807393	Guide Piec (BUMPER GUIDE LH)	1	pcs.	20.30 <i>new</i> ✓	#1	20.30	21.72
5E0810969B	Wheelhouse	1	pcs.	107.00 <i>cut</i> ✓	#1	107.00	114.49
6N0809966A	Expanding Nut	6	pcs.	0.81 <i>new</i> ✓	#1	4.86	5.20
5E5807521F 9B9	Spoiler	1	pcs.	177.00 <i>xm</i> ✓	#1	177.00	189.39
5E5919485C	Sensor Bra	1	pcs.	11.40 <i>new</i> ✓	#1	11.40	12.20
5E5919485B	Sensor Bra	2	pcs.	11.40 <i>new</i> ✓	#1	22.80	24.40
5E5919486C	Sensor Bra	1	pcs.	11.40 <i>new</i> ✓	#1	11.40	12.20
D 822150A1	Bonding Agent For Plastic	1	pcs.	59.40 <i>new</i> ✓	#1	59.40	63.56
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	75.94 <i>new</i> ✓	#1	75.94	81.26
5E5945311A	Cover LH TAILLAMP SIDE COVER (BLACK)	1	pcs.	20.90 <i>new</i> ✓	#1	20.90	22.36
5E5945711	Taillight (LH TAILLIGHT)	1	pcs.	685.00 <i>cut</i> ✓	#1	685.00	732.95
5E0945067A	Unbekannt TAILLIGHT PLUG	2	pcs.	1.16 <i>new</i> ✓	#1	2.32	2.48
5E5809601D	Sectional (LHR FENDER)	1	pcs.	1,130.00 <i>buy</i> ✓	#1	1,130.00	1,209.10
5E0807905B	FOIL REAR FENDER FOIL LH	1	pcs.	51.95 <i>new</i> ✓	#1	51.95	55.59
5E5813319	Insert Pla TAILLIGHT PANEL LH	1	pcs.	251.00 <i>7xm</i> ✓	#1	251.00	268.57
7PP819181A	Vent Trim LHS RR FENDER AIR DUCT	1	pcs.	55.70 <i>7xm</i> ✓	#1	55.70	59.60
D 007600A1	Inox-Spray	1	pcs.	62.88 <i>new</i> ✓	#1	62.88	67.28
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	61.67 <i>new</i> ✓	#1	61.67	65.99
D 180003M2	2k-Body Adhesive	1	pcs.	406.76 <i>new</i> ✓	#1	406.76	435.23
311601361	Rubber Valve	1	pcs.	3.29 <i>new</i> ✓	#1	3.29	3.52
5E0601025AJHA7	Alloy Whee TYRE	1	pcs.	1,465.00 <i>cut</i> ✓	#1	1,465.00	1,567.55
	CHECK WATERLEAK TEST	1	pcs.	720.00 <i>80% cut 570</i> ✓	#1	720.00	770.40
	R&R LUGGAGE COMPARTMENT TRIM	1	pcs.	150.00 ✓	#1	150.00	160.50
	LABOUR	8	pcs.	840.00 <i>420</i> ✓	#1	840.00	898.80
	Spray Painting	4	pcs.	840.00 <i>3360</i> ✓	#1	6,720.00	7,190.40
				<i>1680</i>	#1	3,200.00	3,424.00
				<i>2000</i>			

Quotation valid till 05-02-2020

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Quotation

Non binding - Preview

Page 2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
YIK
JINXIONG (YI JINXIONG)
BLK 287 BUKIT BATOK EAST AVE 3
#20-405
SINGAPORE 650287

Document no.
Document date 30-01-2020
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2020000303/ 1
Job order date 29-01-2020
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SML9181J	5E36UDR1	25-04-2019	TMBBU7NE4K0114466	Octavia RS 2.0 TSI 180kW DSG	80

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,170.00	17,719.77	7%	1,322.28	18,889.77	20,212.05
Total	1,170.00	17,719.77		1,322.28	18,889.77	20,212.05

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

Tanjin 97495749.
- WP
4/2/2020 1130.
Resin before paint.
08 days
tanjin@khando.com.

Supplementary or Omitted List



VEHICLE NUMBER: SML9181J

MODEL GOLF

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
	CHANGE LANE ASSIST SYSTEM CALIBRATION	1	\$ 840.00	\$ 840.00
Total				nec ✓

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
TOTAL:						\$0.00

Total Labour & Parts

\$0.00

Survey By

TAUFIKH