



### ESTEEM PERFORMANCE

81k 6033 Ang Mo Kio, Ind Park @ #01-251/252,  
Tel: +65-6464 1221 Fax: +65-6464 7829 Web:

#### Repair Estimates

SMA 6196 U

Parts	(a) Cost / List Price Items	\$ <u>174410</u>	3,381.95
	Plus/Less 25%	\$ <u>473.53</u>	845.49
	Total of Cost / List	\$ <u>142057</u>	2,536.46
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
	Total Parts Cost	\$	<u>2,736.46</u>
	Labour	\$ <u>500.00</u>	1,570.00
	Total	\$ <u>1970.57</u>	4,306.46

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : CKK

Survey conducted on : 3/2/20 at 11:30am

#### Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 03 day(s)
- (c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 3/2/20

0.0  
0.0  
497.5+  
40+  
112.7+  
582.6+  
149.7+  
511.6+  
=  
1,894.1\*  
1,894.1\*  
75.0+  
1,420.575\*  
0.0  
200.0+  
280.0+  
20.0+  
50.0=  
550.0\*  
0.0  
1,420.57+  
550.0=  
1,970.57\*

2/2/2020

CKK



