

Steve (LKK) WML M/L 17/3/20, 11.30am  
3 days, L/S  
Ry AL sy

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

## Estimate

31/01/2020

**EQ INSURANCE CO LTD**  
**5 MAXWELL ROAD**  
**#17-00 TOWER BLOCK MND COMPLEX**  
**SINGAPORE 069110**

Page # :- 1  
Veh # :- SJJ5275U  
Veh Model :- TOYOTA VIOS 1.5L  
Estimate# :- CK420324  
Claim # :-  
ACC. Date :- 29/01/20  
Terms :- C.O.D Days  
Remarks :-

Attention :- XA039

| No.                                                                                                                  | Description                                 | Qty   | U.Price | Amounts S\$ |
|----------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-------|---------|-------------|
| <b>LIST ITEMS :</b>                                                                                                  |                                             |       |         |             |
| 1.                                                                                                                   | FRONT BUMPER / DD                           | 1 PC  | 598.30  | 598.30 ✓    |
| 2.                                                                                                                   | FRONT BUMPER TOW COVER / M/S                | 1 PC  | 79.40   | 79.40 ✓     |
| 3.                                                                                                                   | FRONT BUMPER FOG LIGHT COVER RH ?           | 1 PC  | 114.20  | 114.20 ?    |
| 4.                                                                                                                   | FRONT BUMPER FOG LIGHT CHROME RH ?          | 1 PC  | 91.10   | 91.10 ?     |
| 5.                                                                                                                   | FRONT BUMPER FOG LIGHT ?                    | 1 PC  | 278.50  | 278.50 ?    |
| 6.                                                                                                                   | FRONT BUMPER REINFORCEMENT ?                | 1 PC  | 311.20  | 311.20 ?    |
| 7.                                                                                                                   | FRONT BUMPER REINFORCEMENT BRACKET RH X 500 | 1 PC  | 250.10  | 250.10 X    |
| 8.                                                                                                                   | FRONT BUMPER RETAINER RH / DR               | 1 PC  | 78.30   | 78.30 ✓     |
| 9.                                                                                                                   | FRONT BUMPER CLIPS / MC                     | 10 PC | 3.90    | 39.00 ✓     |
| 10.                                                                                                                  | FRONT BUMPER LOWER GRILLE / DR              | 1 PC  | 114.50  | 114.50 ✓    |
| 11.                                                                                                                  | FRONT HEADLAMP RH                           | 1 PC  | 478.10  | 478.10 ?    |
| 12.                                                                                                                  | FRONT FENDER RH - REPAIR X R                | 1 PC  |         | R.          |
| LIST TOTAL S\$                                                                                                       |                                             |       |         | 2,432.70    |
| 25% DISCOUNT S\$                                                                                                     |                                             |       |         | -608.18     |
|                                                                                                                      |                                             |       |         | 1,824.52    |
| <b>LABOUR :</b>                                                                                                      |                                             |       |         |             |
| TO REPAIR FRONT FENDER RH, FRONT SUPPORT PANEL. TO REMOVE & REFIX DAMAGED PARTS. STRAIGHTEN & REALIGN AFFECTED AREAS |                                             |       |         | 250 480.00  |
| TO SPRAY AFFECTED AREAS                                                                                              |                                             |       |         | 400 500.00  |
| TO CHECK WHEEL ALIGNMENT                                                                                             |                                             |       |         | WHL X 80.00 |
| LABOUR TOTAL S\$                                                                                                     |                                             |       |         | 1,060.00    |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis,
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Customer's Signature/Co. Stamp**  
Acknowledged by Repairer

Signature:

Date:

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,884.52

GST @ 7 % 201.92

AMOUNT DUE S\$ 3,086.44

**MOVA AUTOMOTIVE PTE LTD**