

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005506

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

DATE 03/02/2020
 ACCIDENT DATE : 26/01/2020
 VEHICLE NO : SME7845C
 CHASSIS/ENG.NO : MR2B23F3201151365D
 VEHICLE MODEL : TOYOTA VIOS
 CLAIM NO :
 POLICY NO :
 REMARK 7845 INDIA TP AGST
 SHA7035

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER <i>de</i>	505.00	25	378.75	378.75
2	10	PC	REAR BUMPER CLIPS <i>re</i>	5.50	25	4.13	41.30
3	<i>1pc</i>	PC	REAR BUMPER SIDE RETAINER <i>LH-ud</i>	117.00	25	87.75	175.50
4	2	PC	REAR BUMPER REVERSE SENSOR <i>2 x</i>	385.00	25	288.75	250 577.50
5	1	PC	REAR BUMPER REINFORCEMENT <i>X</i>	345.00	25	258.75	258.75
6	1	PC	REAR BUMPER REFLECTOR(LH) <i>?</i>	175.00	25	131.25	131.25
7	1	PC	REAR TAILLAMP(LH) <i>X</i>	358.00	25	268.50	268.50
8	1	PC	REAR TAILLAMP LOWER BRACKET(LH) <i>?</i>	95.00	25	71.25	71.25
SUB-TOTAL:							1,902.80

** WORK LABOUR **

TO KNOCK REAR END PANEL, REAR FENDER LH, WELD & REPLACE ABOVE		700.00	700.00
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	Rasul	700.00	200 700.00
TO CHECK WIRING	Hp 900/10068	30.00	X 30.00
TO APPLY ANTI RUST COATING	2 days	80.00	X 80.00

		SUB-TOTAL	1,510.00

JANICE

PAGE: 1 of 1

03/02/2020

SUB-TOTAL : S\$ 3,412.80

ADD 7% GST. S\$ 238.90

GRAND TOTAL : S\$ 3,651.70

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.