



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20001929/T1pa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 13-04-2020



ATTN:YVONNE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 4033U	Veh. Inspected	SMR 5016Z
Policy No.	GA189918	Coverage (\$)	0.00
Claim No.	S0M02F4E	Excess (\$)	0.00
Assign From		Assign Date	04/02/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT 1.3	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GK33419866	Colour	BLUE
Odometer	3258	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/02/2020	Inspection Date	04/02/2020
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------