

 $51\, \mathrm{UBI\,AVE}\, 1, \#02\text{-}25\, \mathrm{PAYA\,UBI\,INDUSTRIAL\,PARK}, \mathrm{SINGAPORE\,408933\,\,TEL:} \\ (065)\, 62563561\,\,\mathrm{FAX:} \\ (065)\, 62564315\,\,\mathrm{FAX:} \\ (067)\, 625643$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 13/3/2020

Survey Details:

Date of loss	1-Feb-2020
Date of appointment	4-Feb-2020
Date of survey	4-Feb-2020
Location of survey	Gold Autoworks Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SMR5016Z
Make and Model	HONDA FIT 1.3GF CVT
Date of registration	10/1/2020
Parf Rebate	
Market Value	\$ 68,000.00
Parf Rebate	\$ 30,561.00
Nett Loss	\$ 37,439.00

Repair details:

Initial Estimate	\$ 11,508.03

Proposed/Revised repair cost:

Parts	\$ 5,047.84
Check items (estimate)	
Labour	\$ 2,060.00
Total	\$ 7,107.84
Lump Sum(if applicable)	\$ 5,700.00

Number of days for repair	7
---------------------------	---



 $51\, \mathrm{UBI\,AVE}\, 1, \#02\text{-}25\, \mathrm{PAYA\,UBI\,INDUSTRIAL\,PARK}, \mathrm{SINGAPORE\,408933\,\,TEL:} \\ (065)\, 62563561\,\,\mathrm{FAX:} \\ (065)\, 62564315\,\,\mathrm{FAX:} \\ (067)\, 625643$

Remarks:

Insured driver changed lane and collided with third
party(SMR5016Z), the impact caused insured car to hit onto the
vehicle(GBE1303U) stopped in front of him.

Mandate:

Liability(TP)	100%	
Proposed repair cost (WITH GST)	\$ 6,099.00	
Loss of use	NIL	
Loss of rental (9 DAYS X \$100)	\$ 900.00	no. of days
Loss of income	NIL	
LTA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 7,006.45	