

ASS. REC. BY:

REF: C1/TPD 20001932/Kg

Special Instructions

SURVEYOR

ASSIGNMENT (Office)

Date/Time: 03/02/2020

From (Person): Kamaliyah Kamis

SPF

Bill to:

Estimated Cost:

Estimated Cost: _____
 OD+TP+WS+TP RES / OD RES / EVA / INV / MY / CS
 100-107304

Insured:

To Inspect Vehicle No:

Tel:

at Workshop m/s

of

Policy No:

MHASPF06000032182/1

Claim No:

70/1P/04019/2020

Sum Insured:

Excers:

D.O.A.

21/01/2020

Make of Veh: _____
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

DateTime

Action/Instruction ()	Estimate
------------------------	----------

Estimate

E74
kesir

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Monday, 3 February, 2020 2:03 PM
To: Sherwin Beh (LKK Auto); Naz (LKKAuto)
Cc: SPF-TP FAIT; Intan Wulandari (SPF); Bryan Ang (LKKAuto)
Subject: RE: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **26 vehicles** below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]

a) **Case IAFP-IB-20200131 - Mechanical Inspection of Motor Car, SCY8827L (TP/IP/00589/2020)**

On 03 January 2020 at about 09.31 pm, Police incident was created regarding an accident along Hougang Mall Basement 2 carpark. Driver is a 69 years old male, he was conscious and did not sustain any injuries however both his grandsons aged 16 and 14 years old, who were seated at the rear seats sustained back pain and a cut on the right cheek respectively. Driver claimed that upon driving out from the carpark lot where he parked his vehicle head-out and turned left, his vehicle suddenly surged forward causing him to lose control of his vehicle and collide onto a pillar on the left. After the impact, the driver said that he quickly counter steered to the right whilst stepping onto the brake pedal. Whilst applying brakes, driver said that his vehicle did not slow down and continued moving forward before colliding onto the rear of a stationary parked motor van that was parked further ahead.

Vehicles to be inspected: SCY8827L - Driver (Potential Defendant)

IO In-Charge: IO Intan

b) **Case IAFP-IB-20200131 - Mechanical Inspection of Motor Taxi, SHD1099T (TP/IP/01893/2020)**

On 12 January 2020 at about 6.25 am, the driver of motor taxi, SHD1099T was negotiating a left turn from the carpark of Blk 66 Lorong 4 Toa Payoh into lane 2 of 2 lanes along Lorong 4 Toa Payoh and collided into a pedestrian who was crossing from his right to left from the centre divider along Lorong 4 Toa Payoh. The pedestrian was conveyed unconscious and subsequently died due to his injuries on 12 January 2020. As such, this vehicle has to undergo a thorough mechanical inspection by an external expert.

Vehicles to be inspected: SHD1099T - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

- c) **Case IAFP-IB-20200131 - Mechanical Inspection of Motorcycle, FX5957J (TP/IP/04019/2020)**
d) **Case IAFP-IB-20200131 - Mechanical Inspection of Motor Van, GBF4732P (TP/IP/04019/2020)**

On 21 January 2020 (Tuesday) at 11.14 a.m., the Deceased (who was alone on his motorcycle) was travelling straight along Gul Way towards Pioneer Road (major road) when motor van GBF 4732 P which was travelling along Gul Avenue towards Benoi Road (minor road) failed to give way to the motorcycle and collided into the right portion of motorcycle FX 5957 J. As a result of the accident, the Deceased sustained multiple injuries and succumbed to his injuries. He was pronounced dead at the hospital.