

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 13:33

Company Reg. No. 199902271W
GST Reg. No. 199902271W

| | | |
|---|--|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120 | Invoice No: 85015171 Date : 21/05/2020 Order : SJJ3920D Term : 30 | Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 |
|---|--|--|

| | | | |
|--|----------------------------|--------------------|----------------|
| Regn No: SJJ3920D (V 38464) | Regn Date: 26/07/2018 | Mileage: 21745 | WIP No.: 28080 |
| Model: A3 SEDAN 1.0 TFSI 8VMANG | Chassis: WAUZZZ8V9J1069554 | Engine: CHZ 466306 | Dept: U |
| You have been assisted by :- UB-Lim Kee Siang (43) | | | |

| | | Details | Qty | Unit Price | Amount |
|---|-----------------|---|---------|------------|----------|
| S | SUBLET | M: BNP - TO SUPPLY VEHICLE NUMBER PLATE | 40.00 | 1.00 | 40.00 |
| Q | EXC | M: 8888 Insurance Excess/Liability | -300.00 | 1.00 | -300.00 |
| S | BODYWORK | M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY | 360.00 | 1.00 | 360.00 |
| S | BODYWORK | M: TO DISMANTLE AND RENEW BONNET AND HEADLIGHT. TO REPAIR FRONT BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | 1250.00 | 1.00 | 1,250.00 |
| S | BODYWORK | M: TO RESPRAY FRONT BUMPER AND BONNET | 1100.00 | 1.00 | 1,100.00 |
| S | BODYWORK | M: TO CARRY OUT DIAGNOSTIC CHECK | 192.00 | 1.00 | 192.00 |
| X | A8V5807647B 9B9 | GRILLE (SK) | 1.00 | 150.50 | 120.40 |
| X | A8V3853651AA3FZ | GRILLE | 1.00 | 1338.00 | 1,070.40 |
| X | A8V3853949 | PLATE AP | 1.00 | 179.50 | 143.60 |
| X | A8V0010515A | STICKER | 1.00 | 6.70 | 5.36 |
| X | A8K0010520A | STICKER | 1.00 | 12.80 | 10.24 |
| X | A8V5823029A | HOOD | 1.00 | 2988.00 | 2,390.40 |
| X | A8V0823126B | EDGING | 1.00 | 26.00 | 20.80 |
| X | A8V0941773D | HEADLIGHT | 1.00 | 5193.00 | 4,154.40 |

Parts 7,915.60
Labour 0.00
Sublet 2,942.00
Menus 0.00
Lubricant 0.00

| | |
|--------------------|------------------|
| Sub-Total | 10,557.60 |
| 7% GST | 739.03 |
| Grand Total | 11,296.63 |



Received by _____

For & on behalf of
Premium Automobiles Pte Ltd