	Connerh	ASSI	GNMENT (Office)	and the second
From (Person	Grace Teo	30	Sm 0	1	Date/Time 5.2. 2020 11-414*
I stimped Co			Bill to:		
OD TP W	STTP RESTOR RES ducte No. SMC	1293 U	MV / CS	Insured	SLD 8643D
at Workshop	We Esteem R	rbormand		Tel:	SLD 8643D 65662112/87990066
J 385 Si	n miny Dowe				-
Policy No.	DI9MIRENT OU	0119	Claim No.	(MTI) 1	902181/IJH
Sum Insued.			Execut		
Make of Veh)	DOA 3-5.2019
(Client's Recor			655211	2	
	/ REP. / REV 24 HB	IS.	Jia Ling		H.O.D Endorsonest:
Date/Inn	147970 ILU14M	Person Con	notal diving	V	eluci IN 1 DUT
Date/Fine	Action/histraction (V) Est	imale		
	Smr 12034-		15		
	SLD EGUSD-	X			
6/2/20	Email preli	covided .	to Irono		
6/2/20	Email neels	covided .	to Irono		

TOTAL

261



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref:

CMTD1902181/UH

Our ref:

CS/SMO20001990/Ksf3

DATE: 6/2/2020

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.SMC 1293U

We thank you for your instruction on 5/2/2020

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/2/2020 at the premises of M/s ESTEEM PERFORMANCE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$6,561.64			
Revised Estimate Amount	: S\$3,132.36			
"Check" Items Amount	: S\$			
Market Value	: S\$			
LTA Reimbursement Value	: S\$			
Nett Value	: S\$			

Description of Damage:

The vehicle sustained damages at the

rear portion

rear

nearside

offside

front

Comments/Present Status:

Damages Consistent

Yours faithfully,

KENNETH KONG

Licensed Appraiser

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

50 Raffles F #05-01/06,	Singapore Land Tower	51 Ubi Ave 1 #01-25		25 I Park
IRENE JAM	ES HENRY	Date:	06 Feb 2020	
	Prelimin	nary Adv	ice	
d Mahiala Na	- CI D0C42D			
			Accident Date	: 03/05/2019
11414				: 05/02/2020
tion At			Lat. Duradum of Trep	un (-1
of Impact / G	eneral Description of Damages			
hicle sustaine	ed impact / damages rear portion a	and parts cla	imed are consistent	to the accident.
	Renairer's Estimate (Gross)	1-9	s 6 561 64	
	The state of the s			
	Total			
	Lump Sum Repair	:5	SS	
	Total Loss Consideration			
	New for Old Value	:8	SS	
	Pre-Accident Value			
	Margin for Repair	:5	\$	
rks				
		ount. We ha	ve also confirmed e	xcess and policy coverag
				for the wreck.
	#05-01/06, Singapore 0 IRENE JAM I Vehicle No nicle No f Inspection at thicle sustained thicken the sustained thicken the sustained thicken thicken the sustained	d Vehicle No : SLD8643D icide No : SMC1293U : HONDA SHUTTLE HYBRID f Inspection :5/2/2020 tion At :ESTEEM PERFORMANCE PTE of Impact / General Description of Damages thicle sustained impact / damages rear portion at Repairer's Estimate (Gross) Revised Amount Check Items (Estimated) Total Lump Sum Repair Total Loss Consideration New for Old Value Pre-Accident Value COE / PARF Rebate Salvage Value Margin for Repair	#05-01/06, Singapore Land Tower Singapore 048623 IRENE JAMES HENRY Date: Preliminary Adv Vehicle No : SLD8643D incle No : SMC1293U : HONDA SHUTTLE HYBRID If Inspection :5/2/2020 Ition At :ESTEEM PERFORMANCE PTE LTD of Impact / General Description of Damages hicle sustained impact / damages rear portion and parts cla Repairer's Estimate (Gross) Revised Amount Check Items (Estimated) Total :S Lump Sum Repair :S Total Loss Consideration New for Old Value Pre-Accident Value COE / PARF Rebate Salvage Value Margin for Repair :S rks The vehicle is repairable at our adjusted amount. We have the salvage with the salvage of the salvage with the s	#05-01/06, Singapore Land Tower Singapore 048623 RENE JAMES HENRY Date: 06 Feb 2020

...CLAIM SUBFOLDER...(New Assignment)

Clipt	Notified	Est Supmitted	Adj Assigned	Arr tier		STATE STATE	Contract of	The state of the s		
	04 May 2010		05 Feb 2020	1201.050		Att Sub	mitted	Inc Authors	Status	
Main	04 May 2019		11:45 Assign						New Ass Cancel Ca	
	tain .	Re	ference		Claim D	etails		Documen	its	Show All
CLAIM SU	FOLDER DE	TAILS								
Insured:	ETHOZ GR	OUP LTD, Co. F	Reg. No.: 198104	531H		_	[Create	d by insurer]		
Main Claimant:	ESTEEM L	EASING PTE LTD			5D					
Vehicle Reg, No.:	SMC129:	30			Date	of Loss:	03/05/20	19 20:00 - :59		THE STATE OF THE S
Claim Type:	STATE SHIP PARKETS IN	D1902181			Policy Note !	/Cover	[10 Months and 7 Days From LTA Reg Date (Man Yr)] D19MTRENT000119 (Third Party Only)			
Vehicle Reg. No. (Insured):	SLD8643D				Policy (Claim	No.			25 118.6	
Repairer:	Esteem Pe	rformance Pto I	M - Cla Man /		Excess	11				
Handling Insurer:	Sompo Ins	rformance Pte L urance Singapo	re Pte. Ltd. (HQ	1Q) 385 Sin () - Tel: 646	Ming Dr	ive, 575	718 Sin M	ing - Tel: ENE JAMES HEN		5280
ldjuster:	LKK Auto C	onsultants Pte	Ltd (HO) - Tel: (1756.7561	reter		de de 100	ENE JAMES HEN	RY - 6322 46	18]
Oriver/Custo fian Insured):		CHUAN () , NRIC					due 14/0	2/2020]		
ldj Asg. lemarks:	WS: JENNY	8799 0066 / 6566	2112							
SSOCIATE	D MAIL REC	EIVED								
here are no	mail for this cr	ise.							New All Co	mpose Case Mail
ALL ASSOC	ATED TASK	sΞ					447775574			
Due Date	Priority	Type Tank G	roup Subjer	ar accord			View All		Create New T	ask Complete
o results.	HEATHUR	11110470	on annie	Handl	er (Assigne	п Бу	Completed On	Create	On Done?
No results.	HILTHUK	1999.00	onto ambles	T Handl	ier g	Assigne	я Бу	Completed On	Create	On Do

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 6 February 2020 11:37 AM 'Teo, Grace': SUR; 'Henry, Irene James'

To:

'Ye, Yong Kang Melvin'

Subject:

RE: CMTD1902181/JH - LKK/ SLD8643D & SMC1293U ACC ON 03.05.2019

Attachments:

SMC 1293U PRELI ADVISED.pdf

Dear Irene.

Enclosed preliminary revised of vehicle SMC 1293U

Date of survey: 5/2/2020

Number of days (estimated): 4 days

Best Regards,

Veron Chen | Case Handler ON BEHALF OF SHIRLEY

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Wednesday, 5 February 2020 11:53 AM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>

Subject: RE: CMTD1902181/UH - LKK/ SLD8643D & SMC1293U ACC ON 03.05.2019

Dear Sir/Madam,

Thank you for the assignment.

wishing you a Happy and Prosperous Lunar New Year



Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

From: Teo, Grace <grace.teo@sompo.com.sg> Sent: Wednesday, 5 February, 2020 11:41 AM

To: jenny chong <jenny@esteemperf.com.sg>; 'admin-d@lkkauto.com' <admin-d@lkkauto.com>;

'assignments@lkkauto.com' <assignments@lkkauto.com>; sur@lkkauto.com

Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>; Henry, Irene James

<irene.henry@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1902181/IJH - LKK/ SLD8643D & SMC1293U ACC ON 03.05.2019

Our Reference: CMTD1902181/IJH

Your Reference: SMC1293U

Date: 05/02/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S ESTEEM PERFORMANCE PTE LTD

Dear Jenny,

ACCIDENT INVOLVING SLD8643D & SMC1293U ON 03.05.2019

We refer to your email reply of today.

We will appoint Mr. Kenneth of LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for SMC1293U on a without prejudice and any admission of liability basis.

Please be informed that Ms. Irene Henry is the handler of this case who can be contacted at 63224 618/ irene.henry@sompo.com.sg.

Please revert with your report upon completion of survey to my colleague, Ms. Irene.

Thank You.

Best Regards Grace Teo Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sq | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





For Travel, Personal Accident & Home Insurance | 2 For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: jenny chong <<u>jenny@esteemperf.com.sg</u>>
Sent: Wednesday, February 5, 2020 10:47 AM
To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Claims - Motor Survey < MotorSurvey@sompo.com.sg>; carmen lim < carmen@esteemperf.com.sg>; serence ctc

<serence@esteemperf.com.sg>

Subject: Re: CMTD1902181/IJH - PRI/ SLD8643D & SMC1293U ACC ON 03.05.2019

Dear Grace

We are prefer LKK - kenneth to survey the car.

Thank you

Happy New Year

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sq

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre (Showroom)

www.esteemperformance.com









On Wed, Feb 5, 2020 at 10:07 AM Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1902181/IJH

Your Reference: SMC1293U

Date: 05/02/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S ESTEEM PERFORMANCE PTE LTD

Dear Jenny,

ACCIDENT INVOLVING SLD8643D & SMC1293U ON 03.05.2019

We refer to your Notice of Accident dated 04/02/2020.

Please be informed that Ms. Irene Henry is the handler of this case who can be contacted at 63224 618/ irene.henry@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
-		Jeffrey Ong	

Please let'us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





³ For Travel, Personal Accident & Home Insurance | ³ For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: jenny chong <jenny@esteemperf.com.sg>

Sent: Tuesday, February 4, 2020 5:05 PM

To: Claims - Motor Survey < Motor Survey@sompo.com.sg>

Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>

Subject: REQUEST FOR PRI SURVEY SMC1293U

Dear Sir / Mdm,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCICDENT CASES (NIMA)

We act for Esteem Leasing Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no . SMC 1293 U.

Please be informed that the said vehicle can be inspected at :

Name of workshop: Esteem Performance Pte Ltd

Address: 385 SIN MING DRIVE (S) 575718

Tel: 8799 0066 / 6566 2112

Fax: 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Thank you.

Happy New Year

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221 F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259 (Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com







Summer Lee (LKK Auto)

From:

Teo, Grace <grace.teo@sompo.com.sg>

Sent:

Wednesday, 5 February, 2020 11:41 AM

To:

jenny chong; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com';

sur@lkkauto.com

Cc:

carmen lim; serence ctc; Henry, Irene James; Ye, Yong Kang Melvin

Subject:

CMTD1902181/JJH - LKK/ SLD8643D & SMC1293U ACC ON 03.05.2019

Attachments:

SMC1293U_03052019.pdf

Our Reference: CMTD1902181/IJH

Your Reference: SMC1293U

Date: 05/02/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S ESTEEM PERFORMANCE PTE LTD

Dear Jenny,

ACCIDENT INVOLVING SLD8643D & SMC1293U ON 03.05.2019

We refer to your email reply of today.

We will appoint Mr. Kenneth of LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for SMC1293U on a without prejudice and any admission of liability basis.

Please be informed that Ms. Irene Henry is the handler of this case who can be contacted at 63224 618/ irene.henry@sompo.com.sg .

Please revert with your report upon completion of survey to my colleague, Ms. Irene.

Thank You.

Best Regards Grace Teo Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG





¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: jenny chong <jenny@esteemperf.com.sg> Sent: Wednesday, February 5, 2020 10:47 AM To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Claims - Motor Survey <MotorSurvey@sompo.com.sg>; carmen lim <carmen@esteemperf.com.sg>; serence ctc

<serence@esteemperf.com.sg>

Subject: Re: CMTD1902181/IJH - PRI/ SLD8643D & SMC1293U ACC ON 03.05.2019

Dear Grace

We are prefer LKK - kenneth to survey the car.

Thank you



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221 F: 6484 7829

E: jenny@esteemperf.com.sq

5033 Ang Mo Kio Industrial Park 2 #01-259 (Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com





On Wed, Feb 5, 2020 at 10:07 AM Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1902181/IJH

Your Reference: SMC1293U

Date: 05/02/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S ESTEEM PERFORMANCE PTE LTD

Dear Jenny,

ACCIDENT INVOLVING SLD8643D & SMC1293U ON 03.05.2019

We refer to your Notice of Accident dated 04/02/2020.

Please be informed that Ms. Irene Henry is the handler of this case who can be contacted at 63224 618/irene.henry@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG







For Travel, Personal Accident & Home Insurance | For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

From: jenny chong < jenny@esteemperf.com.sg>

Sent: Tuesday, February 4, 2020 5:05 PM

To: Claims - Motor Survey < MotorSurvey@sompo.com.sg>

Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>

Subject: REQUEST FOR PRI SURVEY SMC1293U

Dear Sir / Mdm,
NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRACTION PROTOCOAL FOR NON INJURY MOTOR ACCICDENT CASES (NIMA)
We act for Esteem Leasing Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no . SMC 1293 U.
Please be informed that the said vehicle can be inspected at :
Name of workshop : Esteem Performance Pte Ltd
Address: 385 SIN MING DRIVE (S) 575718
Tel: 8799 0066 / 6566 2112
Fax: 6259 3326
We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.
If you fail to conduct the pre-repair inspection within the past 2 weeking do not be

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Thank you.



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221 F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre (Showroom)

www.esteemperformance.com







SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available #foresaid

ACC	IDEN	т ста		_
ACC	IDEN	ISIA	ALI EN	REM I

Date Of Report 04/05/2019 09:48 Date Of Accident 03/05/2019 20:10

Exact Location Of Accident PIE TOWARDS BEDOK

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC1293U

Insured/Policyholder

Name Of Registered Owner ESTEEM LEASING PTE LTD

Co Reg No 201807215D Email Address NOEMAIL

Mobile Phone No. (LOCAL) +65-84033656 Alternative Phone No. OFFICE-84033656

Vehicle Particulars

Manufacturer HONDA Model SHUTTLE

Exact Purpose for which vehicle was being used at time of accident

WORK PURPOSE

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

REPORTING ONLY PRIVATE HIRE

Insurance Company

Vehicle Category

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number 5101728862

Cover Note Number

Driver

Name of Driver TOH KWOH WEI NRIC No S7563595H Date Of Birth 15/04/1975

Occupation OUTDOOR Date Of Driving Pass 23/09/1999

Driving Experience 19 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-84033656

Fax Number

Contact Number

EMail Address NOEMAIL Address

BLK 147 BISHAN STREET 11 #09-25

Postcode

570147

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

OTHER - HIRER

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: GRAB PASSENGER 1

GENDER:

: FEMALE

Passenger 2

NAME:

GRAB PASSENGER 2

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

THE VEHICLE IN FRONT STOPPED. I FOLLOWED SUIT BUT VEHICLE SLD8643D KNOCKED INTO THE REAR PORTION OF MY VEHICLE. (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLD8643D

Vehicle Make/Model/Colour

MAZDA / RED

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NG LEONG CHUAN

NRIC/Passport Number

S7011227B

Contact Number

90900681

Address

Postcode

, Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)





SKETCH PLAN

ITANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as appsible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudlate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle[s] involved in this accident shall be collectively referred to as the "insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed;
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:


Oriver's Signath (If driver is not the p

Date & Time: 0 4 MAY 2019

AICO

Reporting Centre Personnel's Signature

ING WING KIN JAMES admin.vac@vicom.com.sg



0 4 MAY 2019



ESTEEM PERFORMANCE PTE LTD

Repair Estimates	SM	MC 1293 U		/	Not 1	organi
Parts (a) Cost / List Price Items	\$	4,408.30			cong	B4 pa
Plus/Less 20%	\$	881.66				
Total of Cost / List	\$	3,526.64	DOCALL	o Consults	titl) himse notify	
(b) Nett Price Items			- To remen		following:	
Less			* Party 210			
Total of Nett Item			= 1 me par			
(c) Special Nett Items	\$	295.00				and Accounty
otal Parts Cost	\$	3,821.64	Southern Control	and by Please		
abour	\$	2,740.00	Control Control			
otal The above total will be subjected to	\$ 7% G.S.T.	6,561.64				
	\$ 7% G.S.T.		Kenneth			
he above total will be subjected to	Hamilton II		Kenseth CKK			
he above total will be subjected to Name of Surveyor	Hamilton II		2/2	t		
he above total will be subjected to Name of Surveyor Company	Hamilton II		2/2			
Name of Surveyor Company Survey conducted on		5/2	2/20 a			
Name of Surveyor Company Survey conducted on Remarks By Surveyor	authorized /	5/3	2/20 a			
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	authorized /	5/2	2/20_a			
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is (b) Recommended Days of Rep	authorized /	is not authorized until furth OC Required / Not Required	2/20_a	t	5/2/2	



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

ν	ehi	cle	e i	No.	
				91	

Make & Model: Chassis No

SMC 1293 U

HONDA SHUTTLE GP71213362

Submit By

Year Manufacture

JENNY

2018

Engine No. Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	M	1	\$120.00		
2	Rear windscreen sealant	M	1	\$50.00	s.N	Posa
3	Reverse sensor	Su	2	\$200.00	S.N	X
4	Rear number plate	h	1	\$45.00	S.N	×
5	Rear No.plate lamp LH	5~	1	\$38.50		×
6	Rear No.plate lamp RH	1-	11	\$38.50		X
7	Rear bumper	nu	1	\$1,150.60		
8	Rear bumper clip	m	10	\$35.00		
9	Rear bumper side retainer LH	54	1	\$26.50		×
10	Rear bumper side retainer RH	5	1	\$26.50		×
11	Rear bumper bracket LH	n	-1	\$48.70		×
12	Rear bumper bracket RH	N	110	\$48.70	-	1
13	Rear bumper sponge	5~	2	\$179.00		X
14	Tail door	R	1	\$1,193.00		_
15	Tail door lock	n	1	\$157.10		X
16	Tail door emblem	ne	1	\$38.00		<u> </u>
17	Wording "SHUTTLE"	14	-1	\$55.00		
18	Wording "HYBRID"	na	1	\$80.10		
19	Tail door chrome	5	1	\$383,10		×
20	Taildoor reflector LH	Sa	1	\$395.00		×
21	Taildoor reflector RH	5-	1	\$395.00		1
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	SMC 1293 U	Submit By	:	SERENCE	
Make & Model	21	TOYOTA PRIUS	Year of Manufacture	:	2017	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR,		
	SPARE TYRE COMPARTMENT)	\$1,000.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR,		
	SPARE TYRE COMPARTMENT)	\$1,000.00	4001
3	To tuff coat.	\$150.00	301
4	TO Check wiring	\$50.00	15%
5	To transfer boot mechanism to new boot	\$120.00	601
6	To conduct water leakage tests to ensure proper air and		
	sealing	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	501
8	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/SMO20001990/KSF3N2

Date:

03/03/2020

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd.

Policy No:

D19MTRENT000119

Claimant Vehicle

SMC1293U

Insured Vehicle No: SLD8643D

Date of Loss:

03/05/2019

Nature of Claim:

TP

Claim No: CMTD1902181

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No :

SMC1293U

Make & Model:

HONDA SHUTTLE HYBRID, 1.5 (A) 26/06/2018 (Man. Year: 2018)

Engine No:

LEB6556236

Reg. Date: Colour:

Metallic Black

Chassis No: Odometer:

GP71213362 140733 km

Engine Capacity: Market Value/New Car Price:

1496 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

185/60R15

Rear Tyre Size:

185/60R15

Front Left Side: Front Right Side: ROADMARCH 9 mm ROADMARCH 9 mm Rear Left Side: Rear Right Side: West Lake 8 mm West Lake 8 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
3,821.64	2,177.36	1,644.28	43.03
0.00	0.00	0.00	
2,740.00	955.00	1,785.00	65.15
0.00	0.00	0.00	
0.00	0.00	0,00	
6,561.64	3,132.36	3,429.28	52.26
+ GST 7.00/7.00% (S\$) 459.31 2	219.27	240.04	52.26
7,020.95	3,351.63	3,669.32	52.26
	3,821.64 0.00 2,740.00 0.00 0.00 6,561.64 459.31	3,821.64 2,177.36 0.00 0.00 2,740.00 955.00 0.00 0.00 0.00 0.00 6,561.64 3,132.36 459.31 219.27	3,821.64 2,177.36 1,644.28 0.00 0.00 0.00 0.00 2,740.00 955.00 1,785.00 0.00 0.00 0.00 0.00 0.00 0.00 6,561.64 3,132.36 3,429.28 459.31 219.27 240.04

INSPECTION

Date of Assignment:

Date Inspected:

05/02/2020

05/02/2020 Inspected At:

Esteem Performance Pte Ltd - Sin Ming (HQ)

385 Sin Ming Drive Singapore 575718

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference

REPAIR DETAILS

Part Source: (Last Synchronised: 28 Feb 2020)

Parts: HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for SMC1293U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
2	1		*REAR NO PLATE LAMP LH	Serviceable	38.50 FL	*-FL
3	1		*REAR NO PLATE LAMP RH	Serviceable	38.50 FL	*-FL
4	1		*REAR BUMPER	Dented	1,150.60 FL	*1,150.60 FL
5	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
6	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	26.50 FL	*-FL
7	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	26.50 FL	*-FL
8	1		*REAR BUMPER BRACKET LH	Repair	48.70 FL	*-FL
9	1		*REAR BUMPER BRACKET RH	Repair	48.70 FL	*-FL
10	2		*REAR BUMPER SPONGE	Serviceable	179.00 FL	*-FL
11	1		*TAIL DOOR	Bent	1,193.00 FL	*1,193,00 FL
12	1		*TAIL DOOR LOCK	Repair	157,10FL	*-FL
13	1		*TAIL DOOR EMBLEM	Necessary	38.00 FL	*38.00 FL
14	1		*WORDING SHUTTLE	Necessary	55.00 FL	*55.00 FL
15	1		*WORDING HYBRID	Necessary	80.10 FL	*80.10 FL
16	1		*TAIL DOOR CHROME	Serviceable	383.10 FL	*+FL
17	1		*TAILDOOR REFLECTOR LH	Serviceable	395.00 FL	*-FL
18	1		*TAILDOOR REFLECTOR RH	Serviceable	395.00 FL	*-FL
19	1		*REAR WINDSCREEN SEALANT	Necessary	50.00FS	*40.00 FS
20	2		*REVERSE SENSOR	Serviceable	200.00 FS	*-FS
21	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*-FS
F=Fra	nchise ;	part. S=SpcNe	ett. L=ListttemDisc.	_	1000 10	
				Sub Total (S\$)	4,703.30	2,711.70
			- List Item Discount on L	Items 20.00/20.00% (S\$)	881.66	534.34
				Total Parts (S\$)	3,821.64	2,177.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL,TAILDOOR,SPARE TYRE COMPARTMENT)	New	1,000.00	400.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, SPARE TYRE COMPARTMENT)	New	1,000.00	400.00
3	TO TUFF COAT	New	150.00	30.00
4	TO CHECK WIRING	New	50.00	15.00
5	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120,00	60.00
6	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
7	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
8	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
	Gross Labor	ur Cost (S\$)	2,740.00	955.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >