

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27153

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0106/2020/NS
Date	:	24-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Premium Leasing Pte Ltd
Address	:	9 Leng Kee Road Singapore 159090
Telephone	:	+65 64712123
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SLP 7242 X
Model Code	:	Audi Q2 Sport 1.4 TFSI
Model / Year	:	Jun-17
Engine No	:	CHZ 300978
Chassis No	:	WAUZZZGA6HA022118
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Jan-20
Place of Accident	:	Along Rd 1 Stevens Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7242 X

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 ✓	
2	To remove and transfer lhs rear door's multi-lock and power window devices.	S/N \$	280.00 ✗	
3	To dismantle lhs front door panel trim. To remove and renew lhs wing mirror mounting.	S/N \$	400.00 ✗	
4	To dismantle and renew rear bumper and lhs rear door. To repair lhs rear door. To repair lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00 500.	
5	To respray rear bumper, rear lower bumper, lhs front door, lhs wing mirror cover, lhs rear door, door cover, door handle, lhs rear fender and both rear wheel arch trims. ✓	\$	6,400.00 1100.	
6	To carry out diagnostic check.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	<u><u>\$ 10,352.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR TOP BUMPER	\$ 1,108.00	Rx
2	REAR BUMPER FIXING PARTS	\$ 73.00	X
3	REAR MIDDLE BUMPER	\$ 733.00	X
4	WHEEL HOUSING LINER TRIM - LH	\$ 26.00	X
5	REAR BUMPER SPOILER - LH	\$ 545.00	Y
6	REAR LIGHT REFLECTOR - LH	\$ 28.00	X
7	REAR BUMPER GUIDE SECTION - LH	\$ 51.00	X
8	REAR WHEEL COVER - LH / RH	2 \$ 852.00	* ? plus p.
9	REAR DOOR - LH	\$ 2,380.00	X NC
10	REAR DOOR OUTER SEAL - LH	NEC \$ 127.00	X
11	BONDING AGENT	NEC \$ 46.00	X
12	CLEANING SOLUTION	NEC \$ 64.00	X
13	REAR DOOR ATTACHMENT PARTS	\$ 89.00	X
14	REAR DOOR CATCH	\$ 113.00	X
15	REAR DOOR COVER - LH	\$ 290.00	cut ✓
16	EXTERIOR MIRROR MOUNTING	\$ 485.00	X NC
17	MIRROR CAP - LH	\$ 159.00	X NC
18	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$ 7,469.00	
TOTAL LABOUR CHARGES		: \$ 10,352.00	
GRAND TOTAL		: \$ 17,821.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Taufki 97495744

Surveyed Date

: 4/2/20 @ 1020

Authorised Date

:

Excess Cost

:

Not Authorised

Liability

:

Ex to be advise.

Remarks

:

Resurvey before print.
04 days
sur @ Kuantan.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant