

Ala d.



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

not Authorized
2/5 @ 3100
4 days.

Car Number: SGA2228J

Date: 05/02/2020

Model: Honda Accord

Damaged Area: (Right Side Portion Damaged)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

Parts / Material:

	Quantity	
1 Front RH Door	body 050/serf	987.00
2 Front RH Outer Door Handle Garnish	\$ 5.00	390.00
3 Front RH Outer Door Handle Garnish Cap	\$ 1.1	112.00 X
4 Front RH Door Inner Lock	\$ 1.1	286.00 X
5 Front RH Door Inner Trimboard Clips	\$ 1.1	60.00 X
6 Front RH Door Weather Strip	\$ 1.1	295.00 X
7 Front RH Door Sticker	\$ 1.1	165.00
8 Centre Door Inner Pillar RH	\$ 1.1	986.00 X
9 Rear RH Door	\$375.00 X 2 pcs	\$ 10/serf 897.00
10 Rear RH Door Hinge (Top)	\$119.20 X 2 pcs	\$ 1.1 48.00 X
11 Rear RH Door Hinge (Bottom)		\$ 1.1 46.00 X
12 Rear RH Door Linkage		\$ 1.1 55.00 X
13 Rear RH Door Inner Trimboard Clips		\$ 1.1 60.00 X
14 Rear RH Door Weather Strip		\$ 1.1 275.00 X
15 Rear RH Door Quarter Glass Moulding Seal (Set)		\$ 1.1 324.00 X
16 Rear RH Door Sticker		\$ 1.1 155.00
17 Right Rocker Garnish	be/ \$ 1.1	672.00
18 Right Rocker Garnish Clips	\$ 1.1	60.00
Parts: \$		5,873.00
Less Parts 20%: \$		1,174.60
Total Parts: \$		4,698.40

Labour:

To Remove, Repair & Renew Affected Accident Areas	\$	1,200.00 400
To Putty, Spray Paint on Affected Accident Areas	\$	1,000.00 700
To Check & Re-Connect all electrical wiring	\$	50.00 20
To Remove & Install Front RH Door Components	\$	200.00 60
To Remove & Install Rear RH Door Components	\$	200.00 60
To Remove & Install Rear RH Door Quarter Glass	\$	150.00 X
To Rust Proof Affected Areas	\$	200.00 60
Total Labour: \$		3,000.00

TOTAL PARTS: \$ 4,698.40

TOTAL LABOUR: \$ 3,000.00

TOTAL REPAIR COST: \$ 7,698.40

LKK Auto Consultants / Total Labour: \$ 3,000.00

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No other claim(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 3221.50
202
2577.20
3877.20
3101.76