



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002012/Eda3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 340T	Veh. Inspected	SLR 1067P
Policy No.	D-20094921MFSH	Coverage (\$)	0.00
Claim No.	D20000783MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	04/02/2020

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JMYSRCY1AGU007247	Colour	GREY
Odometer	189888	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	NEUTON	5 mm
L/H Front Tyre	205/60 R16	NEUTON	5 mm
R/H Rear Tyre	205/60 R16	NEUTON	5 mm
L/H Rear Tyre	205/60 R16	NEUTON	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/01/2020	Inspection Date	05/02/2020
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**