



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002023/Dda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-05-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6387C	Veh. Inspected	FBJ 3577G
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D20000801MFSH/1	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	05/02/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA CBR400	c.c	399
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	NC471000651	Colour	BLACK
Odometer	102774	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	BRIDGESTONE	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60 R17	BRIDGESTONE	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS
--

5. General Information

Accident Date	01/02/2020	Inspection Date	05/02/2020
Survey held at	S9 MOTOR TRADING PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------