

Kp

MULTILATERAL SERVICES
160, Sin Ming Drive, Sin Ming Auto City,
#06-01 Singapore 575722
Tel: 6453 5654, 6459 1630 Fax: 6459 1698
Reg. No. 46956800/C

Not Authorised
L/L Rep @ 2250p
Money After Repair
9 days

Date : 24/02/2020

QUOTATION -THIRD PARTY CLAIM

FWD SINGAPORE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : SLF 7177 D
Model : MERCEDES E200d
Insured Ins: NTUC INCOME
GST Reg. No : 19 - 9603355 - R

Accident on : '24/01/2019

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SGG 1701 J		
1	FRONT RH DOOR <i>1753</i> <i>Ref/way</i>	\$ 2,485.00	✓
1	FRONT RH DOOR LOCK	\$ 980.00	X
1	FRONT RH DOOR WINDOW CHROME MOULDING	\$ 520.00	X
1	FRONT RH DOOR INNER RUBBER <i>301</i> <i>me</i>	\$ 385.00	<i>501m</i>
1	FRONT RH DOOR LOWER CHROME <i>205</i>	\$ 580.00	✓
1	REAR RH DOOR	REPAIR	
	TOTAL :	\$ 4,950.00	
	LESS 10%	\$ 4,455.00	
	Total Parts :	\$ 4,455.00	
	Balance b/f	\$ 4,455.00	
	<u>LABOUR CHARGES</u>		
	Labour charges, to do cutting, welding, replace repair accident affected area	\$ 600.00	<i>2501</i>
	To transfer door parts to another door	\$ 100.00	<i>601</i>
	To do computer setting for door after repair	\$ 150.00	<i>7001</i>
	To check wiring system on accident area	\$ 120.00	<i>201</i>
	Anti rust		
	To do spray painting on accident affected area	\$ 600.00	<i>4801</i>
	Remove refix , replace garnish , side trim, firm board, car seat upholstery etc	\$ 150.00	X
	Total Labour :	\$ 1,720.00	
	TOTAL PARTS & LABOUR :	\$ 6,175.00	