

Not Authorized
11 Day @ 6300k
Recovery After Paint 3 days

ESTIMATE

Date: 4/2/2020
 DOA: 2/2/2020

Vehicle No: SML2443A
 Make & Model: Audi A5 2.0 A

S/N	Qty	Item Description	Parts	Price	Surveyor
1	1	Rear Boot Lid	R	\$ 2,236.30	X
7	1	Rear Boot Lid Lock Mechanism	R	\$ 117.20	X
8	1	Rear Boot Lid Lock Catch	R	\$ 97.20	X
9	1	Rear Boot Lid WeatherStrip	Sm	\$ 178.70	X
12	1	Rear End Panel (Outer)	R	\$ 850.00	X
13	1	Rear End Panel Top Garnish	Sm	\$ 135.90	X
14	2	Rear Fender Inner Trim	Sm	\$ 1,243.90	X
15	2	Tail Lamp	Sm	\$ 1,926.00	X
16	2	Tail Lamp Side Retainer	Sm	\$ 83.50	X
17	2	Fender Inner Shield	Sm	\$ 299.60	X
18	1	Rear Bumper Assy <i>1210</i>	Bu	\$ 1,468.60	X
19	2	Rear Bumper Retainer	cls 0.1	\$ 180.60	X
21	1	Rear Bumper Reinforcement <i>410</i>	Bu	\$ 494.90	X
23	2	Rear Bumper Reinforcement Bracket	R	\$ 452.20	X
25	1	Rear Bumper Inner Garnish	Sm	\$ 264.30	X
27	1	Rear Bumper Tow Cover	Sm	\$ 148.50	X
29	1	Rear Bumper Parking Sensor	DM	\$ 959.80	X <i>239.95</i>
31	1	Rear Bumper Parking Sensor Holder	Sm	\$ 216.00	X <i>54</i>
33	1	Rear Bumper Parking Sensor Wiring	R	\$ 473.50	X
35	2	Rear Exhaust Bracket	R	\$ 120.90	X
37	2	Rear Exhaust Mounting	Sm	\$ 127.90	X
				\$ 12,075.50	
				\$ 1,207.55	
				\$ 10,867.95	

Less 10%

Special Nett Items		Price	Surveyor
1	Sundries	\$ 50.00	X
2	1 Rear Boot Lid Logo	\$ 180.00	X
3	1 Rear End Lower Panel (Inner) Sealant	na \$ 120.00	X
4	1 Rear End Top Panel (Inner) Sealant	\$ 120.00	X
5	1 Rear End Panel (Outer) Sealant	\$ 120.00	X
6	1 set Rear End Panel Top Garnish Clips	\$ 80.00	X
7	2 set Rear Fender Inner Trim Clips	na \$ 120.00	X
8	2 Rear Tail Lamp Tinting	\$ 300.00	X
9	2 set Tail Lamp Clips	na \$ 50.00	X
10	2 set Fender Inner Shield Clips	\$ 60.00	X
11	1 set Rear Bumper Assy Clips	\$ 50.00	X
12	1 set Rear Bumper Lower Garnish Clips	\$ 60.00	X
13	1 Rear Bumper Lower Diffuser Lip <i>1500</i>	CM \$ 1,800.00	X
14	1 set Rear Bumper Lower Diffuser Lip Clips	na \$ 80.00	X
15	1 Rear Bumper Lower Diffuser Lip Sealant	\$ 120.00	X
16	1 set Rear Exhaust Assy <i>3400</i>	Bu \$ 4,800.00	X
17	1 set Rear No. Plate with Garnish	na \$ 80.00	X