


# MBM WHEELPOWER PTE LTD



Your Ref: SLM4009P

Our Ref: SMP6244K

To: AIG

CC

Fax

Date: 5/2/2020  
From: Eryx Tan  
Fax: 64525333  
Contact: 93288668  
Make / Model: HONDA STEPWAGON SPADA 1.5  
Chassis No.: RP31232237  
Engine No.: L15B5145522  
Year of Make: 2019  
Accident Date: 17 January 2020

ESTIMATE FOR VEHICLE NO. : SMP6244K

## LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$ 500.00 *400*

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 600.00 *440*

|                     |           |                 |
|---------------------|-----------|-----------------|
| Total:              | \$        | 1,100.00        |
| 7% GST:             | \$        | 77.00           |
| <b>Grand Total:</b> | <b>\$</b> | <b>1,177.00</b> |

*Not Notified  
Before After Paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd  
160 SIN MING DRIVE  
#06-02  
SIN MING AUTOCITY  
t 62628888 f 64525333

Company Registration Number : 200204110W