



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBQ4364K LAMBRETTA V200 SPECIAL REPAIR ESTIMATE

ITEM	DESCRIPTION	AMOUNT SGD
1	SIDE GUARD RH	\$180.00 cut
2	REAR SIDE FAIRING RH	\$150.00 Rp
3	STICKER LAMBRETTA RH	\$48.00 res
4	FRONT FENDER	\$110.00 cut
5	FRONT LICENCE PLATE X2 @\$12	\$24.00 res
6	FRONT BEADING LH - SILVER	\$45.00 cut
7	BRAKE LEVER LH -SILVER	\$22.00 bt
8	BALANCER COVER LH SILVER	\$12.00 cut
9	SIDE MIRROR LH-CHROME	\$45.00 cut
10	FRONT BEADING LOWER LH - SILVER	\$38.00 cut
11	REAR FOOTREST LH	\$25.00 cut
12	SIDE STAND	\$45.00 Rp
13	MAIN STAND	\$85.00 bt
14	SIDE GUARD LH-CHROME	\$180.00 cut
15	CLUTCH COVER	\$185.00 del
16	REAR SIDE FAIRING LH	\$150.00 Rp
17	STICKER LAMBRETTA LH	\$45.00 res
18	REAR TOP BOX (BOLD)	\$280.00 cut
19	SPRAN PAINTING	\$600.00 400
20	WORKMANSHIP TO REPLACE DAMAGED PARTS	\$300.00 200
21	HEAT PROTECTION	\$65.00 bt
22	TRANSPORTION TP - IDAC - BIKESHOP	\$100.00 80
23	TO RE-ALIGN FRONT FORK	\$150.00 120 X plus MAX
24	CONE BEARING SET	\$80.00 X an

TOTAL \$ \$2,964.00

Tanpin 97445749

WP

15/7/20 @ 1130

4-5 days

Tanpin @ 11hant.com

Recovery before/after paint.

To check 4/5 - (p/r)

Part 1389

10% - 1250.10

Labour - 680

\$1930.10

4 days

Recovery 31/8