

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366.2323 Fax : (65) 6841 1183

Supplementary Estimate 1

CST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims I

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0136/2020/NS

6-Feb-20

Raymond Ting

1 of 1

SMP 4729 S

Audi A4 SEDAN 2.0 TFSI 8W

Quantity Description

Unit Price

Amount

Labour

1 To dismantled and renew both headlight.

\$

700.00

nn

\$

700.00

TOTAL

\$

700.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0136/2020/NS

14-Feb-20

Glory Tan

1 of 1

SMP 4729 S

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Shock absorber mounting LHS <i>bl</i>	\$ 59.00	46.72
2	Shock absorber mounting RHS <i>bl</i>	\$ 59.00	46.72
3	Front bumper securing strips <i>ms</i>	\$ 67.00	52.96
4	Lift cylinder RHS <i>cr</i>	\$ 198.00	158
5	Bracket for lift cylinder RHS <i>Xnn</i>	\$ 12.00	
6	Lift cylinder hose <i>cut</i>	\$ 88.00	69.68
7	Ready mix-coolant -25" <i>cr</i>	\$ 169.00	134.72
8	Air mass meter <i>cr</i>	\$ 546.00	436.40
9	Coolant pipe - return <i>cut</i>	\$ 91.00	72.24
10	Silicone sealant <i>nee</i>	\$ 116.00	92.16
11	Tube for oil dipstick <i>cut</i>	\$ 106.00	84.40
12	Engine mounting RHS <i>cr</i>	\$ 397.00	317.60
13	Hexagon head bolt (combi) <i>cr</i>	\$ 46.00	36.16
14	Single wire seal lead with 1 contact in the bag -1500MM <i>cut</i>	\$ 465.00	372
15	1 set single wires each with 2 silver-plated contacts <i>cut</i>	\$ 251.00	200.80
16	Cable guide for headlamps <i>ms</i>	\$ 19.00	14.48

Labours

1	To cut out and weld both front shock absorber mountings.	\$ 1,050.00	500 x
---	--	-------------	-------

Labours total	\$ 1,050.00
Parts total	\$ 2,689.00
TOTAL	\$ 3,739.00

For Premium Automobiles Pte Ltd

Authorised Signature

Rajul

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Steve 18/2/20, 4.00pm

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

14-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Engine mounting LHS / BR	\$ 397.00	317.60
2	Hexagon head bolt (combi) / MC	\$ 46.00	X
3	Gearbox mounting (Rear) / BR	\$ 199.00	159.60
4	Gearbox support (Rear) / MC	\$ 77.00	61.20
5	Stop (Rear) / BR	\$ 61.00	48.64
6	Transmission oil sump / BR	\$ 323.00	258.40
7	Hex socket head bolt (combi) / MC	\$ 65.00	52
8	Coolant hose feed/return / cut? ✓	\$ 25.00	19.60
9	Potential distributor fuse / Short (Putting cable) ✓	\$ 500.00	400
10	Guard plate RHS / DD	\$ 30.00	23.92
11	Dual clutch transmission fluid atf 1.0 Ltr / MC	\$ 847.00	677.60
12	Retainer for exhaust pipe / nec? ✓	\$ 33.00	26.16
13	Hexagon bolt / MC	\$ 70.00	55.68

Labours

1	To renew engine mounting, gearbox mounting, transmission oil sump and potential distributor fuse.	S/N \$ 600.00 / ✓
---	---	-------------------

Labours total	\$ 600.00
Parts total	\$ 2,673.00
TOTAL	\$ 3,273.00

For Premium Automobiles Pte Ltd

add
chassis member LH (To repair)

repair day (TBA)

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Steve 19/2/20

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

19-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
Parts			
1	Coolant pipe ✓ TN	\$ 67.00	53.44
2	Exhaust pipe with front silencer ✓ DO	\$ 863.00	690.40
3	Seal ✓ APC	\$ 11.00	8.48
4	Heat shield for bulkhead ✓ TN	\$ 106.00	84.80

Labours

- 1 To remove and renew exhaust pipe with front silencer. Align to position.

S/N \$ 480.00 ✓

TOTAL

\$ 1,527.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

24-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Subframe cross member <i>cm /</i>	\$ 602.00	481.60
2	Socket head bolt with inner multipoint head <i>na /</i>	\$ 22.00	19.96

TOTAL

\$ 624.00

For Premium Automobiles Pte Ltd

Authorised Signature

Pam
25/02/2020
add ~~extra~~ xtra
4 days

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

25-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity Description

Unit Price Amount

Parts

- | Quantity | Description |
|----------|------------------------|
| 1 | Lhs front tyre |
| 2 | Tyre monitoring system |

nn TBC *tn 3 X inconsistent*
TBC *nn*

Labours

- | Quantity | Description |
|----------|---|
| 1 | To repair and respray front lhs chassis member. |

\$ 2,800.00 *1550 nn X*
check with Rasal

TOTAL

\$ 2,800.00

For Premium Automobiles Pte Ltd

Authorised Signature

Steve
26/2/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

27-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Engine support bearing RHS b1	\$ 64.00	50.88

TOTAL

\$ 64.00

For Premium Automobiles Pte Ltd

Paul
27/02/2020

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

3-Mar-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Lift cylinder LHS ? see photo CM ✓	\$ 198.00	158

TOTAL

\$ 198.00

For Premium Automobiles Pte Ltd

Authorised Signature

Stere
3/3/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

3-Mar-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Noise insulation rear <i>hu</i> ✓	\$ 371.00	296.40
2	Noise insulation front <i>xu</i> ✓	\$ 537.00	429.60

TOTAL

\$ 908.00

For Premium Automobiles Pte Ltd



Authorised Signature