



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HAI HOCK DONALD
BLK 113 RIVERVALE WALK #14-43
SINGAPORE 540113

Attention : THE OWNER
Contact : 97281488

Estimate : ES006917

Date : 05/02/2020
Vehicle Num. : SJN4452K
Make/Model : NISSAN TEANA 2.0-2009
Chassis/Eng# : JN1BDUJ32Z0000572/MR20678938A
Accident Date : 04/02/2020
Claim No. :
Reference :
Policy No. :

Not Noted
11 Lmp & ?
Repair After Pain
4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

NETT ITEMS :				
1.	1	BONNET	1,050.00	—
2.	1	BONNET LOCK	325.00	X
3.	1	RADIATOR GRILLE	642.00	—
4.	1	HEADLAMP L/H	830.00	—
5.	1	HEADLAMP BRACKET L/H	186.00	?
6.	1	FRONT BUMPER	955.00	—
7.	1	FRONT BUMPER REINFORCEMENT	683.00	X
8.	1	FRONT BUMPER SPONGE	176.00	?
9.	1	FOG LAMP L/H	460.00	?
10.	1	FRONT BUMPER LOWER COVER GARNISH L/H	288.00	?
Nett Total S\$:			5,595.00	
10.00% Discount S\$:			559.50	
			5,035.50	

SPECIAL NETT ITEMS :				
1.	1	RADIATOR GRILLE LOGO	63.00	—
2.	2	HEADLAMP CLIP L/H	5.50	—
3.	6	FRONT BUMPER CLIP	5.00	—
4.	2	FRONT BUMPER CHROME MOULDING	232.00	—
5.	2	FRONT BUMPER BRACKET	211.00	X
6.	1	FOG LAMP GARNISH L/H	163.00	?
7.	1	FRONT NUMBER PLATE	25.00	X
8.	1	FRONT NUMBER PLATE GARNISH	184.00	—
9.	1	FRONT NUMBER PLATE HOLDER	33.00	—
Special Nett Total S\$:			1,395.00	
LABOUR :			90.00	206
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HAI HOCK DONALD
BLK 113 RIVERVALE WALK #14-43
SINGAPORE 540113

Attention : THE OWNER
Contact : 97281488

Estimate : ES006917

Date : 05/02/2020
Vehicle Num. : SJN4452K
Make/Model : NISSAN TEANA 2.0-2009
Chassis/Eng# : JN1BDUJ32Z0000572/MR20678938A
Accident Date : 04/02/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		RUST PROOFING TREATMENT		100.00
		SPRAY PAINT DAMAGED AREA AFFECTED	450l	900.00
		TO KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	500l	980.00
		Labour Total S\$:		2,070.00

SingDollars : Eight Thousand Five Hundred & Cents Fifty Only

Total S\$: 8,500.50
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun