

12/20/2004

AES REC BY:

RFP: CS/ICA20002096/Grd3

Special Instruction:

Surveyor: Quoqiand

ASSIGNMENT (Office)

From (Person): Muhammad Hakimullah of ICA Date/Time: 6/02/2020

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 2239J Insured: _____

at Workshop m/s Traxx Motor Tel: 6459 2338

of 9 Tagore Lane #04-02

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14/02/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 12:17pm @ 6/2/2020 Person Contacted: Rebecca Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Estimate (✓)</u>
	<u>FBK 2239J-x</u>
<u>18/3/20</u>	<u>@ 12:15pm David said vehicle not repair yet</u>

REC BY: @Q. REF: ICA


ASSIGNMENT

14 May 2015

From: Hakim
 Date: 9839 T186
 Estimated Cost: 9839 T186
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Traxx Motor
 of David - 98207919
 Insured: 64592338
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: PBK 229J Yr Regn: 2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Adventure
 Make: BMW F800GS c.c. 798
 Colour: Black & Red A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WB10B 050 6E.8 30 3335
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Tyre Size: F: _____ R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 06-02-20
 Survey held at w/s Si30 pm

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/2/20	@ 1131am Spoken to Hakim, explain to him for the check items Cob: 5067

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____

1) Date/Time, File Return to?
 2) _____

Resurvey No. of Trip: _____

Request Format:
 Equip. Sum / M.B. etc

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Insp (\$) : Wash end (\$)

Survey Fee: _____
 Transportation: _____ \$ + RS. _____ \$
 Photos: _____
 Other: _____
 P.T.L. _____

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 7 February 2020 5:38 PM
To: Muhammad Hakimullah MOHAMED IKBAR (ICA)
Cc: Revathy_KARUPAN@ica.gov.sg; GAN_Lip_Tat@ica.gov.sg; June_ENG@ica.gov.sg; LOW_Soo_Hue@ica.gov.sg; SUR
Subject: RE: Quotations for Pre-Repair Assessment-FBK 2239J
Attachments: FBK 2239J (PRELI REVISED).pdf

Dear Hakim,

Enclosed preliminary revised of vehicle FBK2239J
Date of survey: 6/2/2020
Number of days (estimated) : 3 days

Please provides ref. number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Hakimullah MOHAMED IKBAR (ICA) <Muhammad_Hakimullah_MOHAMED_IKBAR@ica.gov.sg>
Sent: Tuesday, 4 February, 2020 9:48 AM
To: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Cc: assignments@lkkauto.com; Revathy KARUPAN (ICA) <Revathy_KARUPAN@ica.gov.sg>; Lip Tat GAN (ICA) <GAN_Lip_Tat@ica.gov.sg>; June ENG (ICA) <June_ENG@ica.gov.sg>; Soo Hue LOW (ICA) <LOW_Soo_Hue@ica.gov.sg>
Subject: RE: Quotations for Pre-Repair Assessment


Message Classification: Restricted

Hi Nivitha,

ICA would be engaging LKK to conduct a physical pre-repair inspection. Pls link us up with the relevant party to discuss on the necessary. Thank you.

Best Regards,

Muhammad Hakimullah Bin Mohamed Ikbar
Senior Officer (Admin Planning), Corporate Services
Integrated Checkpoints Command (Land)
Immigration & Checkpoints Authority



Immigration & Checkpoints Authority W ica.gov.sg FB fb.com/Immigration.Checkpoints.Authority

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: Friday, 31 January 2020 8:57 AM
To: Muhammad Hakimullah MOHAMED IKBAR (ICA) <Muhammad_Hakimullah_MOHAMED_IKBAR@ica.gov.sg>; assignments@lkkauto.com
Cc: Lip Tat GAN (ICA) <GAN_Lip_Tat@ica.gov.sg>
Subject: RE: Quotations for Pre-Repair Assessment

Dear Sir/Mdm,

Thank you for the email.

Please be informed that our quotation for the pre and post-repair is \$280.00.

All above charges are subject to GST 7%.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Hakimullah MOHAMED IKBAR (ICA)
[mailto:Muhammad_Hakimullah_MOHAMED_IKBAR@ica.gov.sg]
Sent: Wednesday, 29 January 2020 12:16 PM
To: assignments@lkkauto.com
Cc: Lip Tat GAN (ICA)
Subject: Quotations for Pre-Repair Assessment

Message Classification: Restricted


Hi,

A member of public is seeking compensation for damage sustained to his motorcycle at Woodlands Checkpoint. We've been told that the motorcycle is at a workshop, yet to be repaired. The claimant's lawyers have also provided pictures of the damaged motorcycle. Hence, we are seeking:

- a. A quotation to perform a physical pre-repair assessment and
- b. Information on the procedures involved in doing such pre-repair assessments for e.g., the location of the repair assessment, should the claimant be there, etc.

Expecting your reply at the soonest. Thank you.

Best Regards,
Muhammad Hakimullah Bin Mohamed Ikbar
Senior Officer (Admin Planning), Corporate Services
Integrated Checkpoints Command (Land)
Immigration & Checkpoints Authority
DID: (65) 6767 2143



Immigration & Checkpoints Authority W ica.gov.sg FB fb.com/Immigration.Checkpoints.Authority

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: PLEASE ADVISED

Our Ref: CS/ICA20002096/Gvd3

Date: 7/2/2020

M/s IMMIGRATION & CHECKPOINTS AUTHORITY SINGAPORE

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO : FBK 2239J

We thank you for the instruction on 6/2/2020


Please be informed that we had conducted the inspection of the abovementioned vehicle on 6/2/2020 at the premises of M/s TRAXX MOTOR COMPANY PTE LTD and have the following to report:-

Workshop Estimate Amount : S\$ 24,198.60
Revised Estimate Amount : S\$ 17,338.83
" Check" Items Amount : S\$ 1,472.94
Market Value : S\$ _____
LTA Reimbursement Value : S\$ _____
Nett Value : S\$ _____

Description of Damage:

The vehicle sustained damages at the o/s and n/s body.

Comments/ Present Status:
Damages Consistent



Yours Faithfully,

XING GUO QIANG (HP 8288 0282)
M.MATAI, AMSAE-A
Automotive Assessor

Nivitha (LKK Auto)

From: Muhammad Hakimullah MOHAMED IKBAR (ICA)
<Muhammad_Hakimullah_MOHAMED_IKBAR@ica.gov.sg>
Sent: Thursday, 6 February 2020 11:53 AM
To: Nivitha (LKK Auto); ASSIGNMENTS@LKKAUTO.COM
Cc: Revathy KARUPAN (ICA); Lip Tat GAN (ICA); June ENG (ICA); Soo Hue LOW (ICA)
Subject: RE: Quotations for Pre-Repair Assessment
Attachments: 20191129 Letter to AGC.pdf

Message Classification: Restricted

Hi Nivitha,


Pls find the appended docs for conducting the inspection. The workshop is TRAXX Motor Company Pte Ltd.

In addition, would you be able to provide an estimate of the repair cost (a range if need be) based on the photos in the appended docs **before** the physical inspection is done? There's some urgency to obtain a cost estimate from the legal side of this case. How soon would we be able to get an estimate and would there be additional charges?

Thank you.

Best Regards,

Muhammad Hakimullah Bin Mohamed Ikbar
Senior Officer (Admin Planning), Corporate Services
Integrated Checkpoints Command (Land)
Immigration & Checkpoints Authority
DID: (65) 6767 2143



Immigration & Checkpoints Authority W ica.gov.sg FB fb.com/Immigration.Checkpoints.Authority

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: Tuesday, 4 February 2020 11:11 AM
To: Muhammad Hakimullah MOHAMED IKBAR (ICA) <Muhammad_Hakimullah_MOHAMED_IKBAR@ica.gov.sg>;
ASSIGNMENTS@LKKAUTO.COM
Cc: Revathy KARUPAN (ICA) <Revathy_KARUPAN@ica.gov.sg>; Lip Tat GAN (ICA) <GAN_Lip_Tat@ica.gov.sg>; June
ENG (ICA) <June_ENG@ica.gov.sg>; Soo Hue LOW (ICA) <LOW_Soo_Hue@ica.gov.sg>
Subject: RE: Quotations for Pre-Repair Assessment

Dear Hakimullah,

Thank you for the email.

Kindly provide us the workshop details in order for us to call an arrange for the survey.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Hakimullah MOHAMED IKBAR (ICA)

[mailto:Muhammad.Hakimullah.MOHAMED.IKBAR@ica.gov.sg]

Sent: Tuesday, 4 February 2020 9:48 AM

To: Nivitha (LKK Auto)

Cc: assignments@lkkauto.com; Revathy KARUPAN (ICA); Lip Tat GAN (ICA); June ENG (ICA); Soo Hue LOW (ICA)

Subject: RE: Quotations for Pre-Repair Assessment

Message Classification: Restricted

Hi Nivitha,

ICA would be engaging LKK to conduct a physical pre-repair inspection. Pls link us up with the relevant party to discuss on the necessary. Thank you.

Best Regards,


Muhammad Hakimullah Bin Mohamed Ikbar

Senior Officer (Admin Planning), Corporate Services

Integrated Checkpoints Command (Land)

Immigration & Checkpoints Authority

DID: (65) 6767 2143



Immigration & Checkpoints Authority [W ica.gov.sg](http://ica.gov.sg) [FB fb.com/Immigration.Checkpoints.Authority](https://fb.com/Immigration.Checkpoints.Authority)

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>

Sent: Friday, 31 January 2020 8:57 AM

To: Muhammad Hakimullah MOHAMED IKBAR (ICA) <Muhammad.Hakimullah.MOHAMED.IKBAR@ica.gov.sg>; assignments@lkkauto.com

Cc: Lip Tat GAN (ICA) <GAN.Lip.Tat@ica.gov.sg>

Subject: RE: Quotations for Pre-Repair Assessment

Dear Sir/Mdm,

Thank you for the email.

Please be informed that our quotation for the pre and post-repair is \$280.00.

All above charges are subject to GST 7%.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Hakimullah MOHAMED IKBAR (ICA)
[mailto:Muhammad_Hakimullah_MOHAMED_IKBAR@ica.gov.sg]
Sent: Wednesday, 29 January 2020 12:16 PM
To: assignments@lkkauto.com
Cc: Lip Tat GAN (ICA)
Subject: Quotations for Pre-Repair Assessment

Message Classification: Restricted

Hi,


A member of public is seeking compensation for damage sustained to his motorcycle at Woodlands Checkpoint. We've been told that the motorcycle is at a workshop, yet to be repaired. The claimant's lawyers have also provided pictures of the damaged motorcycle. Hence, we are seeking:

- a. A quotation to perform a physical pre-repair assessment and
- b. Information on the procedures involved in doing such pre-repair assessments for e.g., the location of the repair assessment, should the claimant be there, etc.

Expecting your reply at the soonest. Thank you.

Best Regards,


Muhammad Hakimullah Bin Mohamed Ikbar
Senior Officer (Admin Planning), Corporate Services
Integrated Checkpoints Command (Land)
Immigration & Checkpoints Authority
DID: (65) 6767 2143



HOME TEAM
• TRANSFORMATION 2025 •
One Home, One Team
Building Our Future Together

Immigration & Checkpoints Authority W ica.gov.sg FB [fb.com/Immigration.Checkpoints.Authority](https://www.facebook.com/Immigration.Checkpoints.Authority)

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has
been checked
for viruses by
AVG antivirus
software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	766G
Vehicle No.:	FBK2239J
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2020
Vehicle Make:	B.M.W.
Vehicle Model:	F800GS ADVENTURE MANUAL
Primary Colour:	Beige
Manufacturing Year:	2014
Engine No.:	802EA08833549
Chassis No.:	WB10B0506EZ303335
Maximum Power Output:	-
Open Market Value:	\$14,320.00
Original Registration Date:	14 May 2015
First Registration Date:	14 May 2015
Transfer Count:	1
Actual ARF Paid:	\$2,148.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	13 May 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,512.00
COE Rebate Amount:	\$5,067.00
Total Rebate Amount:	\$5,067.00

The information contained herein is correct as at 12 Feb 2020

OK

8-3

[REPORT ERROR > \(/LISTING/LISTING/ERROR/USEDBIKE/14847/\)](#)[+ SHORTLIST](#)

Share 5

[SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/BMW-BMW-F800GS/14847/\)](#)

BMW F800GS

Listing Type	Paid Ad
Brand	BMW (/listing/usedbike/brand/bmw/)
Model	BMW F800GS (/listing/usedbike/model/bmw-f800gs/)
Engine Capacity	798cc
Classification	Class 2 (/listing/usedbike/model/motorcycle-for-sale/class/class-2/)
Registration Date	13/01/2014
COE Expiry Date	12/01/2024 (3 years 11 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Sport Tourers (/listing/usedbike/model/motorcycle-for-sale/sport-tourers/)

Price: ^{SGD}\$15800

DETAILS

Bmw F800GS For Sale. Prices Are Negotiable. Trade In Or Loan Available. Viewing Will Be At Dynasty Motor Pte Ltd @ Bukit Batok, Midview Building, 50 Bukit Batok St 23 #01-24, S'pore 659578.

Marina One Residences Tower 23 - Official Site by MS Pte Ltd

Limited 1/2/3/4-Bedrooms Available. Singapore's Most Prestigious Address. Limited Units. marina-one-residence.com

[OPEN](#)

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)



TRAXX Motor Company Pte Ltd

9 Tagore Lane #04-02 Singapore 787472

Tel: +65 6459 2338

ESTIMATE

Date:	11 Nov 2019	Quote No.:	Q1900116
Customer:	Mohamed Zuraimi, Shukee	Svc Order No.:	S1900286
Address:	712 Woodlands Drive 70 #02-95 Singapore Singapore 730712		
Email:	sabribin@gmail.com	Make:	BMW
Bike No.:	FBK2239J	Model:	F800 GS ADV
VIN No.:	WB10B0506EZ303335	Model Code:	K75
	Phone: 87795549	Mileage (km):	0 km

No.	Labour Code	Description	Qty	Unit Price	Amount
1	46 050	Removing / installing or replacing rear frame			\$280.00
2	31 011	Replacing front fork assembly			\$160.00
3	46 251	Removing / Installing or Replacing both sides motorcycle protection bars			\$56.00
4	46 253	Removing / Installing or Replacing both sides engine protection bars			\$56.00
5	46 008	Removing / installing or replacing both sides hand protector			\$32.00
6	46 011	Removing / installing or replacing headlight cowling			\$64.00
7	46 014	Removing / installing or replacing both sides fairing			\$48.00
8	46 018	Removing / installing or replacing both sides pillion foot rest			\$16.00
9	46 015	Removing / installing or replacing left or right rider foot rest			\$16.00
10	46 202	Removing / Installing or Replacing both sides steel case holders			\$80.00
11	51 001	Replacing both badge logos			\$32.00
12	51 101	Replacing or coding top case lock barrel (aluminium cases)			\$8.00
13	61 302	Removing or replacing side stand switch			\$40.00
14	61 011	Installing or Replacing battery & check charging system			\$40.00
15	63 011	Removing / Installing or Replacing both front indicator assemblies			\$64.00
16	12 001	Removing / installing or replacing crankshaft sensor (excl. additional works)			\$24.00
17	63 091	Removing or replacing headlight unit			\$64.00
18	34 010	Replacing brake fluid in entire system			\$64.00
19	36 559	Removing / Installing or Replacing front tyres (with static balancing)			\$40.00
20	18 002	Remove / installing or replacing exhaust manifold			\$80.00
21	17 004	Removing / installing radiator (without bleeding)			\$48.00
22	17 010	Replacing coolant (incl. bleeding cooling system)			\$68.00
23	61 005	Testing and diagnostics (incl. resetting & learning adaptation values)			\$80.00
24	00 08				
					600 included
					Sub-Total: <u>\$1,460.00</u>

No.	Part Code	Description	Qty	Unit Price	Amount
1	31 42 7 711 181	Fork leg, left / BT.	1	\$1,326.40	\$1,326.40
2	32 71 8 533 880	Handlebar / BT.	1	\$353.10	\$353.10
3	32 71 7 660 112	Handlebar vibration absorber, L= 36MM < LH - Cut RH X NV	2	\$50.90	50.9 101.80
4	07 12 9 908 433	Fillister head screw, M8X45-8.8-ZNNIV < BR LH - BR RH X NV	2	\$7.60	\$15.20
5	32 72 7 705 606	Clutch lever / Cut.	1	\$116.40	\$116.40
6	32 72 8 524 170	Handbrake lever / BT	1	\$112.10	\$112.10
7	31 42 7 684 359	ISA screw, M10X70 X NV.	2	\$11.80	\$23.60
8	31 42 7 715 488	Silent block / } AC.	4	\$4.90	\$19.60
9	33 30 6 760 587	Hex nut with flange, M10-10 ZNS3 / }	2	\$2.70	\$5.40
10	31 42 7 658 261	Washer / }	1	\$3.80	\$3.80
11	31 42 7 658 563	Adjusting screw / M.S.	1	\$21.90	\$21.90
12	46 54 8 543 921	Case holder, left / Cut	1	\$243.30	\$243.30



TRAXX Motor Company Pte Ltd

9 Tagore Lane #04-02 Singapore 787472

Tel: +65 6459 2338

ESTIMATE

Date:	11 Nov 2019	Quote No.:	Q1900116
Customer:	Mohamed Zuraimi, Shukee	Svc Order No.:	S1900286
Address:	712 Woodlands Drive 70 #02-95 Singapore Singapore 730712		
Email:	sabribin@gmail.com	Make:	BMW
Bike No.:	FBK2239J	Model:	F800 GS ADV
VIN No.:	WB10B0506EZ303335	Phone:	87795549
		Model Code:	K75
		Mileage (km):	0 km

Item No.	Part Description	QTY	Unit Price	Total Price
13	Case holder, right <i>Cut</i>	1	\$243.30	\$243.30
14	Set mounting parts for case porter <i>MCC.</i>	1	\$87.90	\$87.90
15	Front wheel cover, top left <i>CRA</i>	1	\$46.20	\$46.20
16	Front wheel cover, top right <i>Cut</i>	1	\$46.20	\$46.20
17	Wheel cover, wheel side <i>Cut</i>	1	\$118.50	\$118.50
18	Flat mushroom-head screw, M5X16-A2-80	8	\$2.90	\$23.20
19	C-clip nut, self-locking, M5 <i>MCC.</i>	4	\$3.50	\$14.00
20	Fillister head screw, M6X16-A2-80	8	\$3.50	\$28.00
21	Windscreen <i>Cut</i>	1	\$353.70	\$353.70
22	Left bracket <i>Mis.</i>	1	\$57.10	\$57.10
23	Covering left	1	\$49.70	\$49.70
24	Oval head screw, M5x25	6	\$3.40	\$20.40
25	Flange sleeve, steel, L=7MM	6	\$5.60	\$33.60
26	Rubber grommet	6	\$4.60	\$27.60
27	Threaded insert M5, L=3,5MM	4	\$11.10	\$44.40
28	Bushing with collar	2	\$5.80	\$11.60
29	Retaining bracket, windshield <i>BT</i>	1	\$320.90	\$320.90
30	Hand protector left <i>Cut</i>	1	\$58.10	\$58.10
31	Hand protector right <i>X NN MT.</i>	1	\$58.10	\$58.10
32	Mounting arm, hand protector	1	\$65.80	\$65.80
33	Bush, hand protector	2	\$31.50	\$63.00
34	BODY SCREW WITH SHOULDER - M5X14,5MM <i>MCC.</i>	2	\$4.80	\$9.60
35	C-clip nut, self-locking, M5	2	\$3.70	\$7.40
36	PLASTIC WASHER - M5	2	\$1.10	\$2.20
37	Front panel carrier <i>BR</i>	1	\$190.70	\$190.70
38	Rubber grommet	3	\$3.60	\$10.80
39	BLIND RIVET NUT, FLAT HEADED - M5	3	\$7.80	\$23.40
40	Isa screw with washer, M6X70-U0-8.8 <i>MCC.</i>	1	\$4.50	\$4.50
41	Hex nut with plate, AM6-8-ZNNIV SI	1	\$1.80	\$1.80
42	Plug-in nut, M5	2	\$3.50	\$7.00
43	Torx-bolt with washer, ISA M6X55	4	\$4.20	\$16.80
44	Intake snorkel cover, left <i>Cut</i>	1	\$438.30	\$438.30
45	Intake snorkel cover, right <i>Cut</i>	1	\$190.00	\$190.00
46	BMW emblem <i>Mis.</i>	2	\$66.20	\$132.40
47	Rubber buffer, 6MM <i>MCC</i>	2	\$7.80	\$15.60
48	Plastic washer <i>MCC</i>	4	\$3.00	\$12.00
49	Radiator trim <i>CRA</i>	1	\$127.90	\$127.90
50	Left engine protection bar <i>Cut</i>	1	\$504.40	\$504.40
51	Right engine protection bar <i>x repairs.</i>	1	\$504.40	\$504.40
52	Fillister head screw, M5X14-A2-80-MK <i>MCC</i>	2	\$3.50	\$7.00
53	Isa screw with washer, M8X25-U0-A2-70	2	\$8.40	\$16.80
54	Footrest, wide, rider, left	1	\$149.30	\$149.30
55	Footrest rubber	1	\$27.40	\$27.40
56	Split pin, 2X16 <i>Cut.</i>	2	\$2.40	\$4.80
57	Footrest, rear left	1	\$86.10	\$86.10
58	Footrest, rear right	1	\$86.10	\$86.10



TRAXX Motor Company Pte Ltd

9 Tagore Lane #04-02 Singapore 787472

Tel: +65 6459 2338

ESTIMATE

Date:	11 Nov 2019	Quote No.:	Q1900116
Customer:	Mohamed Zuraimi, Shukee	Svc Order No.:	S1900286
Address:	712 Woodlands Drive 70 #02-95 Singapore Singapore 730712		
Email:	sabribin@gmail.com	Make:	BMW
Bike No.:	FBK2239J	Model:	F800 GS ADV
VIN No.:	WB10B0506EZ303335	Model Code:	K75
	Phone: 87795549	Mileage (km):	0 km

QTY	Part No.	Description	Unit	Price	Total
59	46 71 7 716 151	Thrust washer, left / <i>MC</i>	1	\$3.80	\$3.80
60	46 71 7 716 152	Thrust washer, right / <i>MC</i>	1	\$3.80	\$3.80
61	46 71 7 664 225	Footrest rubber / <i>CA</i>	2	\$19.20	\$38.40
62	46 61 8 541 992	Front wheel cover, top middle, RACING-RED / <i>CA</i>	1	\$266.30	\$266.30
63	46 63 8 541 995	Fairing side panel, front left, RACING-RED / <i>CA</i>	1	\$273.90	\$273.90
64	46 63 8 542 002	Knee cover, left, GRANITE-GREY / <i>CA</i>	1	\$218.10	\$218.10
65	51 16 8 532 143	Mirror, left / <i>MC</i>	1	\$114.00	\$114.00
66	51 16 8 532 144	Mirror, right / <i>MC</i>	1	\$114.00	\$114.00
67	51 14 8 542 333	Lettering <F800> black/red / <i>MC</i>	1	\$59.00	\$59.00
68	61 21 8 394 179	Battery AGM / <i>flat</i>	1	\$242.60	\$242.60
69	61 32 8 526 970	Switch, side stand / <i>MC</i>	1	\$119.30	\$119.30
70	07 12 9 904 882	Hex nut, M6-8-ZNS3 / <i>MC</i>	1	\$1.30	\$1.30
71	07 12 9 906 498	Securing clip, ZNFE SW / <i>MC</i>	3	\$3.60	\$10.80
72	63 12 8 543 114	Headlight, HELLA / <i>CA</i>	1	\$592.80	\$592.80
73	63 13 8 522 499	LED direction indicator / <i>CA</i>	2	\$73.10	\$146.20
74	61 13 7 668 405	Resistor, 120 OHM / <i>MC</i>	1	\$12.00	\$12.00
75	77 43 8 566 446	Aluminium top case / <i>MC</i>	1	\$691.10	\$691.10
76	51 25 7 698 202	Repair kit f lock cylinder / <i>MC</i>	2	\$58.60	\$117.20
77	77 44 8 546 808	SET: SET BACKREST CUSHION TOP CASE / <i>MC</i>	1	\$143.10	\$143.10
78	13 54 8 406 249	Throttle valve switch / <i>NW</i>	1	\$253.90	\$253.90
79	13 54 7 701 545	ISA screw with washer, M4X25 / <i>MC</i>	2	\$5.10	\$10.20
80	61 31 2 346 550	Alternator regulator / <i>NW</i>	1	\$241.00	\$241.00
81	07 12 9 905 537	ISA SCREW WITH WASHER - M6X30 / <i>MC</i>	1	\$4.90	\$4.90
82	07 12 9 903 784	Mounting screw, M5X25-Z1-8.8 / <i>MC</i>	2	\$3.80	\$7.60
83	06 32 7 651 211	Fillister head screw, M5X12-A2-80 / <i>MC</i>	1	\$2.90	\$2.90
84	07 12 9 907 403	Fillister head screw, M6X16-8.8-ZNNIV / <i>MC</i>	1	\$3.40	\$3.40
85	07 12 9 904 704	ISA screw M8X40-8.8-ZNS3 / <i>MC</i>	1	\$5.40	\$5.40
86	16 11 7 677 883	GASKET (Fuel Pump) / <i>MC</i>	1	\$16.90	\$16.90
87	16 14 8 556 077	FUEL PUMP UNIT WITH LEVER SENSOR (K72) / <i>NW</i>	1	\$638.70	\$638.70
88	16 11 7 677 883	GASKET (Fuel Pump) / <i>MC</i>	1	\$16.90	\$16.90
89	46 51 8 523 352	Rear frame / <i>BT</i>	1	\$1,629.70	\$1,629.70
90	46 51 8 531 478	ISA screw, M10X40 SI-MK / <i>MC</i>	2	\$4.90	\$9.80
91	07 11 9 904 670	Flange Nut M10 / <i>MC</i>	2	\$1.50	\$3.00
92	46 51 8 531 479	ISA screw, M10X18 SI-MK / <i>MC</i>	2	\$4.40	\$8.80
93	77 51 8 533 756	Set off-road protective window / <i>MC</i>	1	\$118.70	\$118.70
94	16 14 8 523 262	SET: FUEL PUMP, ELECTRONIC (to 08/10) / <i>NW</i>	1	\$247.90	\$247.90
95	83 34 0001	Brake Fluid DOT4 (1L) / <i>NN</i>	1	\$17.00	\$17.00
96	83 31 0002	ENI Fork Oil 7.5W (1L) / <i>MC</i>	2	\$23.00	\$46.00
97	83 11 0003	ENI Moto 4T Engine Oil 15W/50 (1L) / <i>NN</i>	3	\$23.00	\$69.00
98	11 42 7 719 357	OIL FILTER (K70/K72/K75) / <i>MC</i>	1	\$25.00	\$25.00
99	36 31 8 564 176	Spoke wheel front, 2.15X21 / <i>BT</i>	1	\$1,387.90	\$1,387.90
100	36 32 2 464 405	Tyre hose 21 / <i>MC</i>	1	\$29.80	\$29.80
101	46 54 8 543 918	Cross-bracket, rear / <i>BT</i>	1	\$65.90	\$65.90
102	71 60 7 696 292	Set, aluminium topcase, carrier / <i>BT</i>	1	\$208.70	\$208.70
103	71 60 7 714 518	Set, mounting parts, topcase carrier / <i>MC</i>	1	\$58.30	\$58.30
104	31 42 8 530 350	Lower fork cross brace / <i>BT</i>	1	\$536.70	\$536.70



TRAXX Motor Company Pte Ltd

9 Tagore Lane #04-02 Singapore 787472

Tel: +65 6459 2338

ESTIMATE

Date:	11 Nov 2019	Quote No.:	Q1900116
Customer:	Mohamed Zuraimi, Shukee	Svc Order No.:	S1900286
Address:	712 Woodlands Drive 70 #02-95 Singapore Singapore 730712		
Email:	sabribin@gmail.com	Make:	BMW
Bike No.:	FBK2239J	Model:	F800 GS ADV
VIN No.:	WB10B0506EZ303335	Model Code:	K75
	Phone: 87795549	Mileage (km):	0 km

Item No.	Part Description	Qty	Unit Price	Total Price
105	31 42 1 234 509 Ring	1	\$11.90	\$11.90
106	31 42 7 663 941 Tapered roller bearing 28X52X16	2	\$68.50	\$137.00
107	31 42 7 692 248 Cap	1	\$11.90	\$11.90
108	31 42 7 711 182 Fork leg, right	1	\$1,326.40	\$1,326.40
109	07 12 9 904 477 ISA screw M8X25-10.9-ZNS3	4	\$6.20	\$24.80
110	36 31 7 713 558 Wheel shaft, front	1	\$154.90	\$154.90
111	36 31 7 705 315 Hex Bolt M14X1.5	1	\$14.30	\$14.30
112	18 12 7 679 350 Rear silencer	1	\$1,271.50	\$1,271.50
113	77 25 8 523 119 Set, mounting parts, tilt stand	1	\$62.60	\$62.60
114	46 63 8 541 994 Fairing side panel, front right RACING-RED	1	\$273.90	\$273.90
115	12 72 8 555 265 CAMSHAFT POSITION SENSOR	1	\$164.60	\$164.60
116	23 00 7 690 404 Hexagon screw with torx socket M6X16-8.8	1	\$2.90	\$2.90
117	65 81 6 936 953 Outside temperature sensor	1	\$86.70	\$86.70
118	65 81 1 370 116 Bracket outside temperature sensor	1	\$2.30	\$2.30
119	62 11 8 535 810 Instrument cluster KM/H	1	\$1,094.80	\$1,094.80
120	07 12 9 906 498 Securing clip, ZNFE SW	3	\$3.60	\$10.80
121	46 63 1 233 200 Rubber grommet	3	\$3.60	\$10.80
122	62 11 7 693 137 Torx bolt 30X16	5	\$2.10	\$10.50
123	23 41 8 534 947 Foot shift lever	1	\$79.70	\$79.70
124	23 41 7 655 284 Rubber grommet	1	\$9.60	\$9.60
125	07 12 9 903 807 ISA SCREW - M6X25-8.8-ZNS3	1	\$3.20	\$3.20
126	61 31 8 550 021 Combination switch left	1	\$423.30	\$423.30
127	61 31 7 708 227 Handle left, grip	1	\$134.90	\$134.90
128	07 11 9 906 567 CSK.FILLISTER HEAD SREW - M3,5X32 (K50)	1	\$3.60	\$3.60
129	61 31 7 708 228 Throttle grip assembly	1	\$205.00	\$205.00
130	12 12 7 690 603 SPARK PLUG - NGK DCPR8E	2	\$15.20	\$30.40
131	13 71 8 529 998 AIR FILTER ELEMENT (K72/K75)	1	\$35.00	\$35.00
132	13 71 7 702 755 Idle control device	1	\$201.00	\$201.00
133	13 71 7 716 027 Set, hose, idle-speed actuator	1	\$51.10	\$51.10
134	11 71 7 679 329 Hose pipe, secondary air system	1	\$72.80	\$72.80
135	13 71 7 705 608 Cap	1	\$6.10	\$6.10
136	13 54 7 689 063 O Ring (18.72X2.62)	2	\$3.50	\$7.00
137	11 43 7 689 572 O-ring 21.83 x 2.53	1	\$2.50	\$2.50
138	11 41 7 652 949 GASKET RING - 24X30X1,5 ALUMINIUM	1	\$2.50	\$2.50
139	11 13 7 708 604 Screw plug, magnetic M24X2	1	\$37.30	\$37.30
140	17 11 8 530 393 Radiator	1	\$613.90	\$613.90
141	83 51 2 355 290 BMW Radiator/antifreeze/anti-corrosion agent (1.5L)	1	\$24.50	\$24.50
142	13 53 7 614 317 Sensor, low pressure	1	\$153.60	\$153.60
143	13 61 7 672 335 Injection valve	2	\$206.10	\$412.20
144	13 53 7 688 284 O-ring	1	\$14.50	\$14.50
145	ZZZ 001 Fuel - RON95	1	\$20.00	\$20.00

Sub-Total: \$22,738.60

Owner acceptance

Total Labour: \$1,460.00

Total Parts: \$22,738.60



TRAXX Motor Company Pte Ltd

9 Tagore Lane #04-02 Singapore 787472

Tel: +65 6459 2338

ESTIMATE

Date:	11 Nov 2019	Quote No.:	Q1900116
Customer:	Mohamed Zuraimi, Shukee	Svc Order No.:	S1900286
Address:	712 Woodlands Drive 70 #02-95 Singapore Singapore 730712		
Email:	sabribin@gmail.com	Make:	BMW
Bike No.:	FBK2239J	Model:	F800 GS ADV
VIN No.:	WB10B0506EZ303335	Model Code:	K75
	Phone: 87795549	Mileage (km):	0 km

Total Amount: \$24,198.60

Date: _____ Time: _____

[Signature]
12/3/2020

Guo Qiang - 82880282
(CLKK)

Guo Qiang @ lkk auto. com

06/2/2020

ump sum repair.

3Days.

After repair photos.

check items : 1430.5

Total items : 18598.7

-10% : 16738.83

labour : 600

Total : 17338.83

-20% : 13850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



TRAXX Motor Company Pte Ltd

9 Tagore Lane #04-02 Singapore 787472

Tel: +65 6459 2338

ESTIMATE

Date:	11 Nov 2019	Quote No.:	Q1900116
Customer:	Mohamed Zuraimi, Shukee	Svc Order No.:	S1900286
Address:	712 Woodlands Drive 70 #02-95 Singapore Singapore 730712		
Email:	sabribin@gmail.com	Make:	BMW
Bike No.:	FBK2239J	Model:	F800 GS ADV
VIN No.:	WB10B0506EZ303335	Model Code:	K75
	Phone: 87795549	Mileage (km):	0 km

Terms and Conditions

1. An asterisk (*) beside any Part listed above denotes stock unavailability.

2. Unless otherwise indicated in writing by the Company, this Quotation is open for acceptance by the customer within thirty (30) days from the date above written.

3. Unless otherwise indicated above, all prices/ sums/ amounts quoted are in SINGAPORE DOLLARS (S\$).

4. The customer undertakes to comply and be bound by all other terms and conditions provided in the Service Order.

5. The customer understands and acknowledges that all quotations and indication of fees payable are for estimation purposes only and are not conclusive. The Company reserves the right to amend the fee estimate to include additional costs incurred by it for labour and/or Parts used in connection with the repair works and services rendered (as set out in the Service Order). In the event that the company is of the opinion that the final fees to be incurred may exceed the estimated fees given in the Quotation by more than twenty percent (20%), the Company shall request for the additional written authorisation of the customer before commencing work.

6. The customer agrees that upon placing his signature beside/ under the 'Owner Acceptance' portion above, this shall indicate his acceptance of the terms and conditions set out in this Quotation, and shall grant the Company permission to proceed with the repair works and services as provided in the Service Order.

7. Simultaneously with the execution of this Quotation, the customer shall pay the Company a non-refundable deposit of either fifty percent (50%) of the Total Amount quoted, or the full sum of the Parts set out herein, whichever being the higher (the "Deposit"). Unless otherwise agreed, the Company shall only commence work upon the full payment of the Deposit by the customer.

