



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD		NAME : Ms Sim Ling Li Felicia LTPI FCI TP		WIP : 61599	
36 ROBINSON ROAD		ADDRESS : Blk 168A Simei Lane		EXCESS :	
#16-01 CITY HOUSE		#12-42		DATE: 30-Jan-20	
SINGAPORE 068877		Singapore 521168			
ATTN. : MOTOR CLAIMS		TEL : 96927827			
FAX :					
VEH NO :	SMQ9155J	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BP2SAAK1101759	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	10-Dec-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	REAR BUMPER MBCKA-50-221ABB <i>de✓</i>	\$ 997.40	\$ 997.40
2	1	BRACKET CENTER MKD53-50-251	X	\$ 5.40
3	1	REAR REINFORCEMENT MBCJH-50-260	X	\$ 541.70
4	1	PLATE SET, REAR BUMPER MBCKA-50-2C0A	X	\$ 213.80
5	1	STAY, REAR BUMPER MBCKA-50-290	X	\$ 91.90
6	1	COVER UNDER, REAR BUMPER MBCKA-50-C51B	X	\$ 63.20
7	1	TOWING COVER LHS MBCKA-50-EL1 BB	X	\$ 12.80
8	1	TOWING COVER RHS MBCKA-50-EK1 BB <i>mis✓</i>	\$ 12.80	\$ 12.80
9	2	BRACKET CENTER, SENSOR MB0J8-67-UC6	\$ 46.80	\$ 46.80
10	1	RETAINER CENTER LHS, SENSOR MB0L9-67-UC5	\$ 25.10	\$ 25.10
11	1	RETAINER CENTER RHS, SENSOR MB0L8-67-UC5 <i>nel✓</i>	\$ 25.10	\$ 25.10
12	1	RETAINER SIDE LHS, SENSOR MB0M2-67-UC5	\$ 25.10	\$ 25.10
13	1	RETAINER SIDE RHS, SENSOR MB0M1-67-UC5	\$ 25.10	\$ 25.10
14	2	SENSOR CENTER, SENSOR MB0J8-67-UC1 64	X <i>nel</i>	\$ 380.00
15	3	TAPE PROTECTOR, SENSOR MBCKA-50-EM1	\$ 14.10	\$ 14.10
16	8	FASTENER, REAR BUMPER MB45A-56-146A	\$ 24.00	\$ 24.00
17	4	GROMMET, REAR BUMPER MBCKA-50-OZ1 <i>nel✓</i>	\$ 9.60	\$ 9.60
18	4	GROMMET, REAR BUMPER MBHN1-50-OZ1A	\$ 10.80	\$ 10.80
19	8	GASKET, TAILLAMP MB45A-51-3G8	\$ 19.20	\$ 19.20
TOTAL PARTS			\$ 1,235.10	\$ 2,543.90
TOTAL PARTS COST			\$ 1,235.10	\$ 2,543.90

Labour Description

1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,320.00
---	--------------	--	-----------	-------------

2	MZ-SP-SREAR1	TO RESPRAY REAR BUMPER.	\$ 630.00	\$ 1,260.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 330.00
4	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	\$ 70.00	\$ 70.00
5	MZ-BR-LTAREG	TO BREAK AND RESEAL VEHICLE WEEKEND NUMBER PLATE LTA REGISTRATION FEE.	\$ 150.00	\$ 150.00
6	MZ-BR-INSCEN	TO SEND THE CAR TO INSPECTION CENTRE FOR THE INSTALLATION OF THE WEEKEND NUMBER PLATE.	\$ 120.00	\$ 120.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	XW.	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
10		TO SUPPLY BRILA PREMIUM COATING.	\$ 100.00	\$ 100.00
11	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 2,410.00	\$ 4,300.00
TOTAL PARTS			\$ 1,235.10	\$ 2,543.90
TOTAL			\$ 3,645.10	\$ 6,843.90
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,645.10	
GST 7%			\$ 255.16	\$ -
GRAND TOTAL			\$ 3,900.26	\$ -

REMARKS:

4 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

\$3645.10
* 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____