

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

SUPPLEMENTARY ITEMS

Total Labour :	8,322.00
Total Parts :	3,458.15
Total Labour & Parts :	11,780.15
GST @7%:	824.61
Grand Total :	<u>12,604.76</u>

	NAME	DATE	QTY
FAX TO	Steve	8/4/10	8
FAX NO	LKR		
FAX TO			
FAX NO			
FAX TO			
FAX NO			
COMMENTS			
DATE			

LOSS OF USE = \$60 X 10 DAYS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 54355**
Date Estimated : **05/02/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Lim Mui Ling (LIN MEILING)
Block 101 Bishan Street 12 #14-292
singapore

Singapore 570101

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF2799E	WBA8E320X0A5532	31/10/2018	318i	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace left side skirting, both left doors and attachments etc including to make good front left fender, left running board and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	3,825.00	0	3,825.00
To respray both left doors and door handles, front left fender, left side skirting and left running board etc.	3,867.00	0	3,867.00
To conduct checks on all doors and bootlid central locking system for proper function.	150.00	0	150.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00
To carry out body cavity preservation.	180.00	0	180.00
Sundries	150.00	0	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# EXPANDING NUT	2.10	6	0	12.60
REAR LH DOOR	1,273.85	1	0	1,273.85
FRT LH DOOR	1,273.85	1	0	1,273.85
FRT DOOR WEATHERSTRIP	141.40	1	0	141.40
REAR DOOR WEATHERSTRIP	141.40	1	0	141.40
REAR LH SIDE WINDOW FIXED	172.55	1	0	172.55
SUPPORTING LEDGE LH	36.40	1	0	36.40
SUPPORTING LEDGE LH	37.95	1	0	37.95
SUPPORTING LEDGE LH	37.75	1	0	37.75
LH SILL TRIM PRIMED	324.10	1	0	324.10
# EXPANDING NUT 7X7 MM	1.05	6	0	6.30
#				
#				
#				
#				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 54355**
Date Estimated : **05/02/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Lim Mui Ling (LIN MEILING)
Block 101 Bishan Street 12 #14-292
singapore

Singapore 570101

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF2799E	WBA8E320X0A5532	31/10/2018	318i	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT ✓ NEC	2.10	6	0	12.60
# EXPANDING NUT 7X7 MM ✓ NEC	1.05	6	0	6.30

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	18.90
Total Labour & Parts :	18.90