



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 3097E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	TORN	468.00	468.00
2	FRONT BUMPER CLIP @\$6.50 (CONSISTENT)	NECESSARY	52.00	30.00
1	FRONT R/H BUMPER SENSOR (CONSISTENT)	NOT NECESSARY	350.00	-
1	FRONT R/H BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	31.00	31.00
1	FRONT R/H BUMPER FOG LAMP (CONSISTENT)	CRACKED	225.90	225.90
1	FRONT R/H HEADLAMP (CONSISTENT)	CRACKED	693.70	693.70
1	FRONT R/H HEADLAMP LOWER BRACKET (CONSISTENT)	NOT NECESSARY	47.00	-
1	FRONT R/H FENDER (CONSISTENT)	NOT NECESSARY	480.60	-
1	FRONT R/H FENDER COWLING (CONSISTENT)	NOT NECESSARY	68.00	-
3	FRONT R/H FENDER COWLING CLIP @\$6.50 (CONSISTENT)	NOT NECESSARY	19.50	-
1	FRONT R/H TYRE (CONSISTENT)	NOT NECESSARY	350.00	-
1	FRONT R/H RIM (CONSISTENT)	NOT NECESSARY	891.00	-
1	FRONT R/H LOWER ARM (CONSISTENT)	NOT NECESSARY	296.00	-
1	FRON R/H KNUCKLE ARM (CONSISTENT)	NOT NECESSARY	319.00	-
1	FRONT R/H KNUCKLE ARM BEARING (CONSISTENT)	NOT NECESSARY	209.00	-
1	FRONT R/H SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	312.00	-
1	FRONT R/H DRIVE SHAFT (CONSISTENT)	NOT NECESSARY	936.70	-
1	FRONT STEERING RACK (CONSISTENT)	NOT NECESSARY	1,099.80	-
	LESS 20% DISCOUNT		-	-289.72
			6,849.20	1,158.88
<u>LABOUR</u>				
	TO REMOVE & REFIT R/H UNDERCARRIAGE ,DRIVE SHAFT & STEERING RACK.	NOT NECESSARY	380.00	-
	TO CHECK WIRING .		100.00	30.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.		1,000.00	200.00
	SPRAY PAINTING.		1,000.00	250.00
			2,780.00	480.00

Report Ref No. CC4/ASM20002134/Apa3q2



GRAND TOTAL		9,629.20	1,638.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CC4/ASM20002134/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.