



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002134/Apa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 03-06-2020



ATTN:VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SML 9366T	Veh. Inspected	SKC 3097E
Policy No.	VPA/P2298379	Coverage (\$)	0.00
Claim No.	S0M02FIW	Excess (\$)	0.00
Assign From		Assign Date	06/02/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHDH41CMCU173755	Colour	WHITE
Odometer	135689	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/01/2020	Inspection Date	17/02/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------