

22/03/2002

ASS. REC. BY:

REF:

CS/GA120007137/KF30

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Sherry Wong

of

GA1

Date/Time:

6.2.2020 4.53p.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GBD 2801Y

Insured:

YP 9452P

at Workshop m/s

Chung HOP

Tel:

67556142

of

Yishun

Policy No:

Claim No:

CLMOMVC000003707

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

7/2/2020 9.49am 9.52m

Person Contacted:

Wei Ling

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBD 2801Y - CCB/MG15013705/KW397 DOA: 8/8/15
	YP 9452P - x
24/2@	2:46pm - Revised via preli advice.
27/2	11 Ly 82100 confirm (Red: 1082: 34%)

ASS. REC. BY:

REF:

201/6012

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

GBO 28014

Yr Regn:

08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Itaque

c.c

2982

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

76675

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JT1F14702P600146706

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

1P5R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/8/19

D.O.I.

17/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 27 FEB 2020

Date/Time, File Pass to?



: Prell. Report

1) 27/2 Typist



: Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trlp:

Survey Fee:

290

Transportation:

S + RS. \$

F. & T. S.

Others

TOTAL

290

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TP

2100/-

Summer Lee (LKK Auto)

From: Motor Claims <motorclaims@sg.gaig.com>
Sent: Thursday, 6 February, 2020 4:53 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June); junephua@singnet.com.sg; admin-d@lkkauto.com; sur@lkkauto.com
Cc: Ng, Sharon
Subject: FW: Our ref: CLMOMVC000003707 - Repair Survey (Single Joint Expert) - GBD2801Y, doa 16/8/19 (Yr insured YP9452P)

Without Prejudice

Hi June,

Noted on the request. We will survey on a without prejudice basis.

Aside to LKK,

Please accept assignment for TP survey. Thank you.

Thank you.



Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: 06 February 2020 4:30 AM
To: Motor Claims <motorclaims@sg.gaig.com>
Cc: June Phua <junephua@singnet.com.sg>

Subject: [External] Re: Our ref: CLMOMVC000003707 - Repair Survey (Single Joint Expert) - GBD2801Y, doa 16/8/19 (Yr insured YP9452P)

Hi Sharon,

Our selection as below :-

5. LKK Auto Consultants

Pls assist to arrange for survey .

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Motor Claims

Sent: Thursday, February 06, 2020 16:05

To: Cheng Hoe Motor Pte Ltd (Yishun-June)

Cc: June Phua

Subject: RE: Our ref: CLMOMVC000003707 - Repair Survey (Single Joint Expert) - GBD2801Y, doa 16/8/19 (Yr insured YP9452P)

WITHOUT PREJUDICE

Dear June

Liability is clear. We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Adjusters & Surveyors Pte. Ltd.
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Kindly let us know which surveyor is selected and furnish the estimates for the necessary survey to be carried out.

Regards
Sharon Ng
Great American

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>

Sent: 06 February 2020 4:18 AM

To: Ngian, Kelvyna <kelvyna.ngian@sg.gaig.com>; Ng, Sharon <sharon.ng@sg.gaig.com>

- Cc: June Phua <junephua@singnet.com.sg>
- Subject: [External] Repair Survey (Single Joint Expert) - GBD2801Y, doa 16/8/19 (Yr insured YP9452P)

Dear Sir,

OUR CLIENT – GBD2801Y

DOA : 16/8/2019 @10.05am

YR INSURED : YP9452P

1) Kindly provide us of your surveyor listing for the selection on the survey.

2) Pls advise has your insured's driver file the report? If yes pls advise on liability and are you agree on **DIRECT SETTLEMENT?**

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 24 February 2020 2:46 PM
To: Motor Claims; Admin-D (LKKAuto); SUR
Cc: Ng, Sharon
Subject: RE: Our ref: CLMOMVC000003707 - Repair Survey (Single Joint Expert) - GBD2801Y, doa 16/8/19 (Yr insured YP9452P)
Attachments: PRELI ADVISED OF GBD 2801Y.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBD 2801Y**
Number of days (estimated) : 6 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claims <motorclaims@sg.gaig.com>
Sent: Thursday, 6 February 2020 4:53 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>; junephua@singnet.com.sg; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Ng, Sharon <sharon.ng@sg.gaig.com>
Subject: FW: Our ref: CLMOMVC000003707 - Repair Survey (Single Joint Expert) - GBD2801Y, doa 16/8/19 (Yr insured YP9452P)

Without Prejudice

Hi June,

Noted on the request. We will survey on a without prejudice basis.

Aside to LKK,

Please accept assignment for TP survey. Thank you.

Thank you.



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	116E
Vehicle Details	
Vehicle No.:	GBD2801Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2429382
Chassis No.:	JTFHT02P600146706
Maximum Power Output:	-
Open Market Value:	\$27,502.00
Original Registration Date:	25 Aug 2014
First Registration Date:	25 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$1,376.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,807.00
COE Rebate Amount:	\$13,630.00
Total Rebate Amount:	\$13,630.00

The information contained herein is correct as at 17 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/08/2019 11:51
Date Of Accident	16/08/2019 10:05
Exact Location Of Accident	COMPOUND OF SEMBAWANG SHIPYARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD2801Y
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	OH AIK GUAN FOOD INDUSTRIAL PTE LTD
Co Reg No	199901116E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64824786

Vehicle Particulars

Manufacturer	TOYOTA
Model	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103547418
Cover Note Number	14/09/2018- 13/09/2019

Driver

Name of Driver	OH BENG YONG
NRIC No	S1688356E
Date Of Birth	09/11/1965
Occupation	OUTDOOR
Date Of Driving Pass	30/08/1983
Driving Experience	35 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97814786
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 876 WOODLANDS AVE 9 #02-250
Postcode	730876
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAITED IN MY VEHICLE AS MY VEHICLE WAS BLOCKED BY LORRY"X" AND M/TRUCK(B). SHORTLY AFTER, I FELT AN IMPACT AND REALIZED THE M/TRUCK(B) HAVE COLLIDED ONTO MY VEHICLE WHILE MOVING OFF.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP9452P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TEO JEE PONG
NRIC/Passport Number	S2564523E
Contact Number	97855174
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

MT/1058109-001
SKETCH PLAN

VEHICLE NO.: G8D 28017
INSURER : NTMC
DATE & TIME: 16.8.19
10:05am

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

17/8/19

Reporting Centre Personnel's Signature
Name: eh
NRIC/FIN No.: 45

SKETCH PLAN

Compound
Sembawang
Shipyards

A = GBD 28019
B = YP 9452P
Teo Jee Hong
S25 64523E
hp: 97855174

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I waited in my vehicle as my vehicle was blocked by lorry "X" and m/truck (B) -

Shortly after, I felt an impact and realized the m/truck (B) have rolled onto my vehicle while moving off.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
17/8/19

GIARMC SketchPlanForm_V3 () Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBD2801Y
TP/GA

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037 FAX: 62353354

ATTN: Motor Claim Department

WS Ref: TP/GA/YS

Claim Type: Third Party

Accident Date: 16/08/2019

TP Veh Reg No: YP9452P

Claim No: ES2090145

Estimate No: ES2090145/YISHUN

Date: 17 Feb 2020

Policy No: 5103547418

Veh Reg No: GBD2801Y

Make/Model: TOYOTA HIACE VAN
TURBO 5 DR MANUAL

Chassis No: JTFHT02P600146706

Engine No: 1KD2429382

Reg. Date: 25/08/2014

Not Noted

1/2 day

Resurvey After claim

6 days

Estimate Repair Cost to Vehicle No : GBD2801Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 RH TAILLAMP	95.00	1 PC	95.00	✓
2 REAR RH FENDER	590.00	1 PC	590.00	✓
			685.00	
	Add 20%		137.00	822.00
Labour				
3 REMOVE & REFIX RH TAILGATE,RH SLIDING DOOR,SLIDING DOOR TRUCK,CUT,WELD & RENEW REAR RH SIDE PANEL,KNOCK & REPAIR RH SLIDING DOOR & REALIGN THE SAME	1,200.00	1 LA	1,200.00	900
4 REMOVE & REFIX TOP ROOF LINING,GARNISH,ETC	80.00	1 LA	80.00	60
5 PUTTY & RESPRAY ON REAR RH SIDE PANEL	600.00	1 LA	600.00	500
6 TO REWRITE ADVERTISEMENT	450.00	1 LA	450.00	750
7 RUSTPROOFING	30.00	1 LA	30.00	✓
				2,360.00

Total S\$ 3,182.00

Add GST @ 7% 222.74

Total Amount payable S\$ 3,404.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged car(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Kt

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBD2801Y
TP/GA

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037

FAX: 62353354

ATTN: Motor Claim Department

WS Ref: TP/GA/YS

Claim Type: Third Party

Accident Date: 16/08/2019

TP Veh Reg No: YP9452P

Claim No: ES2090145

Estimate No: ES2090145/YISHUN

Date: 17 Feb 2020

Policy No: 5103547418

Veh Reg No: GBD2801Y

Make/Model: TOYOTA HIACE VAN
TURBO 5 DR MANUAL

Chassis No: JTFHT02P600146706

Engine No: 1KD2429382

Reg. Date: 25/08/2014

Estimate Repair Cost to Vehicle No : GBD2801Y

Description	U/Price	Quantity	Cost	Amount
Cost Plus			S\$	S\$
1 RH TAILLAMP	95.00	1 PC	95.00	—
2 REAR RH FENDER	590.00	1 PC	590.00	—
			685.00	
	Add 20%		137.00	822.00
Labour				
3 REMOVE & REFIX RH TAILGATE,RH SLIDING DOOR,SLIDING DOOR TRUCK,CUT,WELD & RENEW REAR RH SIDE PANEL,KNOCK & REPAIR RH SLIDING DOOR & REALIGN THE SAME	1,200.00	1 LA	1,200.00	900
4 REMOVE & REFIX TOP ROOF LINING,GARNISH,ETC	80.00	1 LA	80.00	60
5 PUTTY & RESPRAY ON REAR RH SIDE PANEL	600.00	1 LA	600.00	500
6 TO REWRITE ADVERTISEMENT	450.00	1 LA	450.00	7350
7 RUSTPROOFING	30.00	1 LA	30.00	✓
				2,360.00

Total S\$ 3,182.00

Add GST @ 7% 222.74

Total Amount payable S\$ 3,404.74

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

#2662
YS #2100 ✓ dc




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI20002137/Ktf3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 28-02-2020	
			Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 9452P	Veh. Inspected	GBD 2801Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003707	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	06/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTFHT02P600146706	Colour	WHITE	
Odometer	76675	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15X8	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15X8	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2019	Inspection Date	17/02/2020	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2801Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH TAILLAMP (WCP)	CUT	95.00	95.00
1	REAR RH FENDER (WCP)	BENT	590.00	590.00
	COST PLUS 20%		137.00	137.00
			822.00	822.00
	<u>LABOUR</u>			
	REMOVE & REFIX RH TAILGATE, RH SLIDING DOOR, SLIDING DOOR TRUCK, CUT, WELD & RENEW REAR RH SIDE PANEL, KNOCK & REPAIR RH SLIDING DOOR & REALIGN THE SAME.		1,200.00	900.00
	REMOVE & REFIX TOP ROOF LINING, GARNISH, ETC.		80.00	60.00
	PUTTY & RESPRAY ON REAR RH SIDE PANEL.		600.00	500.00
	TO REWRITE ADVERTISEMENT.		450.00	350.00
	RUSTPROOFING.		30.00	30.00
			2,360.00	1,840.00
GRAND TOTAL			3,182.00	2,662.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/GAI20002137/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.