From (Person	i): Kevel	of	M516	Date/Time	0/14
			Bill to:		
To inspect V	STEPRES/O	DRES/EVA/INV/A	AV I-CS	Inmend:	4M 3639
at Workshop	m/s	Modern A	utomotive	Tel: /	my wyn
of	B1K 30231	A UNI ROLL #	01-618 401-58	101	190 21
		1010 0	Claim No:		
Sum Insured		100	Excess:		
ALCOHOLD ALTOHOLD WHEE	-				
Make of Veh	:			D.O.A.	05/2/202
Make of Veh (Client's Recor	d)	10/2			
Make of Veh (Client's Recor CA / REV	d) / REP. / REV	24 HRS 10 1	20 Survey	H.O.D. F	Indossement
Make of Veh (Client's Recor	d) / REP. / REV	24 HRS 10 /		H.O.D. F	Indossement
Make of Veh (Client's Recor	REP. / REV	Person Conta	no survey	H.O.D. F	Indossement
Make of Veh (Client's Recor CA / REV Date/Time;	REP. / REV	ection falmal (	no survey	H.O.D. F	Indossement
Make of Veh (Client's Recor CA / REV Date/Time;	Action/Instru	nction [3/11/16]	no survey	H.O.D. F	Indossement
Make of Veh (Client's Recor CA / REV Date/Time;	Action/Instru	nction [3/11/16]	no survey	H.O.D. F	Indossement
Make of Veh (Client's Recor CA / REV Date/Time;	Action/Instru	action Fallmall (, 8D-X	no survey	H.O.D. E	Endorsement:

# ...CLAIM SUBFOLDER...(New Assignment)

	Votified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sut	mitted	Ins Authled	Status		
	06 Feb 2020 16:25		07 Feb 2020 09:57 Assign					New	Assignme el Case	nt
М	ain	Re	ference		Claim Details		Document	ts	7	Show All
CLAIM SUE	FOLDER DE	TAILS				Create	ed by insurer1			70.010
Insured:	CHAI YOU	N FAH, ID: S17	26606C			Leicate	ed by msurer]			
Main Claimant:	УАР СНОС	ON PING EDMUN	D, ID: S76358	355I						
Vehicle Reg. No.:	SKE6018	BD			Date of Loss:		020 08:00 - :59 onths and <b>2</b> Days Fr	rom LTA	Pen Date	(Man Ve)1
Claim Type:	TP				Policy/Cover Note No.:	8046769	91QMY (Comprehen e: 28/03/2019 - 27	sive)		(14811 11)]
Vehicle Reg. No. (Insured):	SLM36390				Policy No. (Claimant):		2, 20,00,2017	7037202		
Repairer:	Modern Au	utomotive Pte I t	d (HO) BIV 3023	3A Ilbi Bood	Excess:	1 50 400				
Handling Insurer:	MSIG Insu	rance (Singapor	re) Pte. Ltd. (H	Q) - Tel: +6	55 6827 7888	[Handled	3717 Ubi - Tel: 6748 by <b>Fievel Foo We</b>	3 4422 / nvao - 6	6747 4422	2
Adjuster:		Consultants Pte							0.01010	,
Driver/Custo dian (Insured):		KIANG ( / Male)				ice duc	00/02/2020]			
Adj Asg, Remarks:	on WP. Liab	: clear. Agree on	SJE. Assign: LKK	Auto Consu	ultants Pte Ltd. (	Contact: G	irace Chin @ 6748 4	1422.		
ASSOCIATE	D MAIL REC	EIVED					v	iew All	C	
There are no	mail for this o	case.					V	IEW All	Compose	Case Mai
ALL ASSOC	IATED TASK	(S <sup>E</sup>				View All	Search Tasks	Create N	ew Task	Complete
Due Date	Priority	Type Task G	iroup Subje	ect Hand	fler Assign		Completed On		ated On	Done

10/2/2020 (m)
Advan
07/2000 (m)
07/2000 (m)
we chin

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Fievel Foo Wenyao

05 Mar 2020 Date:

# **Preliminary Advice**

Insured Vehicle No : SLM3639C

TP Vehicle No

: SKE6018D

Accident Date

: 05/02/2020

Make

: HONDA STREAM

Assignment Date

: 07/02/2020

Date of Inspection : 10/02/2020

Est. Duration of Repair

Inspection At

: MODERN AUTOMOTIVE PTE LTD (HQ) BLK 3023A UBI ROAD 1, #01-61 & #01-58

SINGAPORE 408717

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7858.48
Revised Amount	:S\$	3,800.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,800.00

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

The vehicle is economical/not economical for repair.

( X )

The above survey was conducted on a 'without prejudice' basis.

# View Sent Message

This mail is associated with:

\*SKE6018D (619210) [SLM3639C]

YAP CHOON PING EDMUND Feb 5 2020 8:00AM [CHAI YOON FAH] Modern Automotive Pte Ltd

Resend	View Recipients	Print Message	Delete Message	Forward	į.
					-

 From
 LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 11/02/2020 12:19 PM.

 To
 MSIG\_FFWY1

 Subject
 TP SURVEY SKE 6018D

Dear Fievel,

Please be informed that we have inspected the vehicle SKE 6018D on 10/2/2020.

We are pending estimate from repairer.

Best Regards, Veron Chen

#### **DOCUMENTS SUMMARY**

There are no documents.

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	8551	
Vehicle Details		
Vehicle No.:	SKE6018D	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	11 Feb 2020	
Vehicle Make:	HONDA	
Vehicle Model:	STREAM 1.8X A	
Primary Colour:	White	
Manufacturing Year:	2008	
Engine No.:	R18A1777390	
Chassis No.:	RN61069957	
Maximum Power Output:	103.0 kW (138 bhp)	
Open Market Value:	\$18,862.00	
Original Registration Date:	03 Jun 2008	
First Registration Date:	03 Jun 2008	
Transfer Count:	3	
Actual ARF Paid:	\$18,862.00	
Intended PARF Rebate Details		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		
COE Expiry Date:	02 Jun 2023	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	5	
PQP Paid:	\$18,953.00	
COE Rebate Amount:	\$12,544.00	
Total Rebate Amount:	\$12,544.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Feb 2020

Products

Insurance

Articles

Forum

Resources



# ANNOUNCING Cosmo Automobiles

as sgCarMart Premium Dealer for the 5th Consecutive Year

• 5 M 0 AUTOMOBILES



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!




Borneo Unit! 8x Free Servicing! All-In Pricel GST Inclusive! Full

Accessories!

\$66600! \$66600! PROMO! New Borneo Toyota Dyna 150!







02/2023)

Selling Cheap! No Worries To Drive Until Scrap! Powerful And Responsive. Spacious Interior! Very Comfortable 7 Seater MVP For Family, Very Well Maintained, Contact Us To Arrange A Viewing Now!

FREHUIT ICE

Posted: 10-3an-2020



Honda Stream 1.8A RSZ (COE till 04/2023)

\$23,666

\$7,370 /yr

29-Apr-2008

1.799 cc

147,000 km


Available



Full Loan Available. 2 Owner Only. Very Well Maintain And Low Mileage, Comfortable And Reliable Luxury 7 Seater MPV, Low Maintenance Cost! Pristine Condition, Price Negotiable. Please Contact/Whatsapp Now To Arrange A Viewing.







S.VM: 200101919 | Vegett Automotive Rte., be. - Q. ENTRY DATE & TAYE (8.602.8020 13.60) SUBVITTED BY Con Sci Shong

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- The Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid:

			-			т А		-1	ы	-	4 10	
AC			-1		•	1 14	٠.	-1	ш	-		
	_	_	_	-	_	_	-	-		_	_	

 Date Of Report
 06/02/2020 13:50

 Date Of Accident
 05/02/2020 08:25

Exact Location Of Accident FILTERING FRM BT BATOK AVE 1 TO BT BATOK WEST AVE

Country/State of Loss SINGAPORE

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SKE6018D

Insured/Policyholder

Name Of Registered Owner YAP CHOON PING EDMUND

NRIC No SXXXX855I

Email Address EDM.PURCHASE@OUTLOOK.SG

Mobile Phone No (LOCAL) +65-94894441
Alternative Phone No OFFICE-94878930

Vehicle Particulars

Manufacturer HONDA

Model STREAM-1.8 X (A)

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5099937671-01

Cover Note Number

Driver

Name of Driver SOH I LING @JOANNE SOH I LING

 NRIC No
 SXXXX756F

 Date Of Birth
 31/05/1982

 Occupation
 INDOOR

 Date Of Driving Pass
 26/11/2012

Driving Experience 7 YEARS AND 2 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-94878930

Fax Number

Contact Number

EMail Address DARJOANNE315@GMAIL.COM.SG

Address

BLK 185 BUKIT BATOK WEST AVE 6 #02-199

Was driver an employee of the Insured's Company

If No. Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

NO

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I WAS STOPPING AT THE STOP LINE AND WHEN I STOP TO CHECK THAT THE TRAFFIC WAS CLEAR ALONG BUKIT BATOK WEST AVE 6, I FELT A BUMP FROM MY REAR. VEHICLE B HIT DIRECTLY ONTO MY CAR REAR PORTION.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLM3639C

Vehicle Make/Model/Colour

AUDI / GREY

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

97562088

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)


Date & Time:

8/2/2020

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stopping at the stop live, and when I stop to check that the traffic was clear along Brikit Batok west Ave 6, I felt a brugo from my year, vehicle B' hid directly onto my car rear partion.
Charle that the traffic was clear along Brilit Batok wast
Ave 6, I let a brugo from my year, vehicle B' hid
directly onto my car rear partion.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)
Date & Time: 0 421 2000

aure,

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Athi. Advisus

# MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422 / 6745 4422 Fax: 6747-6720 REG NO 200501102H

4 Shen SGX ( Singap Hot line	NSURANCE (S) PTE LTD  Iton Way # 21 - 01 Centre 2 Fore 068807 E 6827 - 7660 6225- 7402 ( CLAIM )	DATE VEH NO MODEL D O A YR REF	: 05.02.2020
Attn:	Motor Claim Dept (pls arrange vehic	cle survey & che	ck liability)
RE:	ESTIMATE FOR ACCIDENT REPAIR SKE6018	D (HONDA STR	EAM)
Item	Description	_Qty	_Amt
NO	LIST ITEMS		
1	Rear Bumper Distofed	1	688.90
2	Rear Bumper Clips ~~	1 set	30.00
3	Rear Bumper Side Holder - LH & RH New	2	46.40
4	Rear Bumper Towing Cover	1	28.90
5	Rear Bumper Bracket - LH & RH LH Sent	21	54.00 25.50
6	Rear End Panel Deviled	1	590.20
7	Rear End Panel Inner Member Report	1	325.50
8	Rear End Panel Inner Member	1	116.70
9	Tail Lamp - LH & RH He M	2	704.80 🛧
10	Tailgate Devled	1	903.20
11	Tailgate Lock	1	
12	Tailgate Weatherstripe Cut	1	121.60
13	Tailgate Inner Trim Board De C	1	3124 189.60 121.60 2499.10 284.00
14	Tailgate Inner Trim Board Clips	1 set	30.00
15	Tailgate Outer Garnish	1	160.70 🤝
16	Tailgate Glass Moulding No.	1	89.00
17	Honda Logo Nfm	1	28.20 ~
18	Rear Fender Inner Trim Board 2 H	2	449.40
19	Rear Fender Inner Trim Board Clips \	1 set	60.00 ×
			\$ 4,898.10
	Less 20	%	(979.62)
			\$ 3,918.48
	S/NET ITEMS		
1	Rear Bumper Side Garnish Not M	2	\$ 760.00 +
2	Reverse Sensor Dan d	1	\$ 280.00-200
3	Tailgate Glass Sealant	1	\$ 60.00

#### RE: ESTIMATE FOR ACCIDENT REPAIR SKE6018D (HONDA STREAM)

4	Rear Number Plate 2x4	2	1	\$ 30.00
5	Rear Number Plate Holder	260	1	\$ 30.00
				\$ 1,160.00
		Total parts		\$ 5,078.48
	LABOUR CHARGE			
1	To knocking & pull out rear portion & re-	new above parts		\$ 1,000.00 800
2	To putty and spray up paint works			\$ 1,000.00 8W 1,000.00 8W 50.00 30
3	To check wiring system			\$ 50.00 30
4	To underseal			\$ 150.00 60
5	To remove reverse sensor	2000		\$ 100.00 50
6	To transfer tailgate fittings			\$ 150,00 80
7	To remove tailgate glass			\$ 180.00 120
8	To remove upholstery			\$ 150.00 60
				\$ 2,780.00
		GRAND TOTAL		\$ 7,858.48

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 4759.20 L/3: 3.81C. 06 Denys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

	FOLDER TRAC	T	Transfer and the second	Transmission	Tarra	4		Charles	
Case	Notified 06 Feb 2020 16:25	Est Submitted	Adj Assigned 07 Feb 2020 09:57 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,8	soo.oo Rpt	Ins Auth'ed	Pending for Su Report Cancel Case	
	Main	Ref	erence	Claim Det	ails		Documents		Show All
CLAIM SU	BFOLDER DE	TAILS		Fig. of conductors	[C	reated by	/ insurer]		
Insured:	CHAI YOO	N FAH, ID: S172	6606C						
Main Claimant:	<b>УАР СНОО</b>	N PING EDMUND	ID: S76358551						
Vehicle Reg No.:	SKE6018	ID .		Date of			08:00 - :59 and <b>2</b> Days Fro	om LTA Reg Da	ate (Man Yr)]
Claim Type	: <b>TP</b> / 6192	210		Policy/C Note No			MY (Comprehen 3/03/2019 - 27/		
Vehicle Reg No. (Insured):	SLM36390			Policy N (Claimai					
				Excess:	1-7	1,500.00			
Repairer:	Modern Au	tomotive Pte Ltd	(HQ) Blk 3023A U	bi Road 1, #01-61	& #01-58	3, 408717	Jbi - Tel: 6748	4422 / 6747 4	422
Handling Insurer:	MSIG Insu	rance (Singapore	e) Pte. Ltd. (HQ) -	Tel: +65 6827 788	88 [Har	ndled by F	ievel Foo Wen	yao - 6643 13	16]
Adjuster:	LKK Auto	Consultants Pte L	td (HQ) - Tel: 625	6-3561 [Handled	by XING	GUO QI	ANG] [Final	Rpt due 0	8/03/2020]
Driver/Cust dian (Insured):	to	niconinos (out intercuento)	NRIC: S1826296						
Adj Asg. Remarks:	on WP. Liab	o: clear. Agree on S	JE. Assign: LKK Aut	to Consultants Pte	td. Conta	act: Grace	Chin @ 6748 44	122.	
ASSOCIA	TED MAIL REC	CEIVED					Vie	w All Com	pose Case Mai
There are r	no mail for this	case.							
ALL ASSO	CIATED TASI	ks⊟			View	All Se	arch Tasks C	Create New Tas	k Complete
Due Dat	ACTION TO STATE OF THE STATE OF	Type Task G	roup Subject	Handler A	ssigned	ву С	Completed On	Created	On Done

Merimen e-Claims Page 1 of 2

#### Claim Documents

\*SKE6018D (619210)

[SLM3639C]

TP

YAP CHOON PING EDMUND
Feb 5 2020 8:00AM

[CHAI YOON FAH]

Modern Automotive Pte Ltd

Ass	essment Reports		1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Prin
1	05/03/20 09:48	Adjuster Immediate Advice	1 Load HTM	1
Pho	otos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Prin
1	04/03/20 00:10	General View	■ Load JPC	<b>V</b>
2	04/03/20 00:10	General View	1 Load JPC	<b>V</b>
3	04/03/20 00:10	General View	1 Load JPC	· 🗹
4	04/03/20 00:10	General View	1 Load JPC	<b>=</b>
5	04/03/20 00:10	General View	1 Load JPC	
6	04/03/20 00:10	General View	1 Load JPC	<b>V</b>
7	04/03/20 00:10	General View	1 Load JPC	
8	04/03/20 00:10	General View	1 Load JPC	· 🗹
9	04/03/20 00:10	General View	1 Load JPC	<b>V</b>
10	04/03/20 00:10	General View	1 Load JPC	<b>V</b>
11	04/03/20 00:10	General View	1 Load JPC	
12	04/03/20 00:10	General View	1 Load JPC	3 <b>V</b>
13	04/03/20 00:10	General View	1 Load JPC	S 2
14	04/03/20 00:10	General View	1 Load JPC	3 <b>•</b>
15	04/03/20 00:10	General View	1 Load JPG	3 <b>V</b>
16	04/03/20 00:10	General View	1 Load JPG	5 <b>V</b>
17	04/03/20 00:10	General View	♠ Load JPC	3 <b>V</b>
18	04/03/20 00:10	General View	1 Load JPC	3 2
19	04/03/20 00:10	General View	1 Load JPG	3 <b>V</b>
20	04/03/20 00:10	General View	1 Load JPC	5 <b>V</b>
21	04/03/20 00:10	General View	1 Load JPG	3 <b>3</b>
22	04/03/20 00:10	General View	1 Load JPG	5 <b>V</b>
23	04/03/20 00:10	General View	1 Load JPG	5 <b>V</b>
24	04/03/20 00:10	General View	1 Load JPG	3 🗸
25	04/03/20 00:10	General View	1 Load JPG	5 <b>V</b>
26	04/03/20 00:10	General View	1 Load JPG	5 <b>V</b>
27	04/03/20 00:11	Reinspection Photo	1 Load JPG	3 <b>4</b>
28	04/03/20 00:11	Reinspection Photo	1 Load JPG	3 <b>•</b>
29	04/03/20 00:11	Reinspection Photo	1 Load JPG	
30	04/03/20 00:11	Reinspection Photo	1 Load JPC	3 <b>•</b>
31	04/03/20 00:11	Reinspection Photo	1 Load JPG	
32	04/03/20 00:11	Reinspection Photo	1 Load JPG	
33	04/03/20 00:11	Reinspection Photo	1 Load JPG	
34	04/03/20 00:11	Reinspection Photo	■ Load JPG	3

Ass	essment Reports		1 per page 🔍	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	_
				V
35	04/03/20 00:11	Reinspection Photo	■ Load JPG	V
36	04/03/20 00:11	Reinspection Photo	1 Load JPG	V
37	04/03/20 00:11	Reinspection Photo	1 Load JPG	<b>✓</b>
38	04/03/20 00:11	Reinspection Photo	1 Load JPG	V
39	04/03/20 00:11	Reinspection Photo	£ Load JPG	<b>✓</b>
40	04/03/20 00:11	Reinspection Photo	1 Load JPG	V
41	04/03/20 00:11	Reinspection Photo	1 Load JPG	V
42	04/03/20 00:11	Reinspection Photo	1 Load JPG	V
43	04/03/20 00:11	Reinspection Photo	1 Load JPG	V
44	04/03/20 00:11	Reinspection Photo	Load JPG	<b>▼</b>
45	04/03/20 00:11	Reinspection Photo	6 Load JPG	<b>V</b>
46	04/03/20 00:11	Reinspection Photo	Load JPG	<b>V</b>
47	04/03/20 00:11	Reinspection Photo	Load JPG	V
48	04/03/20 00:11	Reinspection Photo	■ Load JPG	V
49	04/03/20 00:11	Reinspection Photo	Load JPG	~
50	04/03/20 00:11	Reinspection Photo	■ Load JPG	V
		Reinspection Photo	1 Load JPG	V
51	04/03/20 00:11	CONTRACT AND ACCUSED	1 Load JPG	V
52	04/03/20 00:11	Reinspection Photo	1 Load JPG	<b>Z</b>
53	04/03/20 00:11	Reinspection Photo	Load JPG	₩.
54	04/03/20 00:11	Reinspection Photo	1 Load JPG	<b>Z</b>
55	04/03/20 00:11	Reinspection Photo		<b>▼</b>
56	04/03/20 00:11	Reinspection Photo	1 Load JPG	1,500
57	04/03/20 00:11	Reinspection Photo	1 Load JPG	₩.
58	04/03/20 00:11	Reinspection Photo	1 Load JPG	<b>✓</b>
			1 per page V	
	cumentation	100 - 101 - 101 (UO)	Thumbna	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Load PDF	
1	06/02/20 16:29	OI Gia Report TP SKE6018D Gia report	1 Load PDF	_
2	06/02/20 16:29	PRI ffrom Modern Automotive Pte Ltd	1 Load PDF	_
3	06/02/20 16:29		1 Load PDF	_
5	06/02/20 16:50	Agree on SJE Email from TP - Arrange Survey	1 Load PDF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			,

### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG20002146/AGVF3E2

Date:

06/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A80467691QMY

Claimant Vehicle

SKE6018D

Insured Vehicle No:

SLM3639C

No: Date of Loss:

05/02/2020

Nature of Claim:

TP

Claim No: 619210

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SKE6018D

Make & Model:

HONDA STREAM, 1.8 X (A) 03/06/2008 (Man. Year: 2008)

Engine No: Chassis No: R18A1777390

Reg. Date: Colour:

White

Odometer:

RN61069957 207633 km

Engine Capacity:

1799 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Vec

Handbrake (Serviceable):

es Engine Modification:

No Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Nexen 6 mm

Rear Left Side:

Nexen 6 mm

Front Right Side:

Nexen 6 mm

Rear Right Side:

Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,078.48	2,775.20	2,303.28	45.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	2,000.00	780.00	28.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,858.48	4,775.20	2,303.28 0.00 780.00 0.00	39.24
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	7,858.48	3,800.00	4,058.48	51.64
+ GST 7.00/7.00% (S\$)	550.09	266.00	284.09	51.64
Nett Amount (S\$)	8,408.57	4,066.00	4,342.57	51.64

INSPECTION

Date of Assignment:

07/02/2020

Date Inspected:

10/02/2020 Inspected At:

Modern Automotive Pte Ltd (HQ)

Blk 3023A Ubi Road 1, #01-61 & #01-58

Singapore 408717

Estimated Period of Repair:

6.0 days

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for SKE6018D)
Validity:		es are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values n	ot in reference catalogue are prefixed with an asterisk *.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	688.90 FL	*688.90 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER - LH & RH	Necessary	46.40 FL	*46.40 FL
4	1		*REAR BUMPER TOWING COVER	Deformed	28.90 FL	*28.90 FL
5	1		*REAR BUMPER BRACKET - LH & RH	N/S Bent	51.00 FL	*25.50 FL
6	1		*REAR END PANEL	Dented	590.20 FL	*590.20 FL
7	1		*REAR END PANEL INNER MEMBER	Repair	325.50 FL	*-FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	116.70 FL	*116.70 FL
9	2		*TAILLAMP - LH & RH	Not Necessary	704.80 FL	*-FL
10	1		*TAILGATE	Dented	903.20 FL	*903.20 FL
11	1		*TAILGATE LOCK	Damaged	189.60 FL	*189.60 FL
12	1		*TAILGATE WEATHERSTRIPE	Cut	121.60 FL	*121.60 FL
13	1		*TAILGATE INNER TRIM BOARD	Deformed	284.00 FL	*284.00 FL
14	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FL	*30.00 FL
15	1		*TAILGATE OUTER GARNISH	Not Necessary	160.70 FL	*-FL
16	1		*TAILGATE GLASS MOULDING	Necessary	89.00 FL	*89.00 FL
17	1		*HONDA LOGO	Not Necessary	28.20 FL	*- FL
18	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	449.40 FL	*- FL
19	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
20	2		*REAR BUMPER SIDE GARNISH	Not Necessary	760.00 FS	*- FS
21	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
22	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
23	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
24	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	6,058.10	3,404.00
			- List Item Discount on L Items	20.00/20.00% (S\$)	979.62	628.80
				Total Parts (S\$)	5,078.48	2,775.20

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,000.00	800.00
TO PUTTY AND SPRAY UP PAINT WORKS	New	1,000.00	800.00
TO CHECK WIRING SYSTEM	New	50.00	30.00
TO UNDERSEAL	New	150.00	60.00
TO REMOVE REVERSE SENSOR	New	100.00	50.00
TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
TO REMOVE TAILGATE GLASS	New	180.00	120.00
TO REMOVE UPHOLSTERY	New	150.00	60.00
Gross Lab	our Cost (S\$)	2,780.00	2,000.00
	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS TO PUTTY AND SPRAY UP PAINT WORKS TO CHECK WIRING SYSTEM TO UNDERSEAL TO REMOVE REVERSE SENSOR TO TRANSFER TAILGATE FITTINGS TO REMOVE TAILGATE GLASS TO REMOVE UPHOLSTERY	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS TO PUTTY AND SPRAY UP PAINT WORKS New TO CHECK WIRING SYSTEM New TO UNDERSEAL New TO REMOVE REVERSE SENSOR New TO TRANSFER TAILGATE FITTINGS New TO REMOVE TAILGATE GLASS New	Dur Items         TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS         New         1,000.00           TO PUTTY AND SPRAY UP PAINT WORKS         New         1,000.00           TO CHECK WIRING SYSTEM         New         50.00           TO UNDERSEAL         New         150.00           TO REMOVE REVERSE SENSOR         New         100.00           TO TRANSFER TAILGATE FITTINGS         New         150.00           TO REMOVE TAILGATE GLASS         New         180.00           TO REMOVE UPHOLSTERY         New         150.00

Report was unsubmitted during this print-out.