

22/03/2002

ASS. REC. BY:

REF: (SIC) 20002247/ESf3/12

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Irene Tay

of

CT1

Date/Time: 10.2.2020 11.59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMP 30736

Insured: YH 335

at Workshop m/s Bannu Motor

Tel: 66311505

of 2 Pandan Crescent

Policy No: DMCVSN 30730519000

Claim No: SNM 20022471 / YH 335 / IR626

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16.1.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 10.2.2020 1.43pm

Person Contacted: Carina

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMP 30736 - X

YH 335 - NA / INC 1800172124

D.O.A. - 18/01/2018



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

 Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

www.lexus.com.sg

 Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Ms Oon Poey Leng <i>Summer</i> 57 Faber Green Singapore 129291
	Document No 0	Mobile: 93222880 <i>12/2/2020 - 11am</i>
	Document Date 22/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEZGB	L1	AXZA10R	20/09/2019	SMP3073G	0	18195 11TP/SMP3073G/160121

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHB11B1502012293	A25A5204311	60	Carine Yeo C L	--/--/---- 0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS; CHINA TAIPING ACC DATE: 16.01.2020 T/P VEH: YH 33 S DATE IN: DATE SURVEY: DATE AUTHORIZ:			<i>me</i>	<i>50</i> 100.00
2	S	BP-SUBLET CARRY OUT SURFACE COATING ON BONNET AND FRONT BUMPER				256.00 /
3	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRIGTHEN ON FRONT BUMPER, BONNET AND FIX NEW PARTS <i>866</i>			<i>1732</i>	2598.00
4	B	BP-RES3, TO, SPRAY PAINT ON FRONT BUMPER AND BONNET <i>738</i>			<i>1484</i>	2226.00
5	Z	BP-SLANT SUPPLY BONNET SEALANT (NETT)				100.00 /
6	B	BP-LAB3 TO REMOVE AND RE-INSTALL BOTH HEADLAMPS TO CHECK ON DAMAGES, REPLACE IF DAM AGE.CHECK AND FOCUS HEADLIGHTS (NETT)				216.50 /
7	B	BP-LAB3 TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)				216.50 /

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 22/01/2020
 TIME 15:28

VEHICLE NO SMP3073G

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Inchcape

Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Ms Oon Poey Leng 57 Faber Green Singapore 129291 Mobile: 93222880
	Document No 0	
	Document Date 22/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEZGB	L1	AXZA10R	20/09/2019	SMP3073G	0	18195 1TP/SMP3073G/160121

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHB11B1502012293	A25A5204311	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	B	BP-ECU3 TO RESET ECU & REPROGRAMME (NETT)				216.50 ✓
9	1	L53101-33680 GRILLE SUB-ASSY, / CUT	1.00	1660.70		1660.70 ✓
10	2	L53301-33260 HOOD SUB-ASSY / 00	1.00	2962.10		2962.10 ✓
11	3	L52119-3T945 COVER, FR BUMPER / CR4	1.00	1046.20		1046.20 ✓
12	4	L52542-33010 SEAL, FR BUMPER, CTR / RC	1.00	92.50		92.50 ✓
13	5	L53114-33050 GRILLE, RADIATOR, X N/A	1.00	199.30		199.30 X
14	6	L89341-33220 C4 SENSOR, ULTRASONIC, X N/A	2.00	488.00		976.00 X
15	7	L89341-33220 J2 SENSOR, ULTRASONIC, X N/A	2.00	490.80		981.60 X
16	8	L89348-50130 RETAINER, ULTRASONIC / RC	2.00	19.20		38.40 ✓

Steve (LKK) wrl Phil
12/2/20, 11.00 am
P/P
Ry Ref- SM
5 days

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

13,957.20

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 7,956.80 Labour 5,673.50 Materials 256.00 Lubrication/Fluid 0.00 Others 0.00	13,886.30
			GST 7.00% 972.04
			Less 0.00
			Amount Due 14,858.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES and is subject to final approval from Insurance Company

VEHICLE NO SMP3073G
Acknowledged by Repairer
Signature:
Date:

PLEASE TEAR ALONG PERFORATED LINE

DATE 22/01/2020
TIME 15:28SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

ESTIMATELexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Ms Oon Poey Leng 57 Faber Green Singapore 129291 Mobile: 93222880
	Document No 0	
	Document Date 25/03/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEZGB	L1	AXZA10R	20/09/2019	SMP3073G	0	18457 61SU/SMP3073G
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB11B1502012293	A25A5204311	60	Carine Yeo C L	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUPPLEMENTARY ESTIMATE POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				
2	1	L85362-33020 BRACKET, WASHER, <i>✓ m</i>	1.00	41.90		41.90 A
3	2	L85361-33040 BRACKET, WASHER, <i>✓ m</i>	1.00	29.00		29.00 A
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 70.90 Labour 0.00 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	70.90 GST 7.00% 4.96 Less 0.00 Amount Due 75.86

25/03/2020
11:37

SMP3073G

WORKSHOP

**Borneo Motors**