



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002264/Db3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6306Z	Veh. Inspected	SH 6199D
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20000863MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	07/02/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU164223	Colour	BLUE
Odometer	98144	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	MICHELIN	5 mm
L/H Rear Tyre	195/65 R15	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT & O/S REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS
--

5. General Information

Accident Date	04/02/2020	Inspection Date	10/02/2020
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------