

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM20002285/Hga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN		Date: 11-11-2020 Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLG 3568E	Veh. Inspected	SLR 4073B	
	Policy No.	GA497230	Coverage (\$)	0.00	
	Claim No.	S0M02FQ7	Excess (\$)	0.00	
	Assign From		Assign Date	10/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	OPEL ASTRA HB	c.c	999	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	W0LBE6EA4HG171351	Colour	RED	
	Odometer	60712	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE	5 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	5 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	5 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	01/02/2020	Inspection Date	10/02/2020	
	Survey held at	8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit			
	Repairer	Repairer SPEED AUTO WORKS			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				