




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ZOOM AUTOWERKS PTE LTD		Ref : CC4/TP20002352/Uea3q2		
130 BEDOK RESERVOIR ROAD #08-1339 EUNOS SPRINGSINGAPORE 470130		Date : 03-09-2020		
		Code : TP506		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	Veh. Inspected	SGV 9134P	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	11/02/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA VIOS (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	MR053HY9305004894	Colour	GREY
	Odometer	261817	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	YOKOHAMA	5 mm
	L/H Front Tyre	195/55 R15	YOKOHAMA	5 mm
	R/H Rear Tyre	195/55 R15	YOKOHAMA	5 mm
	L/H Rear Tyre	195/55 R15	YOKOHAMA	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	08/02/2020	Inspection Date	11/02/2020
	Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	