



Your Ref: 13/14/14/VP00/175414

Date: 26<sup>th</sup> February 2020

Our Ref: CS1/LPC20002368/Dvd3s2

**M/s Lonpac Insurance Bhd**

21st Floor, Bangunan Public Bank

No. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SBA 359L  
INSURED VEHICLE: JLS 963 ACCIDENT DATE: 01/04/2014**

We thank you for your instruction on 07/02/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBA 359L from M/s Auto Spec Appraiser.
- b) Polis Diraja Malaysia of Vehicles SBA 359L, JLS 963 and Trailer Lorry
- c) Polis Diraja Malaysia Police Report of Plus Expressway Bhd.
- d) Colour damaged vehicle photographs of SBA 359L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SBA 359L
Make & Model	: Suzuki Vitara 2WD A
Year of Registration	: 2007
Chassis Number	: JSAJTE54V00200277
Engine Capacity	: 1995 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.