

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20002373/Kpa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	15/04/2021	
	ATTN:PETER			Code:	ASM	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YM 862P	Veh. Inspected	l	SJX 5416G	
	Policy No.	P1564959	Coverage (\$)		0.00	
	Claim No.	S0M02FZ5	Excess (\$)		0.00	
	Assign From		Assign Date		11/02/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALTIS (A)	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	MR053ZEE106171801	Colour		METALLIC PEARL WHITE	
	Odometer	168855 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA		7 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA		7 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA		7 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/02/2020	Inspection Dat	е	14/02/2020	
	Survey held at WEI LEE MOTOR WORKS					
		BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					