

kp

威利摩多

WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

11, Feb 2020

AXA Insurance Pte Ltd
143 Cecil Street
#01-01 GB Building
S 069542

Not Authorized
11 Day @ 1700/-
Resurvey After Paint
4 days

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: YM862P
Accident involving vehicle no: SJX5416G/YM862P
DOA: 06/02/2020 At Margaret Dr

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SJX5416G
To supply--

Description	Qty	Amount
Bonnet	1 <i>B₁</i>	833.70 ✓
Front grille	1 <i>Old 10.1</i>	305.80 ✓
Grille logo	1 <i>Ma</i>	60.20 ✓
Front bumper	1 <i>Buc</i>	423.60 ✓
Bumper enforcement	1 <i>R</i>	339.70 X
Bumper lower grille	1 <i>Sn</i>	93.30 X
Parts		2,056.30
Parts less 25%		514.07
		1,542.23

To remove damaged parts and attachments.
To repair/reshape dented areas
Replace/align above parts into position
To spray paint

700.00 *5001*
500.00 *4501*

2,742.27

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier(s) must be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8034