

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring #08-1339 Singapore 470130 Tel: 9450 7920

™ zoomautowerks@gmail.com

866.00

Date: 11/02/2020

Car Number: SKC7985R Model: VW Jetta

Parts / Material: 1

2

4

5

7

8

9

11

12

13

Damaged Area: (Left Side Damaged) Repairer Estimation Cost of Repair:

Front Bumper

Front Left Fender

Front Left Door

Left Rocker Panel

Rear Left Door

Front Left Bumper Bracket Front Bumper Clips

Front Left Fender Inner Shield

Front Left Wing Mirror Assy

Front Left Door Inner Trimboard

Front Left Door Weather Strip

Front Left Door Inner Trimboard Clips

Front Left Fender Inner Shield Clips

Supplementary may be included during the cost of repair :

Quantity		- 1
	\$ 17	1,140.00 X
	\$ 11	44.80 X
	\$ 11	60.00 ×
	\$ n	798.13
	\$ 17	181.70 X
	\$ 17	60.00
	\$ 17	873.80 X
	\$ 190	1,435.72
	\$ cru	1,159.52
	\$ 11	60.00 X
	\$ 11	289.33 🗴
	\$ 5.5	986.70
	11	Repair 🗸
Parts:	\$	7,089.70
Less Parts 10%:	\$	708.97

Total Parts: \$ 6,380.73

1,200.00

50.00 C 200.00

150.00 X

150.00

3,350.00

0,2 1,400.00

200.00

11 \$

Total S/N Parts: \$

Special Net Items:

Rocker Panel Sealant

Labour:

To Remove, Repair & Renew Affected Accident Areas To Putty, Spray Paint on Affected Accident Areas

To Check & Re-Connect all electrical wiring

To Remove & Install RH Front Door Components Trim & Garnish

To Remove, Install Interior Chairs, Carpet, Trims to Facilitate Repairs

To Conduct Water Leakage Test

To Rust Proof Affected Areas

TOTAL PARTS:	\$	6,380.73
TOTAL SPECIAL NET ITEM:	\$	80.00
TOTAL LABOUR :	\$	3,350.00
TOTAL REPAIR COST .	4	9 810 73

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM:

RECOMMENDED NUMBER OF DAYS:

SURVEY BY / SURVEYOR FIRM:

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT : is subject to final approval from insurance Company FINALISED AMOUNT:

LKK Auto Consultants hence notify

Total Labour: \$

- the Repairer of the following:
- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Acknowledged by Repairer

Signature: