

ASS. REC. BY:

REF: CS/SMO20002377/ ky d3

Special Instruction:

Survey: Kenneth

ASSIGNMENT (Office)

From (Person): Grace Teo

of SMO

Date/Time: 11/02/2020 @ 4:18pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 2917A

Insured:

at Workshop m/s Ah Lim Motor

Tel: 64831244

of 10 Amk Ind. Park 2A # 01-09

Policy No:

Claim No: CMTD2000638/syH

Sum Insured:

Excess: TBA

Make of Veh:

(Client's license)

D.O.A. 09/02/2020

CA / (REV) REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4:33pm @ 11/2/2020

Person Contacted:

Zila

Vehicle-IN (OUT)

Date/Time	Action/Instruction
	Tobin ✓
	SKZ 2917A - CS/SMO20002377/TS
	DOA 9/2/2020

ASSIGNMENT

From: \_\_\_\_\_ Date: 12/02/2020

Veh No: SKZ 2917A Yr Regn: 01, 16

Estimated Cost: \_\_\_\_\_

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or \_\_\_\_\_

To Inspect Vehicle No: SKZ 2917A

Make: Mercedes <sup>A)</sup> 6 C.C. 1998

at Workshop m/s Alhim Motor

Colour: M. Black A/C: Insured / Std / NI / NA

of 10 AMK Ind. Park 2A # 01-09

Sp. Reading: 73759 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: Tm 64J1072 G-0221101

Claims No. \_\_\_\_\_

Gen. Cond:  Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: 7BA 0

Steering:  In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake:  In order / Jammed / Leaked / Burnt or


Make of Veh: 9am-12pm

Modi: Nil / S/Rim / STD / R/Rim or

(Policy Condition)

Tyre Size: F: 225/55R17

Remark: The veh had commenced its repair at the time of inspection.



R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO /  YOKO or

Bal. or Market Value: \$ 64k

Front R/Bal: 7 mm Rear R/Bal: 7 mm

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

L/Bal: 7 mm L/Bal: 7 mm

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

D.O.A. 9/2/20 D.O.I. 12/2/20

Est. Repairs: 07 days Res.: Yes or No

Survey held at

Lum Sum: 1-A1 % 3 Val.: Yes or No

Des. of Damages: Nil body Frt / Rear / O/S / N/S / U/C / Rooftop or

CA /  REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/2	Revert via email
17/2	Approval Mandate by Shiang Yi
13/2	Sent email to workshop Authorise
20/3	US \$2950/= (Red \$1175-50, 28%)

RECEIVED 20 MAR 2020

Date/Time, File Pass to?  : Prel. Report

Days Of Repair: 7

1)  : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 20/3/20 Typist

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invt (\$ \_\_\_\_\_)

: Wash and (\$ \_\_\_\_\_)

Survey Fee:

Transportation: \_\_\_\_\_ \$ + RS \_\_\_\_\_ \$

Finley

Other:

TOTAL

250

Report Format:

1)  2950k



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000638/SYH

Date: 12/02/2020

Our Ref: CS/SMO20002377/Kyd3

The Motor Claims Department  
SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sirs/Mdm,


**PRELIMINARY ADVICE OF VEHICLE NO. SKZ2917A**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 12/02/2020 at the premises of M/s AH LIM Motor and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 4,125.50</u>
Revised Estimate Amount	: <u>S\$ 3,119.00</u>
Check <sup>o</sup> Items Amount	: <u>S\$ 396.00</u>
Total	: <u>S\$ 3,515.00</u>
Market Value	: <u>S\$ 64,000.00</u>
LTA Reimbursement Value	: <u>S\$ 50,083.00</u>
Nett Value	: <u>S\$ 13,917.00</u>

**Description of Damage:**

The vehicle sustained at the n/s body portion



**Comments/ Present Status:**

Damage consistent  
Repair cost economical

Yours faithfully  
Kenneth Kong  
Licensed Appraiser

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, February 13, 2020 10:22 AM  
**To:** Zila @ Ah Lim Motor Company  
**Cc:** SUR  
**Subject:** RE: CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKZ2917A (excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**YC Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonne.wong@lkkauto.com](mailto:yvonne.wong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [mailto:[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)]  
**Sent:** Tuesday, February 11, 2020 4:18 PM  
**To:** Zila @ Ah Lim Motor Company <[zila@ahlimmotor.com.sg](mailto:zila@ahlimmotor.com.sg)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Hwang, Shiang Yi <[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg)>  
**Cc:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>  
**Subject:** CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)

Our Claim Reference : CMTD2000638/SYH

Your Reference: SKZ2917A

Hi Zila,

We acknowledged receipt of your claim documents.

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, February 13, 2020 9:35 AM  
**To:** Hwang, Shiang Yi  
**Cc:** Ye, Yong Kang Melvin; SUR  
**Subject:** RE: CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)  
**Attachments:** SKZ2917A ESTIMATE.pdf; SKZ2917A LIC.pdf; SKZ2917A CI.pdf; SKZ2917A GIA.pdf; SKZ2917A PRELI ADVISE OD.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SKZ2917A  
Date of survey : 12/02/2020  
Number of days : 7 days  
Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonne.wong@lkkauto.com](mailto:yvonne.wong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [mailto:[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)]  
**Sent:** Tuesday, February 11, 2020 4:18 PM  
**To:** Zila @ Ah Lim Motor Company <[zila@ahlimmotor.com.sg](mailto:zila@ahlimmotor.com.sg)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Hwang, Shiang Yi <[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg)>  
**Cc:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>  
**Subject:** CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)

Our Claim Reference : CMTD2000638/SYH  
Your Reference: SKZ2917A

Hi Zila,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/  
[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg) .

Please be informed that we will appoint **LKK AUTO** to conduct the survey.

## Yvonne Wong (LKK Auto)

---

**From:** Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>  
**Sent:** Thursday, February 13, 2020 9:52 AM  
**To:** Yvonne Wong (LKK Auto)  
**Cc:** SUR; Claims - Motor Survey  
**Subject:** RE: CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)

Dear Yvonne,

Please proceed authorise repair and excess waived.

Best Regards

**Hwang Shiang Yi**

Claims Division

D: 6329 5205 | T: 6461 6555 | F: 6221 3147



**SOMPO**  
INSURANCE

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>  
**Sent:** Thursday, 13 February, 2020 9:35 AM  
**To:** Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>  
**Cc:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SKZ2917A

Date of survey : 12/02/2020

Number of days : 7 days

Thank you.

Best Regards,

**Yvonne Wong (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonne.wong@lkkauto.com](mailto:yvonne.wong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

**Sent:** Tuesday, February 11, 2020 4:18 PM

**To:** Zila @ Ah Lim Motor Company <[zila@ahlimmotor.com.sg](mailto:zila@ahlimmotor.com.sg)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Hwang, Shiang Yi <[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg)>

**Cc:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>

**Subject:** CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)

Our Claim Reference : CMTD2000638/SYH

Your Reference: SKZ2917A

Hi Zila,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg).

Please be informed that we will appoint **LKK AUTO** to conduct the survey.

Hi **LKK AUTO**,

Please assist to conduct motor survey on **Own Damage** basis.

Please **revert** with your preliminary report upon completion of survey to my colleague, **Ms. Shiang Yi** for authorisation.

Aside to **Shiang Yi**,

Please advise on the Excess and Authorisation.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

**For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)**



**SOMPO**  
INSURANCE

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](http://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

Download now @



or



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Zila @ Ah Lim Motor Company <[zila@ahlimmotor.com.sg](mailto:zila@ahlimmotor.com.sg)>

**Sent:** Tuesday, February 11, 2020 1:36 PM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

**Cc:** Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>

**Subject:** SKZ2917A - OD CLAIM

Hi Claims Dept,

Kindly arrange for survey.

Note: Vehicle is not in – To be arrange

Thanks.

Regards

Zila

Ah Lim Motor (AMK)

10 Ang Mo Kio Ind Pk 2A

#01-09 AMK AUTOPOINT

S568047

TEL: 64831244 Fax: 64836170

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Tuesday, 11 February 2020 4:18 PM  
**To:** Zila @ Ah Lim Motor Company; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com; Hwang, Shiang Yi  
**Cc:** Ye, Yong Kang Melvin  
**Subject:** CMTD2000638/SYH - OD(LKK)/ SKZ2917A ACC ON 09.02.20 - Pls arr suv tmr, 12/2 (9-12n)  
**Attachments:** 2917 - SOMPO.PDF; 2917.pdf

Our Claim Reference : CMTD2000638/SYH  
Your Reference: SKZ2917A

Hi Zila,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/[shiangyi.hwang@sompo.com.sg](mailto:shiangyi.hwang@sompo.com.sg).

Please be informed that we will appoint **LKK AUTO** to conduct the survey.

Hi LKK AUTO,

Please assist to conduct motor survey on **Own Damage** basis.

Please **revert** with your preliminary report upon completion of survey to my colleague, **Ms. Shiang Yi** for authorisation.

Aside to Shiang Yi,

Please advise on the Excess and Authorisation.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**SOMPO**  
INSURANCE


**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](http://www.facebook.com/SompoSG)

## Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @  **App Store** or  **Google Play**

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Zila @ Ah Lim Motor Company <[zila@ahlimmotor.com.sg](mailto:zila@ahlimmotor.com.sg)>

**Sent:** Tuesday, February 11, 2020 1:36 PM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

**Cc:** Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>

**Subject:** SKZ2917A - OD CLAIM

Hi Claims Dept,

Kindly arrange for survey.

Note: Vehicle is not in – To be arrange

Thanks.

Regards

Zila

Ah Lim Motor (AMK)

10 Ang Mo Kio Ind Pk 2A

#01-09 AMK AUTOPOINT

S568047

TEL: 64831244 Fax: 64836170

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 762J

**Vehicle Details**

Vehicle No.: SKZ2917A  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 10 Feb 2020  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT  
Primary Colour: Black  
Manufacturing Year: 2015  
Engine No.: PE20699651  
Chassis No.: JM6GJ1072G0221101  
Maximum Power Output: 121.0 kW (162 bhp)  
Open Market Value: \$20,519.00  
Original Registration Date: 18 Jan 2016  
First Registration Date: 18 Jan 2016  
Transfer Count: 0  
Actual ARF Paid: \$20,727.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 17 Jan 2026  
PARF Rebate Amount: \$15,545.00

**Intended COE Rebate Details**

COE Expiry Date: 17 Jan 2026  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$58,190.00  
COE Rebate Amount: \$34,538.00  
**Total Rebate Amount: \$50,083.00**

The information contained herein is correct as at 10 Feb 2020

OK

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
 GST:M9-0009639-E RCB NO.06470300B

**SURVEYOR COPY**

**M/S :** SOMPO INSURANCE SINGAPORE PTE LTD  
 50 RAFFLES PLACE  
 #05-01/06 SINGAPORE LAND TOWER  
 SINGAPORE 048623

**TEL:** 64616555  
**ATTN:** Motor Claim Department

**Your Ref No:** SKZ2917A  
**Claim Type:** Own Damage  
**Accident Date:** 09/02/2020

**Estimate No:** MC1901038  
**Date:** 11 Feb 2020  
**Policy No:** D20MTPV01000974  
**Veh Reg No:** SKZ2917A  
**Make/Model:** MAZDA 6 4-DOOR  
 SEDAN 2.0

*Li-cc*  
*Nlsbany 9-12 Not Authoizd*  
*Resurvey Bk pain*

*Folan*

**Estimate Repair Cost to Vehicle No : SKZ2917A** *Part: 62564315*

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
<b>SPARE PARTS</b>				
1 FRONT DOOR LH		1 PC	<i>B1</i> 450.00	✓
2 FRONT DOOR OUTER HANDLE LH		1 PC	<i>NE</i> 90.00	✓
3 SIDE MIRROR AM LH		1 PC	<i>SVC</i> 260.00	?
4 SIDE MIRROR COVER LH		1 PC	<i>SVC</i> 40.00	?
5 SIDE MIRROR SIGNAL LAMP LH		1 PC	<i>IN</i> 45.00	X
6 REAR DOOR LH - CHECK PRICE		1 PC	<i>B1 wrap</i> 550.00	✓
7 REAR DOOR INNER LOCK		1 PC	<i>IN</i> 110.00	X
8 REAR DOOR RUBBER @ DOOR		1 PC	<i>SVC</i> 60.00	?
9 REAR FENDER LH		1 PC	<i>B1</i> 580.00	✓
10 REAR WINDSCREEN MOULDING		1 PC	<i>NE</i> 70.00	✓
			1,705.00	
		Add 10%	170.50	1,875.50
<b>Special Nett</b>				
11 INNER SEAL		1 PC	<i>NE</i> 20.00	✓
12 WINDSCREEN SEALANT		1 PC	<i>NE</i> 40.00	✓
				60.00
<b>LABOUR</b>				
13 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	<i>200</i>
14 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.		1 PC	120.00	✓
15 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	150.00	<i>100</i>
16 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.		1 PC	80.00	<i>60</i>
17 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER LH. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	900.00	<i>800</i>
18 TO SPRAY REAR FENDER LH,REAR DOOR LH,FRONT DOOR LH,SIDE MIRROR COVER LH.		1 PC	900.00	<i>650</i>
				2,190.00



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#05-01/06 SINGAPORE LAND TOWER  
SINGAPORE 048623  
TEL: 64616555  
ATTN: Motor Claim Department

Estimate No: MC1901038  
Date: 11 Feb 2020  
Policy No: D20MTPV01000974  
Veh Reg No: SKZ2917A  
Make/Model: MAZDA 6 4-DOOR  
SEDAN 2.0

Your Ref No: SKZ2917A  
Claim Type: Own Damage  
Accident Date: 09/02/2020

## Estimate Repair Cost to Vehicle No : SKZ2917A

Lump Sum Repair	SS 4,125.50
Add GST @ 7%	288.79
Total Amount payable	SS 4,414.29

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FOUR HUNDRED FOURTEEN AND CENTS TWENTY NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

4730.50

For AH LIM MOTOR COMPANY

L&K Auto Consultants hereby notify the Receiver of the following:

- To receive telephone enquiries
- To display details of parts mainly online
- Parts prices are subject to confirmation
- Third party survey is not a "no obligation" visit
- No Register/Check engine scan
- Separately providing a quote is not a commitment
- It is subject to final approval from the relevant authority

Acknowledged by Receiver  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

AUTHORISED SIGNATURE



KY

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmo@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#05-01/06 SINGAPORE LAND TOWER  
SINGAPORE 048623

Estimate No: MC1901038  
Date: 11 Feb 2020  
Policy No: D20MTPV01000974  
Veh Reg No: SKZ2917A  
Make/Model: MAZDA 6 4-DOOR  
SEDAN 2.0

TEL: 64616555  
ATTN: Motor Claim Department

Your Ref No: SKZ2917A  
Claim Type: Own Damage  
Accident Date: 09/02/2020

*Not Notified*  
*Resurvey By paing*  
*11 Reg @ 2950*

## Estimate Repair Cost to Vehicle No : SKZ2917A

*7 days*  
*Est: 6256431.5*

Description	U/Price	Quantity	Cost	Amount
			SS	SS
<b>SPARE PARTS</b>				
1 FRONT DOOR LH		1 PC	By 450.00	—
2 FRONT DOOR OUTER HANDLE LH		1 PC	Ne 90.00	—
<del>3 SIDE MIRROR-AM-LH</del>		<del>1 PC</del>	<del>Se 260.00</del>	<del>X</del>
<del>4 SIDE MIRROR COVER LH</del>		<del>1 PC</del>	<del>Se 40.00</del>	<del>X</del>
<del>5 SIDE MIRROR SIGNAL LAMP LH</del>		<del>1 PC</del>	<del>Se 45.00</del>	<del>X</del>
6 REAR DOOR LH - CHECK PRICE		1 PC	0.0000	— 550
7 REAR DOOR INNER LOCK		1 PC	Ne 110.00	X
<del>8 REAR DOOR RUBBER @ DOOR</del>		<del>1 PC</del>	<del>Se 60.00</del>	<del>X</del>
9 REAR FENDER LH		1 PC	By 580.00	—
10 REAR WINDSCREEN MOULDING		1 PC	Ne 70.00	—
			1,705.00	
	Add 10%		170.50	1,875.50
<b>Special Nett</b>				
11 INNER SEAL		1 PC	Ne 20.00	—
12 WINDSCREEN SEALANT		1 PC	Ne 40.00	—
				60.00
<b>LABOUR</b>				
13 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	200
14 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.		1 PC	120.00	—
15 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	150.00	100
16 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.		1 PC	80.00	60
17 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER LH. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	900.00	800
18 TO SPRAY REAR FENDER LH, REAR DOOR LH, FRONT DOOR LH, SIDE MIRROR COVER LH.		1 PC	900.00	650



*Siang*  
*14-02-2020*

*Man Photo*  
*18-02-2020*

2,190.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20002377/Kyd3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 24-03-2020	
		Code : SMO	
1. Policy Particulars :- OWN DAMAGE			
	Insured Veh.	Veh. Inspected	SKZ 2917A
	Policy No.	Coverage (\$)	0.00
	Claim No. CMTD2000638/SYH	Excess (\$)	0.00
	Assign From GRACE TEO	Assign Date	11/02/2020
2. Vehicle Particulars & Condition			
	Make & Model MAZDA 6 (A)	c.c	1998
	Engine No. HIDDEN	Year of Reg.	2016
	Chassis No. JM6GJ1072G0221101	Colour	METALLIC BLACK
	Odometer 73759	Steering	IN ORDER
	Brakes IN ORDER	Modification	STANDARD ALLOY RIM
	General GOOD		
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	225/55 R17	YOKOHAMA
	L/H Front Tyre	225/55 R17	YOKOHAMA
	R/H Rear Tyre	225/55 R17	YOKOHAMA
	L/H Rear Tyre	225/55 R17	YOKOHAMA
			7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date 09/02/2020	Inspection Date	12/02/2020
	Survey held at AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE MARKET VALUE IS S\$64,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>7 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 2917A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR LH (WCP)	BENT	450.00	450.00
1	FRONT DOOR OUTER HANDLE LH (WCP)	DENTED	90.00	90.00
1	SIDE MIRROR AM LH (WCP)	SERVICEABLE	260.00	-
1	SIDE MIRROR COVER LH (WCP)	SERVICEABLE	40.00	-
1	SIDE MIRROR SIGNAL LAMP LH (WCP)	SERVICEABLE	45.00	-
1	REAR DOOR LH (WCP)	BENT / WARPED	550.00	550.00
1	REAR DOOR INNER LOCK (WCP)	TO REPAIR SEE LABOUR	110.00	-
1	REAR DOOR RUBBER @ DOOR (WCP)	SERVICEABLE	60.00	-
1	REAR FENDER LH (WCP)	BENT	580.00	580.00
1	REAR WINDSCREEN MOULDING (WCP)	NECESSARY	70.00	70.00
	COST PLUS 10%		225.50	174.00
			2,480.50	1,914.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	INNER SEAL (SN)	NECESSARY	20.00	20.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			60.00	60.00
<b><u>LABOUR</u></b>				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.		120.00	120.00
	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		150.00	100.00
	TO REMOVE AND REINSTALL/REPLACE FUEL TANK,FIXTURE AND ATTACHMENTS.		80.00	60.00

Report Ref No. CS/SMO20002377/Kyd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE ALL DAMAGED PARTS,TO CUT & WELD REAR FENDER LH.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR DOOR INNER LOCK.		900.00	800.00
	TO SPRAY REAR FENDER LH,REAR DOOR LH,FRONT DOOR LH,SIDE MIRROR COVER LH.		900.00	650.00
			2,190.00	1,750.00
<b>GRAND TOTAL</b>			<b>4,730.50</b>	<b>3,724.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,950.00</b>

Report Ref No. CS/SMO20002377/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.