

PRE-REPAIR INSPECTION REQUEST – SLT3343T vs SMM9407D (OI) on D.O.A.: 08/02/2020

From: Subramaniam, Divyashni
To: assignments@lkkauto.com, 'Admin A'
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Hor, Yinrul, Subramaniam, Divyashni, Teo, Ericweihong, carmen@esteemperf.com.sg
Sent: 2/10/2020 1:51:28 PM
Attachments:  [SLT3343T_08.02.2020_GIA REPORT.PDF](#)

Hi,

Please refer to the enclosed request from **Esteem Performance Pte Ltd**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign **LKK Auto Consultants Pte Ltd** as Single Joint Expert as requested.*

Thanks & Regards,

Divyashni Subramaniam
AIG

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Carmen Lim [<mailto:carmen@esteemperf.com.sg>]

Sent: Monday, February 10, 2020 11:54 AM

To: AIG SGP, Claims-Survey

Cc: serence etc; jenny chong

Subject: [EXTERNAL] Request for PRI survey SLT3343T

This message is from an external sender; be cautious with links and attachments.

Dear Sir / Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Grab Rentals Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.SLT3343T

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address :385 Sin Ming Drive,(Inside Vicom) S 575718

Tel : 6566 2112 / 8799 0066

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We are prefer LKK to survey the car.

Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive |

Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

[5033 Ang Mo Kio Industrial Park](#)

[2 #01-259 \(Head Office\)](#)

[385 Sin Ming Drive](#) Vicom

Inspection Centre (Showroom)

www.esteemperformance.com

