



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

11 March 2020

Our Ref: TPC/FAS/LONPAC/PL03358

Attn: MOTOR CLAIMS DEPARTMENT

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00
SHAW TOWER
SINGAPORE 189702

Dear Sir /Madam


RE: ACCIDENT INVOLVING SKP3990H & GBB2891Y ON 08/02/2020 ALONG CLEMENTI AVENUE 5 SLIP
ROAD EXIT TO CLEMENTI AVENUE 2

We are pleased to have a direct settlement with you based on the following:

S/N Details	Amount (S\$)
1 Cost of Repair	3,638.00
2 Car Rental @ \$100 X 5 Days	535.00
3 Merimen Search Fee	2.00
	4,175.00
	=====

Enclosed are the relevant documents for your reference.

Thank you and best regards.



Andy Esperanza
Workshop Manager
(Pandan Loop Branch)
Tel : 6779 5665 Fax: 67791110
Email : andy@falconair.com.sg

NB: Please revert all correspondences with regards to the above case to No. 8 Pandan Loop
(Blk K / Blk 1) Singapore 128226

"Without prejudice to Injury/ Medical Claim"

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg