

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/00/0150/2020/NS

Date

18-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLQ 8547 E

Model No

A4 Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Sensor line for tailgate opening ✓ <i>TN</i>	\$	194.00
2	Reinforcement for side panel lhs rear ✓ <i>DN</i>	\$	194.00
3	Reinforcement for side panel rhs rear ✓ <i>DN</i>	\$	194.00

Labours

1	To cut out and weld both reinforcement for side panels. <i>\$14</i>	\$	2,800.00 <i>500</i>
2	To respray both reinforcement for side panels. <i>\$80</i>	\$	1,400.00 <i>300</i>

Total for parts and labour : \$ 4,782.00

For Premium Automobiles Pte Ltd

Steve 19/3/20

Repair days (TBA)

Authorised Signature