

Date: 11.02.2020  
Vehicle No: SJF657E  
Model: FORD FOCUS  
Chassis: WF05XXGCC5FK32680-2015  
Reg.Year: 2015

Third Party Insurer: AIG  
Third Party Veh No: SLG4403R  
Date of Accident: 07.02.2020

*Not Autharised*  
*6/1/2020*

*5-6 days*

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>Bt</i>	1		
2	REAR TAILGATE "FOCUS" EMBLEM <i>na</i>	1		
3	REAR WINDSCREEN RUBBER <i>?</i>	1		
4	REAR TAILGATE INNER TRIM CLIPS <i>?</i>			
5	REAR BUMPER <i>CR</i>	1		
6	REAR BUMPER REVERSE SENSOR <i>mt</i>			
7	REAR BUMPER CLIPS <i>na</i>			
8	REAR BUMPER LOWER LID COVER <i>Bt</i>	1		
9	REAR BUMPER SIDE BRACKET LH <i>Dit</i>	1		
10	REAR BUMPER SIDE BRACKET RH <i>?</i>	1		
11	REAR BUMPER UPPER BRACKET LH <i>?</i>	1		
12	REAR BUMPER UPPER BRACKET RH <i>?</i>	1		
13	REAR BUMPER REFLECTOR LH <i>CR</i>	1		
14	REAR BUMPER FIXING COVER <i>mt</i>	1		
15	REAR BUMPER INNER CENTER RETAINER GUIDE <i>?</i>	1		
16	REAR TAIL LAMP LH <i>CR</i>	1		
17	REAR QUARTER PANEL LINER LH <i>ta</i>	1		
18	REAR QUARTER PANEL LINER RH <i>?</i>	1		
19	REAR END PANEL <i>?</i>	1		REPAIR
20	REAR BUMPER REINFORCEMENT <i>?</i>	1		REPAIR
21	REAR QUARTER PANEL LH	1		REPAIR
SUB TOTAL				\$0.00
LESS 20%				\$0.00
PARTS TOTAL				\$0.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>na</i> \$60.00 <i>60.00</i>
2	REAR WINDSCREEN STOPPER	2	\$15.00	\$30.00 <i>?</i>
S/N TOTAL				\$90.00

I KK Auto Consultants hence no the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Acknowledged by Repairer Branch

452 Tagore Industrial Avenue Singapore 787823  
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 11.02.2020  
Vehicle No: SJF657E  
Model: FORD FOCUS  
Chassis: WF05XXGCC5FK32680-2015  
Reg.Year: 2015

Third Party Insurer: AIG  
Third Party Veh No: SLG4403R  
Date of Accident: 07.02.2020

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST, REAR ACCIDENT AREA & ETC	\$600.00 ?
LABOUR CHARGES TO REMOVE, REPLACE, REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE	\$150.00 120
LABOUR CHARGES TO REMOVE, REPLACE, REFIX REAR BUMPER SENSOR & ETC	\$80.00 60
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATION	\$120.00 60
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR TAILGATE, REAR END PANEL, REAR QUARTER PANEL LH & ETC.	\$800.00 720
TO CHECK WIRING & ELECTRICAL WIRING SYSTEM.	\$60.00 20
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00 ?
TO DIAGNOSE FAULTY CODE & RESET MEMORY.	\$150.00 ?

LABOUR TOTAL      \$2,160.00

<u>ONG</u>	<u>TOTAL</u>	<u>\$2,160.00</u>
------------	--------------	-------------------