

ASS. REC. BY:

REF: CS/CTI 20002419/Gt f3/12

Special Instruction:

Surveyor: GA **ASSIGNMENT (Office)**

From (Person): Chong Boon Sen of CTI Date/Time: 12.2.2020 10.30am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKK 21B Insured: GBD 9006E

at Workshop m/s Wigo Engineering Tel: 64521493 96784116
of Bik 176 sm Ming Drive #04-16

Policy No: DMCVSV 30484719011 Claim No: SMM 20D20073502

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7.2.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS map H.O.D. Endorsement: _____

Date/Time: 12.2.2020 11.20am Person Contacted: Mr Leong Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKK 21B - CC4 / AXH 16023721 / App 3/2 D.O.A - 10/12/2016
	GBD 9006E - X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2020		12 Feb 2020 10:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:	TAN CHIN AIK , ID: S1520010C								
Vehicle Reg. No.:	SKK21B	Date of Loss:	07/02/2020 12:00 - :59						
Claim Type:	TP / SNM20D200735C02	Policy/Cover Note No.:	DMCVSN30484719011						
Vehicle Reg. No. (Insured):	GBD9006E	Policy No. (Claimant):	S109449073						
		Excess:	\$0.00						
Repairer:	Wega Engineering Pte Ltd (HQ) BLK 176 Sin Ming Drive #04-16, Sin Ming AutoCare, 57521 Sin Ming - Tel: 6452 1493								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/02/2020]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 12 February 2020 9:58 AM
To: wega claim
Cc: assignments; Chong Boon Sen
Subject: RE: OUR REF: SNM20D200735/GBD9006E/CBS - Accident Between SKK21B & GBD9006E On 07/02/2020 (TP CLAIM)

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK.

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: wega claim [mailto:wegaclaim@gmail.com]

Sent: Wednesday, February 12, 2020 9:40 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM20D200735/GBD9006E/CBS - Accident Between SKK21B & GBD9006E On 07/02/2020 (TP CLAIM)

Hi Boon Sen ,

As for request n please kindly help to arrange surveyor Xing Quo Qiang

Please kindly refer to attached

thanks

On Tue, Feb 11, 2020 at 5:10 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice

Save as to costs

Dear Sir,
LKK
LBS
STA

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, February 11, 2020 5:07 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; wegaclaim@gmail.com

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D200735/GBD9006E/CBS - Accident Between SKK21B & GBD9006E On 07/02/2020 (TP CLAIM)

Dear Boon Sen,

Please conduct PRS for SKK21B.

Note : officer in charge – Boon Sen 63896171.

**** Kindly quote our reference number when replying.*

Thank you,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: wega claim <wegaclaim@gmail.com>
Sent: Tuesday, February 11, 2020 10:14 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: lucas.lee@sg.cntaiping.com
Subject: Fwd: Accident Between SKK21B & GBD9006E On 07/02/2020 (TP CLAIM)

Dear Sir/Mdm ,

Please kindly help to arrange surveyor

----- Forwarded message -----

From: **wega claim** <wegaclaim@gmail.com>
Date: Mon, Feb 10, 2020 at 5:51 PM
Subject: Accident Between SKK21B & GBD9006E On 07/02/2020 (TP CLAIM)
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Leong Chee kwong <cheekwongwega@gmail.com>

Dear Sir/Mdm ,

Please kindly help to arrange surveyor on 11/02/2020

Thanks & Regards,
Claim Advisor
Wega Engineering Pte Ltd
Tel: 64521493

--

Thanks & Regards,
Claim Advisor
Wega Engineering Pte Ltd
Tel: 64521493

--

Thanks & Regards,
Claim Advisor
Wega Engineering Pte Ltd
Tel: 64521493

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	010C
Vehicle No.:	SKK21B
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2020
Vehicle Make:	B.M.W.
Vehicle Model:	530E MSPT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	23985234B48B20A
Chassis No.:	WBAJA92060BN71254
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$63,950.00
Original Registration Date:	26 Jun 2018
First Registration Date:	26 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$77,110.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2028
PARF Rebate Amount:	\$57,832.00
COE Expiry Date:	25 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,900.00
COE Rebate Amount:	\$28,363.00
Total Rebate Amount:	\$86,195.00

The information contained herein is correct as at 13 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2020 16:42
Date Of Accident	07/02/2020 12:15
Exact Location Of Accident	ADMIRALTY ROAD WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK21B
Insured/Policyholder	
Name Of Registered Owner	TAN CHIN AIK
NRIC No	SXXXX010C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98230231
Alternative Phone No	OFFICE-98230231

Vehicle Particulars

Manufacturer	BMW
Model	530E
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109449073
Cover Note Number	

Driver

Name of Driver	TAN GUAN JI, RUFFORD
NRIC No	SXXXX799C
Date Of Birth	04/11/1988
Occupation	OUTDOOR
Date Of Driving Pass	09/07/2007
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98230231
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 583 SEMBAWANG PLACE
 Postcode 757182
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 4
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD9006E
 Vehicle Make/Model/Colour TOYOTA DYNA
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver ING THIEN SOONG
 NRIC/Passport Number SXXXX666F
 Contact Number 98913154
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YP5474C

Vehicle Make/Model/Colour	MITSUBISHI FUSO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WONG POH FATT
NRIC/Passport Number	SXXXX336H
Contact Number	97327365
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	GBG3106I
Vehicle Make/Model/Colour	MITSUBISHI FUSO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	XUIKIFLI B.MOHB
NRIC/Passport Number	SXXXX391A
Contact Number	96319055
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

Sembawang Camp

Admiralty Road West



- A SKK218
- B GBD9006E
- C YP5474C
- D GBB3106I

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

~~Later starters~~
 My vehicle was stationary, waiting to turn right. (Traffic light Red to turn Right)
 The next moment I heard a few 'bang' sound and then I was hit by a lorry behind.
 We exchanged particulars and there were no injuries to any parties.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

CHINA TAIPING INSURANCE (SINGAPORE) PTE , LTD

Date : 10.02.20

3 Anson Road, #16-00 Springleaf Tower Singapore 079909

Vehicle No : SKK21B
 Chassis No : WBAJA92060BN71254
 Make/Model : BMW 530E
 Year : 2018

S/N	Qty	Description	Unit Price	Amount
-----	-----	-------------	------------	--------

Estimate Cost Of Repair

1	1 PC	REAR BOOTLID <i>X Repair.</i>	\$ 2,160.00	\$ 2,160.00 <i>X</i>
2	1 PC	REAR BOOTLID SPOILER <i>- Cut</i>	\$ 550.00	\$ 550.00 <i>450 -</i>
3	1 PC	REAR BOOTLID LOGO	\$ 93.00	\$ 93.00 <i>71 -</i>
4	1 PC	REAR BOOTLID (COMPETITION) LOGO	\$ 117.00	\$ 117.00 <i>81.9 -</i>
5	1 PC	REAR BOOTLID LAMP RH <i>SCR</i>	\$ 462.00	\$ 462.00 <i>353.35 -</i>
6	1 PC	REAR BOOTLID LAMP LH <i>X NN</i>	\$ 462.00	\$ 462.00 <i>X</i>
7	1 PC	REAR TAILLAMP RH <i>SCR</i>	\$ 780.00	\$ 780.00 <i>692 -</i>
8	1 PC	REAR TAILLAMP LH <i>X NN</i>	\$ 780.00	\$ 780.00 <i>X</i>
9	1 PC	REAR BUMPER ASSY <i>REAR NN</i>	\$ 2,080.00	\$ 2,080.00 <i>1518.95 -</i>
10	1 PC	REAR BUMPER ABSORBER <i>BT</i>	\$ 240.00	\$ 240.00
11	1 PC	REAR BUMPER REINFORCEMENT <i>BT</i>	\$ 1,170.00	\$ 1,170.00 <i>632.45</i>
12	1 PC	REAR BUMPER LOWER GARNISH <i>ODA.</i>	\$ 950.00	\$ 950.00 <i>850</i>
13	1 PC	REAR BUMPER REFLECTOR RH <i>ANN</i>	\$ 52.00	\$ 52.00 <i>X</i>
14	1 PC	REAR BUMPER REFLECTOR LH <i>ANN</i>	\$ 52.00	\$ 52.00 <i>X</i>
15	2/6 PCS	REAR BUMPER REVERSE SENSOR <i>ANN</i>	\$ 480.00	\$ 2,880.00 <i>740</i>
16	1 PC	REAR BUMPER REVERSE SENSOR WIRING <i>X NN</i>	\$ 338.00	\$ 338.00 <i>X</i>
17	1 PC	REAR END PANEL <i>X Repair</i>	\$ 1,105.00	\$ 1,105.00 <i>X</i>
18	1 PC	REAR END PANEL TRIM <i>X NN</i>	\$ 760.00	\$ 760.00 <i>X</i>
19	1 PC	REAR EXHAUST PIPE ASSY <i>X Repair</i>	\$ 2,850.00	\$ 2,850.00 <i>X</i>
20	2 PCS	REAR EXHAUST PIPE O RING <i>X ANN</i>	\$ 30.00	\$ 60.00 <i>X</i>
21	1 PC	REAR BOOTLID WEATHERSTRIP <i>X ANN</i>	\$ 195.00	\$ 195.00 <i>X</i>
22	1 PC	REAR FENDER RH <i>X Repair.</i>	\$ 1,900.00	\$ 1,900.00 <i>X</i>
23	1 PC	REAR FENDER LH <i>X NN</i>	\$ 1,900.00	\$ 1,900.00 <i>X</i>

5389.65
5%: 5120.16

Wega Engineering Pte Ltd



Authorised Signature
 Lim Hock Guan
 Mobile No: 96784116

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

CHINA TAIPING INSURANCE (SINGAPORE) PTE , LTD
3 Anson Road, #16-00 Springleaf Tower Singapore 079909

Date : 10.02.20

Vehicle No : SKK21B
Chassis No : WBAJA92060BN71254
Make/Model : BMW 530E
Year : 2018

S/N	Qty	Description	Unit Price	Amount
-----	-----	-------------	------------	--------

Estimate Cost Of Repair

LABOUR COST

1		TO APPLY PROOFING ON AFFECTED AREA	\$ 200.00	\$ 200.00
2		TO DIAGNOSIS REVERSE SENSOR SYSTEM	\$ 400.00	\$ 400.00
3		TO TRANSFER REAR BOOTLID MECHANISM	\$ 150.00	\$ 150.00
4		TO REMOVE AND REFIT EXHAUST PIPE	\$ 250.00	\$ 250.00
5		TO CHECK WIRING AND FUNCTION	\$ 120.00	\$ 120.00
6		TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TO FACILITATE REPAIR	\$ 180.00	\$ 180.00
7		TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING OR LEAKAGE	\$ 150.00	\$ 150.00
8		TO WELDING & KNOCKING ACCIDENT REAR BOOTLID, END PANEL, BUMPER & FENDER RH & LH	\$ 1,800.00	\$ 1,800.00
9		TO LAMINATE ACCIDENT PORTION REAR BOOTLID, BUMPER, FENDER RH & LH AND REAR END PANEL	\$ 2,800.00	\$ 2,800.00

X NN
407
X SNN
30
60
X NN
4000 500
1200

14/2/2020
6 Days
part by part

before paint photos
Suo Qiang - 82880282
13/02/2020

1830
7512.89

Grand Total

\$ 27,986.00

Wega Engineering Pte Ltd

Authorised Signature
Lim Hock Guan
Mobile No: 96784116



- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

CHINA TAIPING INSURANCE (SINGAPORE) PTE , LTD
3 Anson Road, #16-00 Springleaf Tower Singapore 079909

Date : 24.02.20

Vehicle No : SKK21B
Chassis No : WBAJA920608N71254
Make/Model : BMW 530E
Year : 2018

S/N	Qty	Description	Unit Price	Amount
-----	-----	-------------	------------	--------

Estimate Cost Of SUPPLEMENTARY

1	1pc	SENSOR WIRE FOR SMART OPENER	\$ 54.00	\$ 54.00	$\leftarrow 41.3$ 193 497.05
2	1pc	SENSOR LEAD SMART OPENER BTM	\$ 60.00	\$ 60.00	
3	1pc	CONTROL UNIT SMART OPENER	\$ 559.00	\$ 559.00	

3/5 NW

LABOUR

1		LABOUR TO DIAGNOSIS REAR SMART OPENER SYSTEM	\$	400.00	10% 276.5 X
		TO REQUEST ONE (1) MORE WORKING DAY			
		TOTAL 7 DAYS WORKING DAY			

~~59%~~ 281.65

592.35

59% : 562.73

1073.00

Wega Engineering Pte Ltd

Authorised Signature
Lim Hock Guan
Mobile No: 9834 1211



29059

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002419/GTF3N2
Date: 17/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30484719011
Claimant Vehicle No :	SKK21B	Insured Vehicle No :	GBD9006E
Date of Loss:	07/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200735C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK21B	Engine No:	23985234B48B20A
Make & Model:	BMW 530I, 2.0 LED NAV HUD MSPT (A)	Chassis No:	WBAJA92060BN71254
Reg. Date:	26/06/2018 (Man. Year: 2018)	Odometer:	29177 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/35R19	Rear Tyre Size:	225/35R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	22,609.00	5,682.90	16,926.10	74.86	
Miscellaneous Items	0.00	0.00	0.00		
Labour	6,450.00	1,830.00	4,620.00	71.63	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	29,059.00	7,512.90	21,546.10	74.15	
Approved Total (Overridden) (S\$)		7,512.89			
	(S\$)	29,059.00	7,512.89	21,546.11	74.15
	+ GST 7.00/7.00% (S\$)	2,034.13	525.90	1,508.23	74.15
	Nett Amount (S\$)	31,093.13	8,038.79	23,054.34	74.15

INSPECTION

Date of Assignment:	12/02/2020	
Date Inspected:	13/02/2020 Inspected At:	Wega Engineering Pte Ltd (HQ) BLK 176 Sin Ming Drive #04-16, Sin Ming AutoCare Singapore 57521
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Note: Different 1 cents -Finalised confirm amount: \$7,512.89

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Mar 2020)**Parts:** 143 BMW 530I 2.0 LED NAV HUD MSPT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKK21B)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	2,160.00 F	*- FL
2	1		*REAR BOOTLID SPOILER	Cut	550.00 F	*450.00 FL
3	1		*REAR BOOTLID LOGO	Necessary	93.00 F	*71.00 FL
4	1		*REAR BOOTLID (COMPETITION) LOGO	Necessary	117.00 F	*81.90 FL
5	1		*REAR BOOTLID LAMP RH	Scratched	462.00 F	*353.35 FL
6	1		*REAR BOOTLID LAMP LH	Not Necessary	462.00 F	*- FL
7	1		*REAR TAILLAMP RH	Scratched	780.00 F	*692.00 FL
8	1		*REAR TAILLAMP LH	Not Necessary	780.00 F	*- FL
9	1		*REAR BUMPER ASSY	Deformed	2,080.00 F	*1,518.95 FL
10	1		*REAR BUMPER ABSORBER	Not Necessary	240.00 F	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	1,170.00 F	*632.45 FL
12	1		*REAR BUMPER LOWER GARNISH	Cracked	950.00 F	*850.00 FL
13	1		*REAR BUMPER REFLECTOR RH	Not Necessary	52.00 F	*- FL
14	1		*REAR BUMPER REFLECTOR LH	Not Necessary	52.00 F	*- FL
15	1		*REAR BUMPER REVERSE SENSOR	Not Working (2 Pcs only)	2,880.00 F	*740.00 FL
			(6 Pcs)			
16	1		*REAR BUMPER REVERSE SENSOR WIRING	Not Necessary	338.00 F	*- FL
17	1		*REAR END PANEL	Repair	1,105.00 F	*- FL
18	1		*REAR END PANEL TRIM	Not Necessary	760.00 F	*- FL
19	1		*REAR EXHAUST PIPE ASSY	Repair	2,850.00 F	*- FL
20	2		*REAR EXHAUST PIPE O RING	Not Necessary	60.00 F	*- FL
21	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	195.00 F	*- FL
22	1		*REAR FENDER RH	Repair	1,900.00 F	*- FL
23	1		*REAR FENDER LH	Not Necessary	1,900.00 F	*- FL
24	1		*SENSOR WIRE FOR SMART OPENER	Not Working	54.00 F	*54.00 FL
25	1		*SENSOR LEAD SMART OPENER BTM	Not Working	60.00 F	*41.30 FL
26	1		*CONTROL UNIT SMART OPENER	Not Working	559.00 F	*497.05 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	22,609.00	5,982.00
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	299.10
Total Parts (S\$)	22,609.00	5,682.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO DIAGNOSIS REAR SMART OPENER SYSTEM	New	400.00	0.00
2	TO APPLY PROOFING ON AFFECTED AREA	New	200.00	0.00
3	TO DIAGNOSIS REVERSE SENSOR SYSTEM	New	400.00	40.00
4	TO TRANSFER REAR BOOTLID MECHANISM	New	150.00	0.00
5	TO REMOVE AND REFIT EXHAUST PIPE	New	250.00	0.00
6	TO CHECK WIRING AND FUNCTION	New	120.00	30.00
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TO FACILITATE REPAIR	New	180.00	60.00
8	TO INSPECT RR LIGHTING,MECHANISMS & WATER TEST RR LIGHTING OR LEAKAGE	New	150.00	0.00
9	TO WELDING & KNOCKING ACCIDENT REAR BOOTLID,END PANEL,BUMPER & FENDER RH & LH	New	1,800.00	500.00
10	TO LAMINATE ACCIDENT PORTION REAR BOOTLID,BUMPER,FENDER RH & LH AND RESPRAY END PANEL	New	2,800.00	1,200.00
Gross Labour Cost (S\$)			6,450.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >