

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

11/02/2020 10:16

JOB-NO: 50112426

OWNER'S PARTICULARSNAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA9232M

TRANS: AUTO

CHASSIS: KMHLB41UMGU079771

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4DFU553162

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	800.00	0.00	800.00 <i>400</i>		Y	
2 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00 <i>200 300</i>		Y	
3 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00 <i>200</i>		Y	
4 RUST PROOFING	1.00	80.00	0.00	80.00 <i>X</i>		Y	
TOTAL:		1,380.00	0.00	1,380.00			
MATERIALS							
1 FRONT BUMPER <i>repair</i>	1.00	599.68	119.94	479.74	L	Y	
2 FRONT BUMPER GRILLE <i>ca</i>	1.00	1,110.70	222.14	888.56	L	Y	
3 FRONT BUMPER GRILLE LOGO <i>ca</i>	1.00	142.84	28.57	114.27	L	Y	
4 FRONT BUMPER REINFORCEMENT <i>X</i>	1.00	432.30	86.46	345.84	L	Y	
5 FRONT BUMPER REINFORCEMENT SPONGE <i>X</i>	1.00	99.86	19.97	79.89	L	Y	
6 REAR BUMPER <i>de</i>	1.00	598.90	119.78	479.12	L	Y	
7 REAR BUMPER DIFFUSER <i>de</i>	1.00	228.40	45.68	182.72	L	Y	
8 REAR BUMPER REINFORCEMENT <i>?</i>	1.00	484.40	96.88	387.52	L	Y	
9 REAR BUMPER REINFORCEMENT SPONGE <i>?</i>	1.00	98.90	19.78	79.12	L	Y	
10 REAR BUMPER REINFORCEMENT BRACKET <i>X</i>	1.00	98.63	19.73	78.90	L	Y	
RHS							
11 REAR BUMPER REINFORCEMENT BRACKET <i>X</i>	1.00	98.63	19.73	78.90	L	Y	
LHS							
12 FRONT BUMPER CLIPS <i>ca X</i>	1.00	45.00	0.00	45.00	S	Y	
13 FRONT NUMBER PLATE WITH CASING <i>ca</i>	1.00	100.00	0.00	100.00 <i>40</i>	S	Y	
14 REAR BUMPER CLIPS <i>ca</i>	1.00	45.00	0.00	45.00 <i>30</i>	S	Y	
15 REAR BUMPER PROTECTOR PAD <i>ca</i>	1.00	120.00	0.00	120.00 <i>60</i>	S	Y	
TOTAL:		4,303.24	798.66	3,504.58			
TOTAL PARTS & LABOUR:		5,683.24	798.66	4,884.58			

EXCESS/LOADING:\$ 0.00

No. Of Day: 4 daysRE-SURVEY: BEFORE AFTER PAINTING
PART-BY-PART OR LUMP SUM \$DATE OF SURVEY: 12 / 02 / 2020 @ 1430SURVEYED BY: RSM

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
CONTACT NO: <u>90010068</u> FAX NO: _____							

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: