

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE) CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD 3 ANSON ROAD #16-00, SPRINGLEAF TOWER SINGAPORE 079909	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 1 Inv.date. : 31/08/2020 WIP No. . : 32632 Veh.In/Out: 05/08/2020 26/08/2020 *Tel.No. . : 63896111 Reg.No. . : SMR1109R Reg.date . : 29/11/2019 Mileage . : 11,008 Chassis No: LYVUZ10ADLB501858
--	--

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Mr Loh Wei Jie, Benj

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REMOVE AND REFIT RHF FENDER, RHF DOOR, RHF DOOR PROTECTOR, RHS WING MIRROR ASSY, ETC.		0	1600.00	0		1,600.00	S ✓
800	TO PUTTY AND SPRAY PAINT ON RHF FENDER, RHF DOOR, RHF PROTECTOR, RHS WING MIRROR COVER, ETC.		0	1500.00	0		1,500.00	S ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	495.00	0		495.00	S ✓
	② MIRROR GLASS RH V90C	1.0	EA	221.20	10		199.08	S
	③ MIRROR BACK COVER RH	1.0	EA	388.80	10		349.92	S
	① DOOR MIRROR RH XC60	1.0	EA	603.20	10		542.88	S

Gross Total. 4,686.88

Labour Total	3,595.00	
Parts Total	1,091.88	
Package Total	0.00	

Net.....	4,686.88
GST @ 7.0%	328.08
Total.....	5,014.96
Paid.....	0.00
Please Pay..	5,014.96

GST: S=StdRated; O=OutOfScope; Z=ZeroRated