

S THREE AUTOMOTIVE RECOVERY

TO :
ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO. : **SMP4729S**

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : **CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD**

CONTACT :

ADDRESS :

VEHICLE NO **YP7028U** TRANS.

CHASSIS NO :

MAKE / MODEL : **ISUZU LORRY**

ENGINE NO :

OWNER'S INSURER **FIRST CAPITAL**

JOB-CODE : **TP** S/A : **MICHELLE**

ACCIDENT DATE : **4-Feb-20**

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC %	DISC-PRICE	SUR-DISP	REV. PRICE
1 TAILLAMP ASSY LH	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
2 TAILLAMP ASSY RH	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
3 REAR MUDFLAP LH	1.00	\$ 520.00	10.00	\$ 468.00	Y	X
4 REAR MUDFLAP BRACKET INNER LH	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
5 REAR MUDFLAP BRACKET OUTER LH	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
6 REAR MUDFLAP LOWER RUBBER - ISUZU LH	1.00	\$ 180.00	10.00	\$ 162.00	Y	X
7 REAR NO PLATE LAMP	1.00	\$ 180.00	10.00	\$ 162.00	Y	X

TOTAL (PARTS) :

\$ 2,220.00

\$ 1,998.00

SPECIAL NETT ITEM

1 REAR CABIN TAILLAMP PANEL LH	1.00	\$ 680.00	0.00	\$ 680.00	Y	X
2 REAR CABIN TAILLAMP PANEL RH	1.00	\$ 680.00	0.00	\$ 680.00	Y	X
3 REAR STICKER 60KM	1.00	\$ 30.00	0.00	\$ 30.00	Y	20km
4 REAR REFLECTOR STICKER - RED	1.00	\$ 180.00	0.00	\$ 180.00	Y	50km
5 REAR REFLECTOR STICKER SIDE RH- BLUE & ORANGE	1.00	\$ 360.00	0.00	\$ 360.00	Y	X
6 REVERSE CAMERA	1.00	\$ 380.00	0.00	\$ 380.00	Y	✓
7 REAR CRANE	1.00	\$ 9,500.00	0.00	\$ 9,500.00	Y	X
8 REAR CRANE FORK	1.00	\$ 2,800.00	0.00	\$ 2,800.00	Y	X
9 HYDRALIC OIL	1.00	\$ 450.00	0.00	\$ 450.00	Y	X
10 REVERSE SENSOR ISET	1.00	\$ 520.00	0.00	\$ 520.00	Y	X
11 EXHAUST SILENCER	1.00	\$ 1,900.00	0.00	\$ 1,900.00	Y	X
12 REAR NUMBER PLATE	1.00	\$ 50.00	0.00	\$ 50.00	Y	X
13 REAR NUMBER PLATE BRACKET	1.00	\$ 150.00	0.00	\$ 150.00	Y	X

TOTAL (PARTS) :

\$ 17,680.00

\$ 17,680.00

LABOUR

1 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	\$ 3,800.00	0.00	\$ 3,800.00	Y	X
2 SPRAY PAINTING ON ACCIDENT AREA (2 Tones)	1.00	\$ 1,800.00	0.00	\$ 1,800.00	Y	700ml
3 R&R CRANE TO SERVICE TO LIFT UP & DOWN	1.00	\$ 480.00	0.00	\$ 480.00	Y	X
5 CHECK & REPAIR WIRING SYSTEM	1.00	\$ 80.00	0.00	\$ 80.00	Y	15/2

6	RESPRAY TUFF KOTE ON AFFECTED AREA	<i>nn</i>	1.00	\$	120.00	0.00	\$	120.00	Y	<u>X</u>
7	CONDUCT CHASSIC REPAIR REAR LH PORTION	<i>nn</i>	1.00	\$	1,200.00	0.00	\$	1,200.00	Y	<u>X</u>
8	R&R REAR AXLE, AXLE SPRING & LONG SHAFT TO ASSIT REPAIR	<i>nn</i>	1.00	\$	900.00	0.00	\$	900.00	Y	<u>X</u>
9	RESET & PROGRAMME LTA SYSTEM & INSPECTION	<i>nn</i>	1.00	\$	980.00	0.00	\$	980.00	Y	<u>X</u>
10	POST ACCIDENT REPAIR INSPECTION	<i>nn</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<u>X</u>

TOTAL (LABOUR) : \$ 9,540.00 \$ 9,540.00

TOTAL PARTS & LABOUR \$ 29,440.00 \$ 29,218.00

EXCESS : : S\$ _____

NO. OF DAY : 2-4 days

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 12/2/20

SURVEY BY : Kenneth

CONTACT NO : 96910663

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: