

Re: SME 359K FINALIZE CLOSE CASE

Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Tue 4/7/2020 5:34 PM

To: Speed auto works <speedauto90@gmail.com>

Cc: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Dear susan,

Good day, o.k will be process base on finalized total amount COR \$ 7150 L/SUMP REPAIR and DOR 9 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to lkk claim dept in-charge person handler (CECILIACHONG@LKKAUTO.COM)

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Speed auto works <speedauto90@gmail.com>

Sent: Tuesday, April 7, 2020 4:24 PM

To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Cc: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Re: SME 359K FINALIZE (SECOND REMINDER)

Dear Hock Ann,

Thanks for your mail.

We confirmed accept COR@S\$7,150.00-9 days

--

Best Regards,

Susan

Speed Auto Works

Phone: 6842-2035 | email: speedauto90@gmail.com | fax: 6783-5155
8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit | S(415875)

On Tue, Apr 7, 2020 at 2:50 PM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

Dear susan,

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 11-Feb-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SME359K
ADDRESS	:	MODEL	: NISSAN NOTE
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER ✓ BT	1	\$ 589.00	\$ 589.00
2	REAR BUMPER SIDE RETAINER ✓ ALL	2	\$ 59.20	\$ 118.40
3	REAR BUMPER BRACKET X (SVC)	2	\$ 95.80	\$ 191.60
4	REAR BUMPER SPONGE ✓ LAM	1	\$ 102.00	\$ 102.00
7	REAR NUMBER PLATE LAMP (SET) X (SVC)	1	\$ 115.60	\$ 115.60
12	TAIL GATE ✓ BT	1	\$ 1,089.00	\$ 1,089.00
13	TAIL GATE HINGE X (SVC)	2	\$ 110.00	\$ 220.00
14	TAIL GATE DAMPER X (SVC)	2	\$ 158.00	\$ 316.00
14	TAIL GATE LOGO ✓ ALL	1	\$ 45.60	\$ 45.60
15	TAIL GATE INNER TRIM ✓ LAM	1	\$ 515.00	\$ 515.00
17	TAIL GATE TOP LOCK ✓ Jm	1	\$ 210.00	\$ 210.00
18	TAIL GATE LOWER LOCK X (SVC)	1	\$ 38.20	\$ 38.20
19	TAIL GATE SENSOR SWITCH X (SVC)	1	\$ 176.20	\$ 176.20

436.60 ✓

✓

✓

1000.50 ✓

✓

✓

460.80 ✓

179.80 ✓

20	TAIL GATE DETECTOR	✓ CRA	1	\$	397.20	\$	397.20
21	TAIL GATE WEATHER STRIP	✓ CRA	1	\$	127.80	\$	127.80
22	TAIL GATE OUTER MOULDING	X (SVC)	1	\$	211.00	\$	211.00
23	TAIL GATE STOPPER	X (SVC)	2	\$	28.90	\$	57.80
24	TAIL LAMP	✓ SUR	2	\$	359.80	\$	719.60
25	TAILAMP PANEL	4Hony ✓ AT	12	\$	425.00	\$	850.00
27	REAR FENDER	X (R)	2	\$	1,171.00	\$	2,342.00
28	REAR FENDER INNER COWLING	X (SVC)	2	\$	98.20	\$	196.40
29	REAR FENDER INNER TRIM	✓ CRA	2	\$	548.00	\$	1,096.00
32	REAR WINDSCREEN MOULDING	✓ SUR	1	\$	193.50	\$	193.50
33	REAR END PANEL TOP GARNISH	✓ CRA	1	\$	129.20	\$	129.20
35	REAR END PANEL	✓ AT	1	\$	617.00	\$	617.00
36	REAR CHASSIS EXTENSION MEMBER LH	X (R)	1	\$	965.50	\$	965.50
37	REAR FLOOR PANEL	✓ AT	1	\$	689.00	\$	689.00
39	REAR SPARE TYRE BOLT	X (SVC)	1	\$	28.50	\$	28.50
40	REAR FLOOR PANEL TOP BOARD	✓ CRA	1	\$	495.00	\$	495.00
41	REAR EXHAUST PIPE	X (SVC)	1	\$	986.00	\$	986.00

TOTAL PRICE \$ 13,828.10
 LESS 10% \$ 1,382.81
 SUB TOTAL PRICE \$ 12,445.29

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	✓ SUR	1	\$ 50.00
2	REAR BUMPER CLIP	✓ REC	10	\$ 6.50
3	REAR BUMPER LIP	✓ CRA	1	\$ 1,600.00
4	TAIL GATE INNER TRIM CLIP	✓ REC	10	\$ 6.50
5	TAIL LAMP CLIP	✓ REC	4	\$ 8.00
6	REAR FENDER SEALANT	X (SVC)	1	\$ 80.00
7	REAR FENDER COWLING CLIP	X (SVC)	10	\$ 6.50
8	REAR FENDER INNER TRIM CLIPS	✓ REC	12	\$ 6.50
9	REAR WINDSCREEN MOULDING SEALANT	✓ SUR	1	\$ 80.00
10	REAR WINDSCREEN MOULDING INNER SEAL	✓ SUR	1	\$ 60.00
11	REAR END PANEL TOP GARNISH CLIPS	✓ SUR	4	\$ 6.50
12	REAR END PANEL SEALANT	✓ SUR	1	\$ 150.00
13	REAR FLOOR PANEL SEALANT	✓ SUR	1	\$ 200.00
14	REAR FLOOR PANEL INSULATION SEAL	X SVC	1	\$ 200.00

15	REAR QUARTER GLASS INNER SEAL	X <i>sve</i>	1	\$ 50.00	\$ 50.00
16	BREAK DOWN SIGN	X <i>NS</i>	1	\$ 200.00	\$ 200.00
17	REVERSE SENSOR	✓ <i>short</i>	1	\$ 220.00	\$ 220.00

200 ✓

TOTAL \$ 3,221.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS		\$1,800.00	1400 ✓
2	TO SPRAY PAINT AFFECTED AREA		\$1,600.00	1200 ✓
3	TUFF COAT	X	\$200.00	
4	WIRING CHECK	✓	\$120.00	30 ✓
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	✓	\$220.00	80 ✓
6	REMOVE/REFIX REAR WINDSCREEN	✓	\$120.00	100 ✓
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	✓	\$80.00	20 ✓
8	REAR CHASSIS ALIGNMENT	X	\$300.00	
9	TRANSFER BOOTLID MECHANISM	✓	\$80.00	60 ✓
10	CONDUCT WATER LEAKAGE TEST	✓	\$80.00	30 ✓
11	REMOVE AND REFIX REAR EXHAUST PIPE	✓	\$180.00	40 ✓

TOTAL \$4,780.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,666.29
TOTAL LABOUR COST : \$ 4,780.00
TOTAL REPAIR COST : \$ 20,446.29

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

L/S repr
without previous
resurvey 9 day
2:40 pm 13/2/20
Hoch Ann
LKR
855118885
Hoch ANN@lkkAuto.com

Resurvey taken
Hoch Ann (LKR)
3:20 pm 13/2/20

parts	6116.80
parts less	10%
	5505.12
spe nett	461
labour	2960
	8926.12
4/s less	20%
	7140.80
total	↓
L/S Amt	\$7150#

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: