

Re: SME 359K FINALIZE CLOSE CASE**Hock Ann (LKK Auto) <HockAnn@lkkauto.com>**

Tue 4/7/2020 5:34 PM

To: Speed auto works <speedauto90@gmail.com>**Cc:** Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Dear susan,

Good day, o.k will be process base on finalized total amount COR \$ 7150 L/SUMP REPAIR and DOR 9 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to lkk claim dept in-charge person handler (CECILIACHONG@LKKAUTO.COM)

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor**LKK Auto Consultants**Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Speed auto works <speedauto90@gmail.com>**Sent:** Tuesday, April 7, 2020 4:24 PM**To:** Hock Ann (LKK Auto) <HockAnn@lkkauto.com>**Cc:** Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>; Admin A <admin-a@lkkauto.com>**Subject:** Re: SME 359K FINALIZE (SECOND REMINDER)

Dear Hock Ann,

Thanks for your mail.

We confirmed accept COR@S\$7,150.00-9 days

--

Best Regards,

Susan

Speed Auto WorksPhone: 6842-2035 | email: speedauto90@gmail.com | fax: 6783-5155

8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit | S(415875)

On Tue, Apr 7, 2020 at 2:50 PM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

Dear susan,

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 11-Feb-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SME359K
ADDRESS	:	MODEL	: NISSAN NOTE
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER ✓ <i>BT</i>	1	\$ 589.00	\$ 589.00
2	REAR BUMPER SIDE RETAINER ✓ <i>all</i>	2	\$ 59.20	\$ 118.40
3	REAR BUMPER BRACKET X <i>(SVC)</i>	2	\$ 95.80	\$ 191.60
4	REAR BUMPER SPONGE ✓ <i>all</i>	1	\$ 102.00	\$ 102.00
7	REAR NUMBER PLATE LAMP (SET) X <i>(SVC)</i>	1	\$ 115.60	\$ 115.60
12	TAIL GATE ✓ <i>BT</i>	1	\$ 1,089.00	\$ 1,089.00
13	TAIL GATE HINGE X <i>(SVC)</i>	2	\$ 110.00	\$ 220.00
14	TAIL GATE DAMPER X <i>(SVC)</i>	2	\$ 158.00	\$ 316.00
14	TAIL GATE LOGO ✓ <i>all</i>	1	\$ 45.60	\$ 45.60
15	TAIL GATE INNER TRIM ✓ <i>all</i>	1	\$ 515.00	\$ 515.00
17	TAIL GATE TOP LOCK ✓ <i>all</i>	1	\$ 210.00	\$ 210.00
18	TAIL GATE LOWER LOCK X <i>(SVC)</i>	1	\$ 38.20	\$ 38.20
19	TAIL GATE SENSOR SWITCH X <i>(SVC)</i>	1	\$ 176.20	\$ 176.20

436.60 ✓
✓
✓
1000.50 ✓
✓
460.80 ✓
179.80 ✓

20	TAIL GATE DETECTOR	✓ CRA	1	\$	397.20	\$	397.20	280.80 ✓
21	TAIL GATE WEATHER STRIP	✓ CRA	1	\$	127.80	\$	127.80	✓
22	TAIL GATE OUTER MOULDING	X (CRA)	1	\$	211.00	\$	211.00	
23	TAIL GATE STOPPER	X (SVC)	2	\$	28.90	\$	57.80	
24	TAIL LAMP	✓ SCR	2	\$	359.80	\$	719.60	✓
25	TAILAMP PANEL	44 only ✓ BT	12	\$	425.00	\$	850.00	290.30 ✓
27	REAR FENDER	X (R)	2	\$	1,171.00	\$	2,342.00	
28	REAR FENDER INNER COWLING	X (CRA)	2	\$	98.20	\$	196.40	
29	REAR FENDER INNER TRIM	✓ CRA	2	\$	548.00	\$	1,096.00	590.90 ✓
32	REAR WINDSCREEN MOULDING	✓ me	1	\$	193.50	\$	193.50	✓
33	REAR END PANEL TOP GARNISH	✓ CRA	1	\$	129.20	\$	129.20	✓
35	REAR END PANEL	✓ BT	1	\$	617.00	\$	617.00	530.30 ✓
36	REAR CHASSIS EXTENSION MEMBER LH	X (R)	1	\$	965.50	\$	965.50	
37	REAR FLOOR PANEL	✓ BT	1	\$	689.00	\$	689.00	600.30 ✓
39	REAR SPARE TYRE BOLT	X (SVC)	1	\$	28.50	\$	28.50	
40	REAR FLOOR PANEL TOP BOARD	✓ CRA	1	\$	495.00	\$	495.00	310.40 ✓
41	REAR EXHAUST PIPE	X (SVC)	1	\$	986.00	\$	986.00	

TOTAL PRICE \$ 13,828.10
 LESS 10% \$ 1,382.81
 SUB TOTAL PRICE \$ 12,445.29

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE ✓ <i>SCR</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP ✓ <i>me</i>	10	\$ 6.50	\$ 65.00
3	REAR BUMPER LIP ✓ <i>CRA</i>	1	\$ 1,600.00	\$ 1,600.00
4	TAIL GATE INNER TRIM CLIP ✓ <i>me</i>	10	\$ 6.50	\$ 65.00
5	TAIL LAMP CLIP ✓ <i>me</i>	4	\$ 8.00	\$ 32.00
6	REAR FENDER SEALANT X <i>(SVC)</i>	1	\$ 80.00	\$ 80.00
7	REAR FENDER COWLING CLIP X <i>(CRA)</i>	10	\$ 6.50	\$ 65.00
8	REAR FENDER INNER TRIM CLIPS ✓ <i>me</i>	12	\$ 6.50	\$ 78.00
9	REAR WINDSCREEN MOULDING SEALANT ✓ <i>me</i>	1	\$ 80.00	\$ 80.00
10	REAR WINDSCREEN MOULDING INNER SEAL ✓ <i>me</i>	1	\$ 60.00	\$ 60.00
11	REAR END PANEL TOP GARNISH CLIPS ✓ <i>me</i>	4	\$ 6.50	\$ 26.00
12	REAR END PANEL SEALANT ✓ <i>me</i>	1	\$ 150.00	\$ 150.00
13	REAR FLOOR PANEL SEALANT ✓ <i>me</i>	1	\$ 200.00	\$ 200.00
14	REAR FLOOR PANEL INSULATION SEAL X <i>SVC</i>	1	\$ 200.00	\$ 200.00

15	REAR QUARTER GLASS INNER SEAL	X Svc	1	\$	50.00	\$	50.00
16	BREAK DOWN SIGN	X NS	1	\$	200.00	\$	200.00
17	REVERSE SENSOR	✓ short	1	\$	220.00	\$	220.00

200 ✓

TOTAL \$ 3,221.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS		\$1,800.00	1400 ✓	1200
2	TO SPRAY PAINT AFFECTED AREA		\$1,600.00	1200 ✓	1100
3	TUFF COAT	X	\$200.00		
4	WIRING CHECK	✓	\$120.00	30 ✓	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	✓	\$220.00	80 ✓	
6	REMOVE/REFIX REAR WINDSCREEN	✓	\$120.00	100 ✓	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	✓	\$80.00	20 ✓	
8	REAR CHASSIS ALIGNMENT	X	\$300.00		
9	TRANSFER BOOTLID MECHANISM	✓	\$80.00	60 ✓	
10	CONDUCT WATER LEAKAGE TEST	✓	\$80.00	30 ✓	
11	REMOVE AND REFIX REAR EXHAUST PIPE	✓	\$180.00	40 ✓	

TOTAL \$4,780.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,666.29
TOTAL LABOUR COST : \$ 4,780.00
TOTAL REPAIR COST : \$ 20,446.29

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

L/S report
without preparation
resurvey 9 day
2:40pm 13/2/20
Hochman
Liker
PS312883
Hochman BMM@Hochman

Resurvey taken
Hochman BMM (Liker)
3:20pm 13/2/20

Parts	6116.80
parts less	10%
	5505.12
Spe nett	461
labour	2960
	8926.12
4/s less	20%
	7140.80
total	↓
L/S Amt	\$7150#

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: